

**Schultz, Robert, Env. Health**

---

**Subject:** Paul Supple, RO174  
**Entry Type:** Phone call  
**Company:** Atlantic Richfield Company

**Start:** Mon 11/8/2004 10:53 AM  
**End:** Mon 11/8/2004 10:53 AM  
**Duration:** 0 hours

**Contacts:** Paul Supple

left v-mail re. prioritization spreadsheet and hesperian workplan comments  
asked for return call

return call from Paul at 3:30PM  
Scott Robinson is preparing response to workplan addendum request  
there are questions re. zoning for the site, also thrifty oil owns the site so BP is not in a position to dictate future site use - likely that thrifty will want unrestricted

also, Paul spoke with URS re. spreadsheet  
they will take a crack at it with MTBE, benzene, location infor to prioritize sites

CONTACT LOG (20200 Hesperian, Hayward)

09/17/99 Called Ray Friedrichson, Thrifty Oil, (562) 921-3581 # 376, to discuss the extreme and unusual ground water flow variations at the site.

09/27/99 Ray Friedrichson left message stating that g.w. has always had same gradient, even when ARCO was conducting investigations at the site.

10/08/99 Called Ray Friedrichson and asked him to submit an interpretation of the varying groundwater flow directions on site & the site geology (is there a former stream channel in area?)

10/08/99 Looked at boring logs w/ Ray Friedrichson & discussed the possibility of a former stream channel on the property.

11/11/99 Brian Vanderveen, 510-740-5807, consultant to ARCO reported that I either meet w/ or conference call w/ him & Paul Supple to discuss the required work.

11/12/99 I called & left message for Brian Vanderveen that I would be available to meet w/ them next week between Nov 16-17 '99.

CONTACT COO (20200 Hesperian, Hayward)

- 05/26/99 Spoke to Ray Friedrichson, Thrifty Oil, (562) 921-3581 #376, after reviewing his workplan. He will meet me out at site tomorrow at 9:30AM for the sampling.
- 05/26/99 Called Rob Weston, Alameda County, and told him that the meeting time was changed from 9AM to 9:30 AM at the site tomorrow, 5/27/99.
- 07/15/99 Called Ray Friedrichson, Thrifty Oil, 562-921-3581 #376 to find out what he got in his soil sample analysis from the 5/27/99 sampling event. I haven't heard from him since the sample date. Requested that he call me back.
- 07/16/99 Ray Friedrichson called back. He didn't have his soil samples analyzed & two of them came back w/ high levels of MTBE. Will send those results w/ the next quarterly report w/in next month.
- 09/03/99 Called Paul Supral, ARCO, 925-299-8892 & gave him heads up for letter regarding soil remediation.
- 09/10/99 Glen Vanderveen, IT Corp., 510-740-5807, called to say that he is Paul Supral's, ARCO's, consultant. Discussed case. He requested that I fax him table w/ g.w. monitoring results, analytical results from the dispense, sampling, and a site figure. Fax: 510-663-3315

CONTACT Lot (20200 Hasperian, Hayward)

05/03/99 Called Ray Friedrichsen, Thrifty Oil, (562) 921-3581 #376. He stated that the most recent quarterly g.w. monitoring report was sent to the County & that he'd submit a 1-pg. workplan outlining sampling below the dispensers. I told him that it must provide sampling protocol, such as sample containers, being at 4°C, etc. Tentatively set dates for Sampling on May 25 or 26 '99. Told him I'd call him back tomorrow after confirming date w/ Rob Weston.

05/03/99 Left message for Rob Weston, ACDOR, to find out whether he can make it out to site on either May 25 or 26 '99.

05/04/99 Rob Weston confirmed that May 25 or 26 '99 is available.

05/04/99 Called Ray Friedrichsen, Thrifty Oil. Although we tentatively scheduled the field work for May 25, Tues. @ 9AM, we will call back by tomorrow to confirm.

05/06/99 Ray Friedrichsen called & stated that he could only make it for field sampling on May 27 or 28 '99 in the morning.

05/10/99 Rob Weston stated that May 27 was open for him.

05/10/99 Call Mr. Friedrichsen & left message requesting that he set the field work for May 27 '99, 9 AM.

05/18/99 Called Ray Friedrichsen, Thrifty Oil, (562) 921-3581 #376. Requested he submit short w.p. for planned sampling on May 27 '99 to me today through Fax.

CONTACT LOG (20200 Hesperian, Hayward)

04/05/99 Raymond Friedrichson, Thrifty Oil, (562) 921-3581, #376, returned my call. He stated that the recent release is really ARCO's responsibility since ARCO currently operates the site. He will contact Paul Supple, ARCO, to see whether a leak report was filed and will call me back to make arrangements to meet out at site and inspect dispensers and to determine soil sample locations & discuss excavation of contaminated. Mr. Friedrichson stated that he thought the dispensers had collection pans underneath, but I stated that Mr. Weston stated that there was no containment.

04/09/99 Raymond Friedrichson, Thrifty Oil, (562) 921-3581 #376 called to say that he is preparing a workplan to address the inspection & sampling of soil below the dispenser areas, in response to the reported leak by Rob Weston, Alameda County. Mr. Friedrichson stated that the ARCO maintenance person had no record of any leaks or repairs.

04/14/99 I spoke to Rob Weston re leak. He said that ARCO maintenance may not know of leak, but H.B. Clegg, contractors, were out there w/ Rob Weston when leak was observed. Mr. Weston will go out to site w/ me at time of sampling to identify formerly leaking dispensers.

04/14/99 Discussed required work w/ Ray Friedrichson & my discussion w/ Rob Weston. Workplan will be submitted w/ next g.w. monitoring report by end of April 99.

CONTACT Log (20200 Hesperian, Hayward)

- 12/11/98 Rob Weston, Senior Hazardous Materials Specialist w/ Alameda County, notified me that a leak had occurred at the site. The leak was apparently observed during tank upgrades and Mr. Weston stated that he reported the leak.
- 01/05/98 Left message for Raymond Friednichsen, Thirsty Oil, (562) 921-3581 Ext. 376 after reviewing the monitoring report for the 10/22/98 Sampling Event. I mentioned that based on our split sample results and their lab analysis results that it appears the site can be closed. However, this office is awaiting add. information on the leak that Rob Weston reported to us on 12/11/98. I provided Mr. Weston's phone # to Mr. Friednichsen - (510) 567-6781
- 04/05/99 Called & left message for Raymond Friednichsen, ~~(510) 567-6781 Ext 376~~, inquiring about what he found out about leak, reported by Rob Weston. Mr. Weston stated that in December he saw a shear valve on dispensee continuously dripping gas directly onto the sand fill which is connected to the native soil. In January 99, when he returned, this valve was no longer leaking. I stated that soil samples will need to be collected below those fittings and requested that he return my call so that we can make arrangements to meet, take a look at valves, & collect soil samples.

Contact Log (20200 Hesperian, Hayward)

- 11/01/98 left message for Chris Panaitescu, Thrifty Oil, (562)921-3581. He sent me g.w. monitoring report, dated Oct 22 '98, & requested closure, however, the results of the Oct 22 '98 sampling event were not included in this report. I explained that the results of that sampling event, which included analysis for all xylenes & lead scavenger, using Method 8260 & 8010, must be submitted prior to this office considering the site for closure.
- 11/01/98 left message for Ray Friedrichsen, Thrifty Oil, inquiring about confusion by Mr. Panaitescu and explaining same as above. Requested that Mr. Friedrichsen call me back w/ status on when monitoring report for the Oct 22, '98 Sampling event would be submitted.
- 11/10/98 Chris Panaitescu returned my call and stated that they had mistakenly reported closure in the last g/w report. They are aware of the Oct 22 '98 Sampling event, and the MTBE analysis using <sup>Method</sup> V8260, and will submit a report documenting the results of this sampling event within the next month.

## Contact Log (20200 Hispanian Blvd.)

10/04/98 Bryan Van Wagner, Thrifty Oil, called & left message. (562) 923-9876.

10/06/98 Called Bryan Van Wagner and left message requesting that we set a date for g.w. sampling, so that I can meet him out at site to collect split samples.

10/06/98 ~~Raymond Friederichsen~~, Thrifty Oil, called back. He is the main contact. His address is:

13539 East Foster Rd.

Santa Fe Springs, CA 90670

Discussed site and requirements.

Mr. Friederichsen stated that additional g.w. monitoring was conducted on 7/31/97; 10/22/97; 01/28/98; 4/22/98; & 6/8/98.

10/19/98 Spoke to Jeff, Thrifty Oil. Groundwater sampling will be conducted on 10/21-22/98, Wed & Thurs. Requested that they wait 'till Thurs, 10/22/98 to collect g.w. samples from Wells MW-1 - MW-3 and Well AR-1 so that I can be out there to collect split samples. Subsequently, they will call me to let me know what time I should be out there. His pager# is 510-734-7059. (Probably ~7:30 AM).

Jan 24, 1996 PERP meeting Notes

### Airport Alliance

- Contracts 1960s - VSTs most probably single-walled
- Wells installed in 1993(?)
- 1994 4 borings advanced by Certified

### Epton / Kipars Proposal

- TPH&
- Continue joint monitoring
- Assist Alliance RP to get into Compliance by getting him "in touch" w/a specialized consultant who would assist in getting permits in "proper order" & application to Cleanup Fund & Loan Proj. to remove VSTs.

See Mr. Logan re: ARCO/Thrift  
RP designated

ARCO's Attorney -  
cc: him on RP  
correspondence

JAMES P. WATSON  
ATTORNEY AT LAW

STANTON, KAY & WATSON  
180 SUTTER ST., THIRD FLOOR  
SAN FRANCISCO, CA 94104  
(415) 788-3496  
FAX (415) 788-4174

7801 FOLSOM BLVD., SUITE 850  
SACRAMENTO, CA 95826  
(916) 381-7888  
FAX (916) 381-7880

Phone Log (20200 Desperian Blvd )

- 11/9/95 Left msg. for Ray Friedricker to call (310) 923-9876 X376 regarding status of quarterly report for Sept 1995 sampling event.
- 2/5/96 Left msg for Ray Friedricker to call re: Clarification of current property owner.
- 09/28/98 Left message for Chuck Headlee, RWQCB, (510) 622-2433. Asked whether there were any guidelines stipulating that RPs could not conduct their own investigations.
- 09/28/98 Chuck Headlee, RWQCB, called back and stated that there are no such requirements.
- 09/28/98 Called Environmental Health Lab, Newton Loring, and inquired whether they are certified to conduct TPHg, BTEX, and MTBE analysis. He said they could use Method 8020. This lab will do the analyses for free and supply the VOA vials.
- 09/28/98 Left a message for Bryan Van Wagner, Thrifty Oil, at (562) 923-9876. Explained that another round of groundwater analysis will need to be conducted for all the site wells, and they will need to give me advance notice so that I can be out at site to collect split samples. Split samples need to be collected to validate the rather sudden decrease in contaminant concentrations. Also, future MTBE analyses will need to be done using Method 8260 per RWQCB guidelines.

5/5/93

I spoke to Hugh Murphy would said that the Hayward Fire Dept. is requiring that the former Shell station install wells to determine whether any contamination resulting from their site at the corner of West "A" St. and Hussey. Mr. Murphy stated that, when the tanks were removed from the site, there was soil contamination identified.

*Patricia Linn*

# PHONE LOG (20200 HESPERIAN Blvd.)

10/28/93 JOEL COFFMAN, GEO STRATEGIES (510) 551-8777  
& Juliet Stein

Mr. Coffman said that he would submit the RAP soon, along w/ information on the remediation systems being installed.

8/8/95 See file notes on conversation w/ RP's

8/23/95 Returned Ray Friedrichsen a call, he said VLR is in the mail - I told him the state did have a record of this site (reg date 1/14/86.) He also indicated that they are coordinating w/ ARCO to replace the Carbon Canisters w/ the SVE system at one time. They ~~can't~~ <sup>plan to</sup> continue the remediation system w/out interruption. He said Thrifty is taking over QMR's as of Sept 1 & ARCO is responsible prior to 9/1/95. He indicated a letter will follow.

9/15/95 Spoke w/ Ray Friedrichsen w/ Thrifty [REDACTED] who indicated Earth Management will be the consultant for this site. He proposes to complete GWM by 9/30 & I asked that a report be forwarded by 10/15. Thrifty does not want to start up SVE until they have recent GW data - this will help to determine if a carbon filter or a barrier should be used. I asked for a proposal writing.

3/9/95 Meeting w/ Hugh Murphy & Madhulla Logan

→ Check into MW →

A-8 - Is it screened properly - require

- \* → Hugh requests ARCO to continue the cooperative gradient & isocone maps for the 5 service stations because he believes it is important to look at how ARCO's remediation system affects gw gradient.
- Have ARCO continue joint gw monitoring until they prove they are completely not involved w/ Cont from Alliance. Possibly hydropunch study in vicinity of A-8.
- Write a letter to ARCO - Call 1st - Re A-8 & letter Hugh Murphy is sending out.

3/16/95 Left a message w/ Mike Whelan w

3/17/95 Mike Whelan called to say he will be out of town until April 3 & we can discuss this site then

Air Contamination 3/9/93

Cliff Garrett, GSI (610) 352-4800  
Juliet Stein

RE: 20200 Cypressin Blvd., San Lorenzo

I spoke to Mr. Garrett regarding the work plan, dated March 6, 1993. He said that a minimum of 2 soil samples from each of the borings will be analyzed. It also clarified that if one of the borings, A-A, A-B, or A-C, screen positive for soil contamination, those <sup>of these</sup> would be converted into vapor extraction wells. I asked him then how would the soil contamination in former SB-2 and SB-3 be addressed. He stated that the air sparging will ADT<sup>t</sup> address probably address the soil contamination in SB-3 and that the groundwater extraction system would probably address the soil contamination in SB-2. He also said that AR-2 will address the soil contam.

ARCO Meeting

11/19/92

20200 Hispanian Blvd.

The site is active. It is uncertain whether there were traded visits at the site in the past. John Vargas stated that he would look into that. He added that recently, the ground water pulled from the extraction well was analyzed for a whole array of constituents that may have included lead. He will check. The Remediation Plan, covering the aquifer test, will be submitted upon the next month to the County for review.

(Note: Talk to Paul regarding alluvium site.)

The planned or projected start-up date for the extraction system is July '93. The revised timetables will be submitted by Dec 17, 1992.

Chuck Carmel - 7/1/91

Arco 20200 Hesperian Blvd  
Hayward 94541

Slipper - Timetable is being completed

t. will be ~~sent~~ sent  
w/in 2 weeks

apparently no P-test was  
done in 1989 - he has checked  
files.

Replace tanks ?? no  
=