



ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION (LOP)
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335

Certified Mail #P143 589 333
11/08/96
STID# 3646

Notice of Requirement to Reimburse

Mr. Jeff Granberry
Shell Oil Products Co.
P.o. Box 4023
Concord C A 94524

Responsible Party (RP)
Property Owner

Shell Service Station
540 Hegenberger Rd
Oakland , CA 94621


SITE

Date First Reported 08/21/96
Substance: Gasoline
Petroleum: (X) Yes
Source: F

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Section 25297.1 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board (SWRCB) not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above referenced underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the SWRCB.

A determination of a secondary RP status may be made if it is shown that one or more of the RP(s) is performing corrective action and it is clear that the party seeking secondary status did not in any way initiate or contribute to the actual discharge. If the primary RP fails to perform corrective action, then the secondary RP will be considered a primary RP. To request designation as a secondary RP, contact this office.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the SWRCB. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, Please fax your request to Roni Riley at the SWRCB at (916) 227-4349 telephone the SWRCB at (916) 227-4408. Please contact Barney Chan, Hazardous Materials Specialist at this office if you have any further questions concerning this matter.


Gordon Coleman, Acting Chief
Contract Project Director

Please Circle One **(Add)** Delete Change

Reason: New Site

c: Lori Casias, SWRCB
Barney Chan, Hazardous Materials Specialist

P 143 589 333

US Postal Service STID 3646

Receipt for Certified Mail

No Insurance Coverage Provided.
Do not use for International Mail (See reverse)

Sent to	
shell Oil Products	
Special Number	
J. Cranberry	
P.O. box 4023	
Post Office, State, & ZIP Code	
Concord, ca 94524	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date, & Addressee's Address	
TOTAL Postage & Fees	\$
Postmark or Date	

PS Form 3800, April 1995