

MEETING NOTES

CASE NO.: RO409
SITE NAME: Unocal #1156
ADDRESS: 4276 MacArthur Boulevard, Oakland
DATE: July 1, 2015

PARTICIPANTS:

Nicole Arceneaux, Chevron
Chad Roper, AECOM
Jerry Wickham, ACEH

The following items were discussed during the meeting:

- Jerry Wickham indicated that active remediation along the northwestern side boundary is a priority due to elevated detections of petroleum hydrocarbons in soil gas.
- Chevron is hesitant to pursue active remediation in the area without knowing the location of the contaminant source. Not feasible to remediate an area downgradient from source and wait for contamination to migrate to remedial system.
- Attendees agreed that source of contamination in the northwestern portion of site was uncertain.
- Jerry Wickham indicated that there needed to be a good faith effort at remediation to reach closure for the site.
- The aquifer tests indicated a hydraulic conductivity of 3.75×10^{-4} cm/sec in the area of MW-1B. Pumping rate was 1 gpm.
- Aquifer test results will be presented in a report.
- Future recommendations may include a feasibility report with data gap identification which likely would lead to data collection or testing of remedial alternatives.

Meeting notes by Jerry Wickham