## Detterman, Mark, Env. Health

Subject: RO454\_Chevron\_Center\_St

Entry Type: Phone call

**Start:** Thu 4/4/2013 10:39 AM **End:** Thu 4/4/2013 10:39 AM

**Duration:** 0 hours

Return a VM from 441 on Monday April 1, to Pamela with non-defined questions on this site.

Pamela has been reading documents on Geotracker and is aware of ongoing discussion with Chevron regarding the site. She is developing a community garden on one of the recently acquired parcels by Chevron and imported 14 yds of mulch and soil and is in the process of growing vegetables in raised beds and raising chickens. A fencing contractor came out the other day with instructions to tear down old fencing and put up a fence around the full three parcels, and she is in communications with Chevron real estate currently (Leslie Tattoo – sp?). I let her know that Chevron tested for surface contamination on all three parcels and found lead and PCBs on the recently purchased parcels (and some on the old service station parcel). She may not have seen the report, but let her know it's on Geotracker (and ACEH website). She is aware of potential for lead, and understands chicken droppings are beneficial, and why they imported mulch and soil. Also should be a protection against PCBs, an oily coolant formed by high temp and pressure situations.