

ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR **1131 HARBOR BAY PARKWAY** ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 6644

May 28, 2014

NOTICE OF RESPONSIBILITY

Site Name & Address:	Local ID:	RO0000464
CHEVRON #9-1851	Related ID:	541
451 HEGENBERGER RD	RWQCB ID:	01-2429
Oakland, CA 94621	Global ID:	T0600102238

Responsible Party:

Date First Reported:

GURINDER GREWAL & SINGH NAVDEEP 349 BRIANNE CT **PLEASANTON CA 94566**

2/23/1996 8006619 Gasoline-Automotive (motor gasoline and Substance: additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CHEVRON CORPORATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your case worker DETTERMAN, MARK, at this office at (510)567-6876 if you have questions regarding your site.

05 2814 Date: **ARIU LEVI, Director**

Contract Project Director

Action: Add Reason: ADD

Attachment A: Responsible Parties Data Sheet

cc: Saliy Meza, SWRCB (email: smeza@waterboards.ca.gov) | Dilan Roe (email: dilan.roe@acgov.org), File

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

May 28, 2014

Site Name & Address: CHEVRON #9-1851 451 HEGENBERGER RD Oakland, CA 94621 Local ID: RO0000464 Related ID: 541 RWQCB ID: 01-2429 Global ID: T0600102238

All Responsible Parties

RP has been named a Primary RP – ALEXIS FISCHER CHEVRON CORPORATION

6111 BOLLINGER CANYON ROAD RM 3660 | SAN RAMON, CA 94583 | Phone (925) 543-2961

RP has been named a Primary RP – MARK GOMEZ CITY OF OAKLAND

250 FRANK OGAWA PLAZA STE #5301 | OAKLAND, CA 94612-2034 | Phone (510) 238-7314

RP has been named a Primary RP -

SIMGAS LLC 655 MONTGOMERY ST, #1900 | SAN FRANCISCO, CA 94111-- | No Phone Number Listed

RP has been named a Primary RP - GURINDER GREWAL & SINGH NAVDEEP

349 BRIANNE CT | PLEASANTON, CA 94566-- | No Phone Number Listed

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."

2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."

3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."

May 28, 2014

Responsible Party Identification

Existence of Unauthorized Release

On October 11, 1995, five soil bores were installed at the site to characterize the subsurface beneath the site. Four of the soil bores were converted to groundwater monitoring wells MW-1 to MW-4. Concentrations up to 8.4 milligrams per kilogram (mg/kg) TPH as gasoline, 2,100 mg/kg Oil and Grease, and 0.0097 mg/kg ethylbenzene. Concentrations up to 170 micrograms per liter (μ g/I) TPH as gasoline, 1,600 μ g/I TPH as diesel, 3.5 μ g/I benzene, and 1.0 μ g/I ethylbenzene were detected in groundwater. These data indicate than an unauthorized release had occurred.

Responsible Party Identification

Chevron Corporation (Chevron) owned or operated the USTs at this site. Chevron is a responsible party for site because it owned or operated an UST used for the storage of a hazardous substance (Definition 1), owned or operated the UST immediately before the discontinuation of its use (Definition 2), and had control over an UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

The City of Oakland had purchased the site by January 1, 2000 and is a responsible party because it owned the property where an unauthorized release has occurred (Definition 3).

Simgas LLC purchased the property in March 2005, and operated the USTs at the site. Simgas is a responsible party because it owned the property where an unauthorized release has occurred (Definition 3),



Certified Mail #: 7009 2820 0001 4359 6736

May 28, 2014

NOTICE OF RESPONSIBILITY

Responsible Party:

CITY OF OAKLAND MARK GOMEZ 250 FRANK OGAWA PLAZA STE #5301 OAKLAND CA 94612-2034 Date First Reported: 2/23/1996 Substance: 8006619 Gasoline-Automotive (motor gasoline and additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CHEVRON CORPORATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your easeworker DETTERMAN, MARK, at this office at (510)567-6876 if you have questions regarding your site.

05/28/14 Date:

ARIU LEVI, Director Contract Project Director Action: Add Reason: ADD

Attachment A: Responsible Parties Data Sheet

cc: Sally Meza, SWRCB (email: smeza@waterboards.ca.gov) | Dilan Roe (email: dilan.roe@acgov.org), File

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

May 28, 2014

Site Name & Address: CHEVRON #9-1851 451 HEGENBERGER RD Oakland, CA 94621 Local ID: RO0000464 Related ID: 541 RWQCB ID: 01-2429 Global ID: T0600102238

All Responsible Parties

RP has been named a Primary RP – ALEXIS FISCHER CHEVRON CORPORATION

6111 BOLLINGER CANYON ROAD RM 3660 | SAN RAMON, CA 94583 | Phone (925) 543-2961

RP has been named a Primary RP – MARK GOMEZ CITY OF OAKLAND

250 FRANK OGAWA PLAZA STE #5301 | OAKLAND, CA 94612-2034 | Phone (510) 238-7314

RP has been named a Primary RP -

SIMGAS LLC 655 MONTGOMERY ST, #1900 | SAN FRANCISCO, CA 94111-- | No Phone Number Listed

RP has been named a Primary RP - GURINDER GREWAL & SINGH NAVDEEP

349 BRIANNE CT | PLEASANTON, CA 94566-- | No Phone Number Listed

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."

2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."

3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."

May 28, 2014

Responsible Party Identification

Existence of Unauthorized Release

On October 11, 1995, five soil bores were installed at the site to characterize the subsurface beneath the site. Four of the soil bores were converted to groundwater monitoring wells MW-1 to MW-4. Concentrations up to 8.4 milligrams per kilogram (mg/kg) TPH as gasoline, 2,100 mg/kg Oil and Grease, and 0.0097 mg/kg ethylbenzene. Concentrations up to 170 micrograms per liter (μ g/I) TPH as gasoline, 1,600 μ g/I TPH as diesel, 3.5 μ g/I benzene, and 1.0 μ g/I ethylbenzene were detected in groundwater. These data indicate than an unauthorized release had occurred.

Responsible Party Identification

Chevron Corporation (Chevron) owned or operated the USTs at this site. Chevron is a responsible party for site because it owned or operated an UST used for the storage of a hazardous substance (Definition 1), owned or operated the UST immediately before the discontinuation of its use (Definition 2), and had control over an UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

The City of Oakland had purchased the site by January 1, 2000 and is a responsible party because it owned the property where an unauthorized release has occurred (Definition 3).

Simgas LLC purchased the property in March 2005, and operated the USTs at the site. Simgas is a responsible party because it owned the property where an unauthorized release has occurred (Definition 3),



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 6743

May 28, 2014

NOTICE OF RESPONSIBILITY

<u>Site Name & Address:</u> CHEVRON #9-1851 451 HEGENBERGER RD Oakland, CA 94621

Local ID: Related ID:	RO0000464 541
RWQCB ID:	01-2429
Global ID:	T0600102238

Responsible Party:

Date First Reported:

SIMGAS LLC 655 MONTGOMERY ST, #1900 SAN FRANCISCO CA 94111
 Date First Reported:
 2/23/1996

 Substance:
 8006619 Gasoline-Automotive (motor gasoline and additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CHEVRON CORPORATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker DETTERMAN, MARK, at this office at (510)567-6876 if you have questions regarding your site.

05/26/14

Date:

ARIU LEVI, Director Contract Project Director

Action: Add Reason: ADD

Attachment A: Responsible Parties Data Sheet

cc: Sally Meza, SWRCB (email: smeza@waterboards.ca.gov) | Dilan Roe (email: dilan.roe@acgov.org), File

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

May 28, 2014

Site Name & Address: CHEVRON #9-1851 451 HEGENBERGER RD Oakland, CA 94621 Local ID: RO0000464 Related ID: 541 RWQCB ID: 01-2429 Global ID: T0600102238

All Responsible Parties

RP has been named a Primary RP – ALEXIS FISCHER CHEVRON CORPORATION

6111 BOLLINGER CANYON ROAD RM 3660 | SAN RAMON, CA 94583 | Phone (925) 543-2961

RP has been named a Primary RP – MARK GOMEZ CITY OF OAKLAND

250 FRANK OGAWA PLAZA STE #5301 | OAKLAND, CA 94612-2034 | Phone (510) 238-7314

RP has been named a Primary RP -

SIMGAS LLC 655 MONTGOMERY ST, #1900 | SAN FRANCISCO, CA 94111-- | No Phone Number Listed

RP has been named a Primary RP - GURINDER GREWAL & SINGH NAVDEEP

349 BRIANNE CT | PLEASANTON, CA 94566-- | No Phone Number Listed

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."

2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."

3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."

May 28, 2014

Responsible Party Identification

Existence of Unauthorized Release

On October 11, 1995, five soil bores were installed at the site to characterize the subsurface beneath the site. Four of the soil bores were converted to groundwater monitoring wells MW-1 to MW-4. Concentrations up to 8.4 milligrams per kilogram (mg/kg) TPH as gasoline, 2,100 mg/kg Oil and Grease, and 0.0097 mg/kg ethylbenzene. Concentrations up to 170 micrograms per liter (μ g/I) TPH as gasoline, 1,600 μ g/I TPH as diesel, 3.5 μ g/I benzene, and 1.0 μ g/I ethylbenzene were detected in groundwater. These data indicate than an unauthorized release had occurred.

Responsible Party Identification

Chevron Corporation (Chevron) owned or operated the USTs at this site. Chevron is a responsible party for site because it owned or operated an UST used for the storage of a hazardous substance (Definition 1), owned or operated the UST immediately before the discontinuation of its use (Definition 2), and had control over an UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

The City of Oakland had purchased the site by January 1, 2000 and is a responsible party because it owned the property where an unauthorized release has occurred (Definition 3).

Simgas LLC purchased the property in March 2005, and operated the USTs at the site. Simgas is a responsible party because it owned the property where an unauthorized release has occurred (Definition 3),



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

May 28, 2014

NOTICE OF RESPONSIBILITY

Site Name & Address: CHEVRON #9-1851 451 HEGENBERGER RD Oakland, CA 94621

CHEVRON CORPORATION

SAN RAMON CA 94583

6111 BOLLINGER CANYON ROAD RM 3660

 Local ID: Related ID:	RO0000464 541	
 RWQCB ID: Global ID:	01-2429 T0600102238	

Responsible Party:

ALEXIS FISCHER

Date First Reported:

Substance:

8006619 Gasoline-Automotive (motor gasoline and additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

2/23/1996

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CHEVRON CORPORATION as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your paseworker DETTERMAN, MARK, at this office at (510)567-6876 if you have questions regarding your site.

-65				
		Date:	65	17
ARIU LEVI, Director	. .			

ARIU LEVI, Director Contract Project Director Action: Add Reason: ADD

Attachment A: Responsible Parties Data Sheet

cc: Sally Meza, SWRCB (email: smeza@waterboards.ca.gov) | Dilan Roe (email: dilan.roe@acgov.org), File

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

May 28, 2014

Site Name & Address: CHEVRON #9-1851 451 HEGENBERGER RD Oakland, CA 94621 Local ID: RO0000464 Related ID: 541 RWQCB ID: 01-2429 Global ID: T0600102238

All Responsible Parties

RP has been named a Primary RP – ALEXIS FISCHER CHEVRON CORPORATION

6111 BOLLINGER CANYON ROAD RM 3660 | SAN RAMON, CA 94583 | Phone (925) 543-2961

RP has been named a Primary RP – MARK GOMEZ CITY OF OAKLAND

250 FRANK OGAWA PLAZA STE #5301 | OAKLAND, CA 94612-2034 | Phone (510) 238-7314

RP has been named a Primary RP -

SIMGAS LLC 655 MONTGOMERY ST, #1900 | SAN FRANCISCO, CA 94111-- | No Phone Number Listed

RP has been named a Primary RP - GURINDER GREWAL & SINGH NAVDEEP

349 BRIANNE CT | PLEASANTON, CA 94566-- | No Phone Number Listed

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."

2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."

3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."

May 28, 2014

Responsible Party Identification

Existence of Unauthorized Release

On October 11, 1995, five soil bores were installed at the site to characterize the subsurface beneath the site. Four of the soil bores were converted to groundwater monitoring wells MW-1 to MW-4. Concentrations up to 8.4 milligrams per kilogram (mg/kg) TPH as gasoline, 2,100 mg/kg Oil and Grease, and 0.0097 mg/kg ethylbenzene. Concentrations up to 170 micrograms per liter (μ g/I) TPH as gasoline, 1,600 μ g/I TPH as diesel, 3.5 μ g/I benzene, and 1.0 μ g/I ethylbenzene were detected in groundwater. These data indicate than an unauthorized release had occurred.

Responsible Party Identification

Chevron Corporation (Chevron) owned or operated the USTs at this site. Chevron is a responsible party for site because it owned or operated an UST used for the storage of a hazardous substance (Definition 1), owned or operated the UST immediately before the discontinuation of its use (Definition 2), and had control over an UST at the time of or following an unauthorized release of a hazardous substance (Definition 4).

The City of Oakland had purchased the site by January 1, 2000 and is a responsible party because it owned the property where an unauthorized release has occurred (Definition 3).

Simgas LLC purchased the property in March 2005, and operated the USTs at the site. Simgas is a responsible party because it owned the property where an unauthorized release has occurred (Definition 3),