STATE WATER RESOURCES CONTROL BOARD DIVISION OF CLEAN WATER PROGRAMS

2014 T STREET, SUITE 130 P.O. BOX 944212 SACRAMENTO, CA 94244-2120

(916) 227-4325 FACSIMILE (916) 227-4349

JAN 0 2 1996



Ditas F. Jaluague Bank of America Properties, Inc. 560 Davis Street San Francisco, CA 94111

Dear Mr. Jaluague:

UNDERGROUND STORAGE TANK (UST) LOCAL OVERSIGHT PROGRAM, SITE NO. 3818, 500 HIGH STREET, OAKLAND, CALIFORNIA, COUNTY OF ALAMEDA

This is in response to your letter dated November 20, 1995 regarding the sale of the subject site to High Street Bridge Self-Storage. Along with a copy of this letter, I am forwarding your letter to Barney Chan of the County for appropriate action. Please be aware that if High Street Bridge Self-Storage is identified as a responsible party, both of you will be considered jointly and severally responsible for site cleanup. Both parties will receive the same invoice and it will be up to both parties to arrange for payment.

If you have any questions, please telephone me at (916) 227-4325.

Sincerely,

Lori Casias

L'asias

Local Oversight Program

cc: Barney Chan (w/enclosure)

Alameda County

Department of Environmental Health

Hazardous Materials Division

1131 Harbor Bay Parkway, 2nd Floor

Alameda, CA 94502



CRES-OREO 3786

November 20, 1995

State Water Resources Control Board Underground Storage Tank Local Oversight Program P.O. Box 944212 Sacramento. CA 94244-2120

Re: Property Address: 500 High Street, Oakland, CA

Site Number: 3818

Enclosed is the invoice for oversight costs on the above noted property for your disposition.

This is to advise you that the property closed escrow on <u>December 30, 1994</u>. Please mark your records to forward all future statements, inquiries, billings, correspondence to the new owner and therefore request that you close this account accordingly:

High Street Bridge Self- Storage c/o Douglas Thielscher

Any information relative to the sale of this property should be coordinated with Jim Bohar of CB Commercial at (510) 874-1996. He was the listing broker who represented the Bank during the sale transaction.

If you have any further questions, please call me at (415) 953-5855.

Very truly yours.

Ditas F. Jaluague Section Administrator

On The

/dfj

enclosures



Mary

1829 Clement Avenue Alameda, California 94501-1396 (510) 521-3773 FAX: (510) 865-2594				ATTENTION: Ms. Andee Gerace-Coles					
				SUBJECT: 500 High Street					
				Oakland, CA					
	f America mental Service	s #4122					्री हता इस		
555 An	ton Boulevard,	Suite 1025		_					
Costa N	Mesa, CA 92626	3							
□ I:	are sending y nvoice lopy of letter		X Report □ Prints □ Plans		Work Order Change Order	□ Specificatio			
Copies	Date	Number	Description						
4	August 9, 1995		Final copy Sec Report	cond Quar	ter 1995 Quarter	ly Groundwater S	Sampling		
The	ese are transm	itted as cl	necked below:			•			
□ F X A □ F	or signature or payment s requested or approval OR BIDS DUE		<ul> <li>□ Approved as submitted</li> <li>□ Approved as noted</li> <li>□ Returned for Corrections</li> <li>□ For review and comment</li> <li>□ For your use</li> </ul>			☐ Resubmitcopies for approval ☐ Submitcopies for distribution ☐ Returncorrected prints			
REMARK	is:								
	<del></del>						· · · · · · - ·		
	<u> </u>								

COPY TO: File

Mr. Barney Chan, ACHCSA Mr. Sum Arigala, RWQCB SIGNED: Mark E. Detterman

LETTER OF TRANSMITTAL


BEI Job No. 92242.2

DATE August 11, 1995

## HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



June 27, 1995 StID # 3818 ROUNTS

ALAMEDA COUNTY-ENV. HEALTH DEPT. ENVIRONMENTAL PROTECTION DIV.; 1131 HARBOR BAY PKWY., #250 ALAMEDA CA 94502-6577 (510)567-6700

Ms. Andee Gerace-Coles Bank of America Environmental Services 555 Anton Blvd. Suite 1025 Costa Mesa, CA 92626

Re: Work Plan Approval for Installation of MW-8 for 500 High St. Oakland CA 94601

Dear Ms. Gerace-Coles:

Our office has received and reviewed Blymyer Engineer's June 21, 1995 work plan for the installation of one additional off-site monitoring well located between existing monitoring wells MW-5 and MW-7 (on Mr. Minor's property). This well will be designated MW-8. Consistent with the conclusions derived from the joint March 27, 1995 meeting, this well installation is approved and should proceed at your consultant's earliest convenience. As you are aware, the analytical results from this well will be used as part of the baseline risk assessment to estimate the health risk to the residents in this area.

Please inform me at least 48 working hours prior to well installation so I may arrange to be present if possible.

Recall also that a work plan for further subsurface investigation on Mr. Minor's property, 4341 Howard St., has also been approved. Although it would be ideal to perform both investigations at the same time, as a matter of expediency, each investigation should proceed as soon as possible.

You may contact me at (510) 567-6765 if you have any questions.

Sincerely,

Barney M. Chan

Hazardous Materials Specialist

cc: M. Detterman, Blymyer Engineers, 1829 Clement Ave., Alameda CA 94501-1395

S. Arigala, RWQCB

James Ullan

- T. Fortner, Artesian Environmental, 3175 Kerner Blvd., Suite E, San Rafael, CA 94901
- J. Minor, 1925 Alameda, P.O. Box 726, Diablo, CA 94528
- J. Makishima, files

MWwp500

RO635

CL

September 22, 1994 BEI Job No. 92242

BLYMYER

Mr. Barney Chan
Alameda County Health Care Services Agency
Department of Environmental Health
1131 Harbor Bay Parkway
Alameda, CA 94502-6577

Subject:

Well Construction Details Former Cobbledick-Kibbe Site, 500 High Street, Oakland, California

Dear Mr. Chan:

During a recent review of boring logs and well construction details at the subject site, originally reported in the *Phase I Subsurface Investigation, Former Cobbledick-Kibbe Site*, by Blymyer Engineers, Inc., dated November 11, 1992, it was noted that the reported well screen intervals in groundwater monitoring wells MW-1 through MW-4 did not appear to be properly placed with respect to the water-bearing zone encountered in each well. A review of the original bore logs, a physical measurement of the top of the well screen and the well casing bottom in the field, and consultation of available information on the original drilling invoices, indicate these recent observations are correct. The following table describes pertinent data, both the previously reported, and the corrected, well construction details.

Table I, Revised Monitoring Well Construction Details  MW-1 through MW-4  BEI Job No. 92242, Bank of America  500 High Street, Oakland, California												
Well Number	Total Bore Depth (feet)	Previous Reported Casing Length (bgs)	Previous Reported Blank Casing Interval (bgs)	Previous Reported Screen Interval (bgs)	Correct Well Length (feet)	Corrected Blank Casing Interval (bgs)	Correct Screen Interval (bgs)					
MW-1	23.5	23	0 - 11	13 - 23	18	0 - 8	8 - 18					
MW-2	25	24.5	0 - 14	14 - 24	18	0 - 8	8 - 18					
MW-3	25	24.5	0 - 14	14 - 24	20	0 - 10	10 - 20					
MW-4	25	24.5	0 - 14	14 - 24	18	0 - 8	8 - 18					

bgs = below grade surface

Adjustments in the recorded depth intervals occupied by backfill materials are also required to complete this modification of the well construction details. It is assumed that the relationship of these materials to the well casing intervals remains consistent (ie sand 1 to 2 feet above the screened interval, 1 foot of bentonite above the sand, etc.)

Should you have any questions, or require additional information, please call the undersigned at (510) 521-3773.



Sincerely,

Blymyer Engineers, Inc.

Mark E. Detterman, C.E.G. 1788

Senior Geologist

John Morrison R.G. 5773

Director, Earth Sciences

cc. Ms. Andee Gerace-Coles, Bank of America Environmental Services

Mr. Carl Becker, Bank of America, OREO Property Management

Mr. Wyman Hong, Zone 7 Water Agency

Mr. Kevin Grave, San Francisco Water Quality Control Board

markd\92242\wellcon.994