

ALAMEDA COUNTY
HEALTH CARE SERVICES
AGENCY



DAVID J. KEARS, Agency Director

R01023

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

Certified Mail # P 113 815 484

06/24/93
STID# 1090

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Notice of Requirement to Reimburse

Nancy Bush
Stephens Partnership No. 14
550 Montgomery, 10th Fl.
San Francisco, Ca 94111

Responsible Party #1
Property Owner

James P. O'neil
Goodyear Tire & Rubber Co.
1000 N. Kraemer Pl.
Anaheim, Ca 92806

Responsible Party #2
Contact Person
Contact Company

Goodyear Service Station
2025 Telegraph Ave.
Oakland, CA 94612

SITE

Date First Reported 04/17/92
Substance: Waste Oil
Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III
Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use: Update Reason: New owner RP#3



Certified Mail # P 113 815 483

06/22/93
STID# 1090

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Nancy Bush
Stephens Partnership No. 14
550 Montgomery, 10th Fl.
San Francisco, Ca 94111

Responsible Party #1
Property Owner

James P. O'neil
Goodyear Tire & Rubber Co.
1000 N. Kraemer Pl.
Anaheim, Ca 92806

Responsible Party #2
Contact Person
Contact Company

Goodyear Service Station
2025 Telegraph Ave.
Oakland, CA 94612

SITE

Date First Reported 04/17/92
Substance: Waste Oil
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use: Update : X Reason: new owner RP#3

ALAMEDA COUNTY
HEALTH CARE SERVICES



AGENCY

DAVID J. KEARS, Agency Director

R01023

RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P 113 815 482

06/22/93
STID# 1090

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Nancy Bush
Stephens Partnership No. 14
550 Montgomery, 10th Fl.
San Francisco, Ca 94111

Responsible Party #1
Property Owner

Tom Deuel
First Republic
388 Market St. 2nd Floor
San Francisco, Ca 94111

Responsible Party #3
Contact Person
Contact Company

Goodyear Service Station
2025 Telegraph Ave.
Oakland, CA 94612

SITE

Date First Reported 04/17/92
Substance: Waste Oil
Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Update: Reason: new owner RP#3

ALAMEDA COUNTY - DEPARTMENT OF ENVIRONMENTAL HEALTH
HAZARDOUS MATERIALS DIVISION

06/22/93

LIST OF RESPONSIBLE PARTIES FOR

SITE StID: 1090
Goodyear Service Station
2025 Telegraph Ave.
Oakland, CA 94612

Date First Reported 04/17/92
Substance: Waste Oil
Petroleum (X)Yes

Nancy Bush
Stephens Partnership No. 14
550 Montgomery, 10th Fl.
San Francisco, Ca 94111

Responsible Party #1
Property Owner

James P. O'neil
Goodyear Tire & Rubber Co.
1000 N. Kraemer Pl.
Anaheim, Ca 92806

Responsible Party #2
Contact Person
Contact Company

Tom Deuel
First Republic
388 Market St. 2nd Floor
San Francisco, Ca 94111
(415)392-1400

Responsible Party #3
Contact Person
Contact Company

ALAMEDA COUNTY - DEPARTMENT OF ENVIRONMENTAL HEALTH
HAZARDOUS MATERIALS DIVISION

06/22/93

LIST OF RESPONSIBLE PARTIES FOR

SITE	StID: 1090 Goodyear Service Station 2025 Telegraph Ave. Oakland, CA 94612
------	--

Date First Reported 04/17/92
Substance: Waste Oil
Petroleum (X)YesNancy Bush
Stephens Partnership No. 14
550 Montgomery, 10th Fl.
San Francisco, Ca 94111Responsible Party #1
Property OwnerJames P. O'neil
Goodyear Tire & Rubber Co.
1000 N. Kraemer Pl.
Anaheim, Ca 92806Responsible Party #2
Contact Person
Contact CompanyTom Deuel
First Republic
388 Market St. 2nd Floor
San Francisco, Ca 94111
(415)392-1400Responsible Party #3
Contact Person
Contact Company

ALAMEDA COUNTY
HEALTH CARE SERVICES
AGENCY

DAVID J. KEARS, Agency Director



R01023

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Certified Mail #

05/04/93
STID# 1090

Notice of Requirement to Reimburse

Nancy Bush
Stephens Partnership No. 14
550 Montgomery, 10th Fl.
San Francisco, Ca 94111

Responsible Party #1
Property Owner

James P. O'neil
Goodyear Tire & Rubber Co.
1000 N. Kraemer Pl.
Anaheim, Ca 92806

Responsible Party #2
Contact Person
Contact Company

Goodyear Service Station
2025 Telegraph Ave.
Oakland, CA 94612

SITE

Date First Reported 04/17/92
Substance: Waste Oil
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Update : X Reason: New RP#2 address

ALAMEDA COUNTY
HEALTH CARE SERVICES
AGENCY

DAVID J. KEARS, Agency Director



R01023

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Certified Mail #

05/04/93
STID# 1090

Notice of Requirement to Reimburse

Nancy Bush
Stephens Partnership No. 14
550 Montgomery, 10th Fl.
San Francisco, Ca 94111

Responsible Party #1
Property Owner

James P. O'neil
Goodyear Tire & Rubber Co.
1000 N. Kraemer Pl.
Anaheim, Ca 92806

Responsible Party #2
Contact Person
Contact Company

Goodyear Service Station
2025 Telegraph Ave.
Oakland, CA 94612

SITE

Date First Reported 04/17/92
Substance: Waste Oil
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.


Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use: update Reason: New RP#2 address



Certified Mail # P113 815 121

07/17/92
STID# 1090

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Nancy Bush
Stephens Partnership No. 14
550 Montgomery, 10th Fl.
San Francisco, Ca 94111

Responsible Party #1
Property Owner

Rick Huseman
Goodyear Tire & Rubber Co.
1800 Merced Street
San Leandro, Ca 94577


Responsible Party #2
Contact Person
Contact Company

Goodyear Service Station
2025 Telegraph Ave.
Oakland, CA 94612

SITE Date First Reported 04/17/92
Substance: Waste Oil
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Susan HUGO, Hazardous Materials Specialist at this office if you have any questions concerning this matter.


Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use: Add: X Reason: New Case



Certified Mail # P113 815 102

07/17/92
STID# 1090

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Nancy Bush
Stephens Partnership No. 14
550 Montgomery, 10th Fl.
San Francisco, Ca 94111

Responsible Party #1
Property Owner

Rick Huseman
Goodyear Tire & Rubber Co.
1800 Merced Street
San Leandro, Ca 94577

Responsible Party #2
Contact Person
Contact Company

Goodyear Service Station
2025 Telegraph Ave.
Oakland, CA 94612

SITE

Date First Reported 04/17/92
Substance: Waste Oil
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Susan HUGO, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III
for Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case