

ALAMEDA COUNTY
HEALTH CARE SERVICES
AGENCY

DAVID J. KEARS, Agency Director



R01083

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

Certified Mail *(Not)*

07/22/93
STID# 519

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Notice of Requirement to Reimburse

Ms. Marla Guensler
Exxon Co., Usa
2300 Clayton Rd. Ste 1250
Concord, C A 94520

Responsible Party #1
Property Owner

Parviz Darabi
Exxon Service Station 7-0234
3450-35th Av
Oakland, C A 94619

Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0234
3450 35th Ave.
Oakland, CA 94619

SITE

Date First Reported 03/20/91
Substance: Gasoline
Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Susan HUGO, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III
Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Change: X Reason: New RP-#1 Address

ALAMEDA COUNTY
HEALTH CARE SERVICES
AGENCY

DAVID J. KEARS, Agency Director



R01083

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

Certified Mail # (Not)

07/22/93
STID# 519

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Notice of Requirement to Reimburse

Ms. Marla Guensler
Exxon Co., Usa
2300 Clayton Rd. Ste 1250
Concord, C A 94520

Responsible Party #1
Property Owner

Parviz Darabi
Exxon Service Station 7-0234
3450-35th Av
Oakland, C A 94619

Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0234
3450 35th Ave.
Oakland, CA 94619

SITE

Date First Reported 03/20/91
Substance: Gasoline
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Susan HUGO, Hazardous Materials Specialist at this office if you have any questions concerning this matter.


Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use: Change Reason: New RP #1 address



Certified Mail #P367 604 728

03/09/92
STID# 519

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Warren Ault
Exxon Corporation
2300 Clayton Rd. Ste 1250
Concord, C A 94520

Responsible Party #1
Property Owner

Parviz Darabi
Exxon Service Station 7-0234
3450-35th Av
Oakland, C A 94619

Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0234
3450 - 35th Ave.
Oakland, CA 94619

SITE Date First Reported 03/20/91
Substance: Gasoline
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case



Certified Mail # P 367 604 727

03/09/92
STID# 519

Notice of Requirement to Reimburse

Warren Ault
Exxon Corporation
2300 Clayton Rd. Ste 1250
Concord, C A 94520

Responsible Party #1
Property Owner

Parviz Darabi
Exxon Service Station 7-0234
3450-35th Av
Oakland, C A 94619

Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0234
3450 - 35th Ave.
Oakland, CA 94619

SITE

Date First Reported 03/20/91
Substance: Gasoline
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case