



3400 Manor Street • Bakersfield, CA 93308 • 661-393-1151 • 800-458-3036 • 661-393-0588 fax • www.inpenviro.com

FAXED

FACSIMILE TRANSMITTAL SHEET

TO: Robert Weston FROM: Amanda Little
 COMPANY: Environmental Health DATE: 4.8.05
 FAX NUMBER: (510) 337-9335 TOTAL NO. OF PAGES INCLUDING COVER: 14
 PHONE NUMBER: RETURN FAX: (661) 393-3834

RE: UST Removal - Dublin, CA Site

URGENT FOR REVIEW PLEASE COMMENT PLEASE REPLY PLEASE RECYCLE

NOTES/COMMENTS:

Health & Safety Plan will follow via a second fax

(* 23 page SSHP

COMMITMENT, SERVICE, DEDICATION AND RELIABILITY...
TO OUR CUSTOMERS AND OUR ENVIRONMENT.

**MP Environmental Services, Inc
Work Plan for UST removal
Busick-Gearing
6341 Scarlett Court
Dublin, CA**

Page One

Site description:

The site location is 6341 Scarlett Court Dublin, CA.
Site map and plot plan attached

EPA LD.NO. (Under which the tanks and associated piping will be manifested

On-site Contractors:

Prime Contractor- Arcadis
Sub Contractor- MP Environmental

Contacts:

MP Environmental - Jim Hickle 661/303-3774
Arcadis - David Gomes 510-918-8121

State Registered Hazardous Waste Transporters/Facility

Bulk Liquid- Romic Environmental Technologies 2081 Bay Rd East Palo Alto
Ca
Tanks and associated piping- Ecology Control Industries, Inc 255 Tarr Blvd
Richmond Ca 94801

Page Two

Treatment of UST's prior to removal:

The tanks will be evacuated of residual liquid via vacuum truck (MP Environmental Services, Inc Contractors License # 613706 HAZ.) The tank rinsate will be manifested on a Uniform Hazardous Waste Manifest and transported via vacuum truck to Romac Environmental East Palo Alto, CA for disposal.

Inerting the tanks will be done by adding dry ice to the tanks. A total of 45 pounds of dry ice will be used (30 LB per 1,000 gal & 15 LB per 500gal). Dry ice will be placed into tanks upon the arrival of agencies.

The tanks will be transported to Ecology Control Industries in Richmond Ca as a Hazardous Waste

Air and vapor monitoring will be performed using an RKI four gas meter that will be calibrated the day prior to use.

Equipment to be used on site:

MP will utilize a 15-ton hydraulic crane to remove the tanks from the ground and load onto a flatbed for transport.

Sampling will be performed using the bucket of a Backhoe to collect the soil from beneath the tanks.

Excavation status:

The excavation will be backfilled and compacted with new and clean excavated soils.

Page Three

Safety:

The minimum PPE required on site is Hard Hat, Safety glasses, steel toed boots.

Safety items located on site will be at the minimum first aid kit, emergency eyewash, fire, extinguisher, (40lb)

Pleasanton Urgent Care Medical located at 3128 Santa Rita Rd will be the nearest medical facility. (925-462-9300)

Shoring is not necessary or required.

MP Environmental Services safety person is Kevin Terrio 661/393-1151.

There will be no overhead obstructions.

Arcadis will notify USA Dig Alert prior to our commencing operations

If you should have any questions or concerns feel free to contact me at 800/458-3036.

Jim Hickle
Project Manger