

Drogos, Donna, Env. Health

Subject: RO2949 - 638-632 2nd
Entry Type: Phone call

Start: Mon 7/16/2007 4:00 PM
End: Mon 7/16/2007 4:00 PM
Duration: 0 hours

07/16/07, 4p
Mathew Rider Smith, Clearwater

Listing site. Need all contact info for RP: Company, person's name, address, phone, e-mail.

Map in report: cannot tell where borings located. Map not in context, building not shown, distance to X-streets not shown, etc. Need appropriately scaled map that shows buildings & streets & borings in relation to. He is concerned scale will be too small to see borings, rec'd he make 11x17 map.

Address is not 626 2nd, has other addresses, he will provide. Are borings actually in front of Ace Hardware, as it is on 3rd st. No, there is a music studio, Black Sea Gallery, etc. I need correct map.

Requested Addendum to report, with map in context, explanation of address situation, & submittal of Phase 1 & UST Cloure report to ftp site. Also any other reports re: env contamination.

Site is being refinanced. Told him its contaminated & all USTs, source & residual contamination left in place with UST in-place closure. Closure for this case will not proceed quickly. He said GW is contaminated. Yes, however there is a soil source present to generate GW plume. Soil borings very shallow....

Drogos, Donna, Env. Health

Subject: RO2949 - 623-636 2ND
Entry Type: Phone call

Start: Mon 7/16/2007 3:00 PM
End: Mon 7/16/2007 3:00 PM
Duration: 0 hours

Discuss site with Mathew Rider Smith, Clearwater

Unable to identify site with maps provided in report, need to list site by address of UST location. Maps provided do not show placement of UST in relation to different property addresses.

He will post an addendum to SWI that depicts UST locations in context.

He will also provide full contact info for RP