


UNITED STATES POSTAL SERVICE

RIO GRANDE DISTRICT

17 JUN 2008 PM 2 T



• Sender: Please print your name, address, and ZIP+4 in this box

JUN 19 2008

ENVIRONMENTAL HEALTH SERVICES  
Environmental Health Services  
Environmental Protection  
1131 Harbor Bay Pkwy, Suite 250  
Alameda, CA 94502-6577  
Attn: Barbara, R02973

R02973

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

C/O Eller Media  
Eltex Investments Corp  
200 E Basse  
San Antonio, TX 78209

2. Article (Tran)

PS Form

COMPLETE THIS SECTION ON DELIVERY

A. Signature  Agent  Addressee

B. Received by (Printed Name) C. Date of Delivery

D. Is delivery address different from item 1?  Yes  No  
If YES, enter delivery address below:

3. Service Type  
 Certified Mail  Express Mail  
 Registered  Return Receipt for Merchandise  
 Insured Mail  C.O.D.

4. Restricted Delivery? (Extra Fee)  Yes

2595-02-M-1540

R0. 2973  
MOR - L -  
2008 - 06 - 16

SENDER: COMPLETE THIS SECTION

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

Ignacio Dayrit  
City of Emeryville Redevelopment  
1333 Park Avenue  
Emeryville, CA 94608

2. Article Number (Transfer from service label)

COMPLETE THIS SECTION ON DELIVERY

A. Signature  Agent  Addressee

B. Received by (Printed Name) C. Date of Delivery

D. Is delivery address different from item 1?  Yes  No  
If YES, enter delivery address below:

3. Service Type  
 Certified Mail  Express Mail  
 Registered  Return Receipt for Merchandise  
 Insured Mail  C.O.D.

4. Restricted Delivery? (Extra Fee)  Yes

7002 2030 0006 9574 1365

PS Form 3811, February 2004

Domestic Return Receipt

192595-02-M-1540

*Ambassador Landers R02973*

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
<ul style="list-style-type: none"> <li>■ Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.</li> <li>■ Print your name and address on the reverse so that we can return the card to you.</li> <li>■ Attach this card to the back of the mailpiece, or on the front if space permits.</li> </ul>	<p>A. Signature  <input checked="" type="checkbox"/> <i>[Signature]</i> <input type="checkbox"/> Agent  <input type="checkbox"/> Addressee</p> <p>B. Received by (Printed Name) <span style="float: right;">C. Date of Delivery</span>  <i>C. GONZALEZ</i> <span style="float: right;"><i>6-13-08</i></span></p> <p>D. Is delivery address different from Item 1? <input type="checkbox"/> Yes            If YES, enter delivery address below: <input type="checkbox"/> No</p>
<p>1. Article Addressed to:</p> <p style="text-align: center;"><b>William Owens            Ambassador Partners Limited            2221 Olympic Boulevard            Walnut Creek, CA 94595</b></p>	<p>3. Service Type</p> <p><input type="checkbox"/> Certified Mail    <input type="checkbox"/> Express Mail  <input type="checkbox"/> Registered        <input type="checkbox"/> Return Receipt for Merchandise  <input type="checkbox"/> Insured Mail       <input type="checkbox"/> C.O.D.</p> <p>4. Restricted Delivery? (Extra Fee) <input type="checkbox"/> Yes</p>
<p>2. Article Number            (Transfer from service label) <span style="float: right;"><b>7002 2030 0006 9574 1396</b></span></p>	
<p>PS Form 3811, February 2004                      Domestic Return Receipt                      102595-02-M-1540</p>	

*Ambassador Landers R02973*

SENDER: COMPLETE THIS SECTION	COMPLETE THIS SECTION ON DELIVERY
<ul style="list-style-type: none"> <li>■ Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.</li> <li>■ Print your name and address on the reverse so that we can return the card to you.</li> <li>■ Attach this card to the back of the mailpiece, or on the front if space permits.</li> </ul>	<p>A. Signature  <input checked="" type="checkbox"/> <i>[Signature]</i> <input type="checkbox"/> Agent  <input type="checkbox"/> Addressee</p> <p>B. Received by (Printed Name) <span style="float: right;">C. Date of Delivery</span>  <i>C. GONZALEZ</i> <span style="float: right;"><i>6-13-08</i></span></p> <p>D. Is delivery address different from Item 1? <input type="checkbox"/> Yes            If YES, enter delivery address below: <input type="checkbox"/> No</p>
<p>1. Article Addressed to:</p> <p style="text-align: center;"><b>Scott Barde            Owens Mortgage Investment            Fund            2221 Olympic Boulevard            Walnut Creek, CA 94595</b></p>	<p>3. Service Type</p> <p><input type="checkbox"/> Certified Mail    <input type="checkbox"/> Express Mail  <input type="checkbox"/> Registered        <input type="checkbox"/> Return Receipt for Merchandise  <input type="checkbox"/> Insured Mail       <input type="checkbox"/> C.O.D.</p> <p>4. Restricted Delivery? (Extra Fee) <input type="checkbox"/> Yes</p>
<p>2. Article Number            (Transfer from service label) <span style="float: right;"><b>7002 2030 0006 9574 1372</b></span></p>	
<p>PS Form 3811, February 2004                      Domestic Return Receipt                      102595-02-M-1540</p>	



Certified Mail #: 7002 2030 0006 9574 1433

June 06, 2008

ENVIRONMENTAL HEALTH SERVICES  
ENVIRONMENTAL PROTECTION  
1131 Harbor Bay Parkway, Suite 250  
Alameda, CA 94502-6577  
(510) 567-6700  
FAX (510) 337-9335

**NOTICE OF RESPONSIBILITY**

**Site Name & Address:**

**AMBASSADOR LAUNDRY  
3623 ADELIN ST  
EMERYVILLE, CA 94608**

**Local ID: RO0002973  
Related ID: NA  
RWQCB ID: NA  
Global ID: T0619717287**

**Responsible Party:**

**LLOYD W. KENDALL JR  
EXCHANGE SUPPORT SERVICES INC  
180 GRAND AVE STE #1385  
OAKLAND CA 94612-3741**

**Date First Reported: 4/28/2008**

**Substance: 12034,12035,14,8006619 Multiple Releases**

**Funding for Oversight: LOPS - LOP State Fund**


**Multiple RPs?: Yes**

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CITY OF EMERYVILLE REDEVELOPMENT as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for

Please contact your caseworker JAKUB, BARBARA, at this office at (510)639-1287 if you have questions regarding your site.

  
\_\_\_\_\_  
ARIU LEVI, Director  
Contract Project Director

Date: 6/10/08

Action: Add  
Reason: New case

ALAMEDA COUNTY ENVIRONMENTAL HEALTH  
LUFT LOCAL OVERSIGHT PROGRAM

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

June 06, 2008

**Site Name & Address:**

**AMBASSADOR LAUNDRY**  
**3623 ADELINE ST**  
**EMERYVILLE, CA 94608**

**Local ID: RO0002973**  
**Related ID: NA**  
**RWQCB ID: NA**  
**Global ID: T0619717287**

**All Responsible Parties**

---

**RP has been named a Primary RP - IGNACIO DAYRIT**  
**CITY OF EMERYVILLE REDEVELOPMENT**  
1333 PARK AVE | EMERYVILLE, CA 94608 | Phone (510) 596-4356

---

**RP has been named a RP - SCOTT BARDE**  
**OWENS MORTGAGE INVESTMENT FUND**  
2221 OLYMPIC BLVD | WALNUT CREEK, CA 94595 | Phone (510) 935-3840

---

**RP has been named a RP - UNK2835 UNK2835**  
**WILSON ASSOCIATES**  
6451 BENVENUE AVE | OAKLAND, CA 94618-1305 | Phone No Phone Number Listed

---

**RP has been named a RP - WILLIAM OWENS**  
**AMBASSADOR PARTNERS LIMITED**  
2221 OLYMPIC BLVD | WALNUT CREEK, CA 94595 | Phone No Phone Number Listed

---

**RP has been named a RP - C/O BELLVIEW CAPITAL MGM**  
**TITLE TWO INVESTMENT CORPORATION**  
POB 10206 | OAKLAND, CA 94610-0206 | Phone No Phone Number Listed

---

**RP has been named a RP - C/O ELLER MEDIA**  
**ELTEX INVESTMENTS CORP**  
200 E BASSE | SAN ANTONIO, TX 78209 | Phone No Phone Number Listed

---

**RP has been named a RP - C/O ELLER MEDIA**  
**ADELINE INVESTMENTS**  
2533 N CARSON ST #A324 | CARSON CITY, NV 89706 | Phone No Phone Number Listed

---

**RP has been named a RP - LLOYD W KENDALL JR**  
**EXCHANGE SUPPORT SERVICES INC**  
180 GRAND AVE STE #1385 | OAKLAND, CA 94612-3741 | Phone No Phone Number Listed

---

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET (Continued)

June 06, 2008

### **Responsible Party Identification Background**

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R. Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

ACEH has named the responsible parties for this site as detailed below.

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET (Continued)

June 06, 2008

### Responsible Party Identification

RO2973, 3623 Adeline St., Emeryville

#### Existence of Unauthorized Release

A UST identified in a geophysical survey was removed on October 30, 2007. Subsequent soil sampling detected total petroleum hydrocarbons as diesel (TPHd) at a maximum concentration of 1,200 milligrams per kilogram (mg/Kg), and total petroleum hydrocarbons as gasoline (TPHg) at a maximum of 31 mg/Kg in soil. Groundwater samples contained maximum concentrations of 398 micrograms per liter (ug/L) benzene, 598 ug/L toluene, 604 ug/L ethylbenzene and 2.05 ug/L methyl tertiary butyl alcohol (MTBE).

#### Responsible Party Identification

Ambassador Business was the business owner, tank owner and property owner following and/or perhaps at the time of the release(s). Ambassador Business meets the definition of a responsible party for the site because they owned and operated the underground storage tanks (Definition 1), formerly owned the property where an unauthorized release occurred, (Definition 3), and may have had control of an underground storage tank at the time of an unauthorized release (Definition 4).

Owens Mortgage Investment Fund purchased the property in May 1994. Owens Mortgage Investment Fund meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Title Two Investment Corporation purchased the property in December 1997. Title Two Investment Corporation meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Adeline Investments, Inc. purchased the property in July 1999. Adeline Investments, Inc. meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Eltex Investment Inc. purchased the property in May 1994. Eltex Investment Inc. meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Exchange Support Services, Inc. purchased the property in May 1994. Exchange Support Services, Inc. meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Wilson Associates purchased the property in May 1994. Wilson Associates meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Emeryville Redevelopment Agency purchased the property in July 2003. The City of Emeryville meets the definition of a responsible party for the site because they are the current owners of a property where an unauthorized release of hazardous substance from an underground storage tank occurred (Definition 3), they owned the underground storage tanks (Definition 1).

**SENDER: COMPLETE THIS SECTION**

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

**Lloyd W. Kendall Jr.**  
**Exchange Support Services Inc.**  
**180 Grand Avenue, Suite 1385**  
**Oakland, CA 94612-3741**

2. Article Number  
(Transfer from service label)

7002 2030 0006 9574 1433

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

**COMPLETE THIS SECTION ON DELIVERY**

A. Signature

X

- Agent  
 Addressee

B. Received by (Printed Name)

C. Date of Delivery

D. Is delivery address different from item 1?  Yes  
 If YES, enter delivery address below:  No

3. Service Type

- Certified Mail  Express Mail  
 Registered  Return Receipt for Merchandise  
 Insured Mail  C.O.D.

4. Restricted Delivery? (Extra Fee)

Yes

**CERTIFIED MAIL™**



7002 2030 0006 9574 1433



ALAMEDA COUNTY  
**HEALTH CARE SERVICES AGENCY**  
 Department Of Environmental Health  
 Environmental Protection Division  
 1131 Harbor Bay Parkway  
 Alameda, CA 94502-6577

**RECEIVED**  
 JUN 17 2008  
 ENVIRONMENTAL HEALTH SERVICES


**Lloyd W. Kendall Jr.**  
**Exchange Support Services Inc.**  
**180 Grand Avenue, Suite 1385**  
**Oakland, CA 94612-3741**

NIXIE 945 DE 1 00 06/14/08

RETURN TO SENDER  
 NOT DELIVERABLE AS ADDRESSED  
 UNABLE TO FORWARD

BC: 94502654031 \*1805-06982-12-06

945026540





Certified Mail #: 7002 2030 0006 9574 1426

June 06, 2008

ENVIRONMENTAL HEALTH SERVICES  
ENVIRONMENTAL PROTECTION  
1131 Harbor Bay Parkway, Suite 250  
Alameda, CA 94502-6577  
(510) 567-6700  
FAX (510) 337-9335

**NOTICE OF RESPONSIBILITY**

**Site Name & Address:**

**AMBASSADOR LAUNDRY  
3623 ADELINE ST  
EMERYVILLE, CA 94608**

**Local ID: RO0002973  
Related ID: NA  
RWQCB ID: NA  
Global ID: T0619717287**

**Responsible Party:**

**C/O ELLER MEDIA  
ADELINE INVESTMENTS  
2533 N CARSON ST #A324  
CARSON CITY NV 89706**

**Date First Reported: 4/28/2008**

**Substance: 12034,12035,14,8006619 Multiple Releases**

**Funding for Oversight: LOPS - LOP State Fund**

**Multiple RPs?: Yes**

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CITY OF EMERYVILLE REDEVELOPMENT as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for

Please contact your caseworker JAKUB, BARBARA, at this office at (510)639-1287 if you have questions regarding your site.

  
ARIU LEV, Director  
Contract Project Director

Date: 6/11/08

Action: Add  
Reason: New case



ALAMEDA COUNTY ENVIRONMENTAL HEALTH  
LUFT LOCAL OVERSIGHT PROGRAM

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

June 06, 2008

**Site Name & Address:**

**AMBASSADOR LAUNDRY**  
**3623 ADELINE ST**  
**EMERYVILLE, CA 94608**

**Local ID: RO0002973**

**Related ID: NA**

**RWQCB ID: NA**

**Global ID: T0619717287**

**All Responsible Parties**

**RP has been named a Primary RP - IGNACIO DAYRIT**  
**CITY OF EMERYVILLE REDEVELOPMENT**  
1333 PARK AVE | EMERYVILLE, CA 94608 | Phone (510) 596-4356

**RP has been named a RP - SCOTT BARDE**  
**OWENS MORTGAGE INVESTMENT FUND**  
2221 OLYMPIC BLVD | WALNUT CREEK, CA 94595 | Phone (510) 935-3840

**RP has been named a RP - UNK2835 UNK2835**  
**WILSON ASSOCIATES**  
6451 BENVENUE AVE | OAKLAND, CA 94618-1305 | Phone No Phone Number Listed

**RP has been named a RP - WILLIAM OWENS**  
**AMBASSADOR PARTNERS LIMITED**  
2221 OLYMPIC BLVD | WALNUT CREEK, CA 94595 | Phone No Phone Number Listed

**RP has been named a RP - C/O BELLVIEW CAPITAL MGM**  
**TITLE TWO INVESTMENT CORPORATION**  
POB 10206 | OAKLAND, CA 94610-0206 | Phone No Phone Number Listed

**RP has been named a RP - C/O ELLER MEDIA**  
**ELTEX INVESTMENTS CORP**  
200 E BASSE | SAN ANTONIO, TX 78209 | Phone No Phone Number Listed

**RP has been named a RP - C/O ELLER MEDIA**  
**ADELINE INVESTMENTS**  
2533 N CARSON ST #A324 | CARSON CITY, NV 89706 | Phone No Phone Number Listed

**RP has been named a RP - LLOYD W KENDALL JR**  
**EXCHANGE SUPPORT SERVICES INC**  
180 GRAND AVE STE #1385 | OAKLAND, CA 94612-3741 | Phone No Phone Number Listed

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET (Continued)

June 06, 2008

### Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R. Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

ACEH has named the responsible parties for this site as detailed below.

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET (Continued)

June 06, 2008

### Responsible Party Identification

RO2973, 3623 Adeline St., Emeryville

#### Existence of Unauthorized Release

A UST identified in a geophysical survey was removed on October 30, 2007. Subsequent soil sampling detected total petroleum hydrocarbons as diesel (TPHd) at a maximum concentration of 1,200 milligrams per kilogram (mg/Kg), and total petroleum hydrocarbons as gasoline (TPHg) at a maximum of 31 mg/Kg in soil. Groundwater samples contained maximum concentrations of 398 micrograms per liter (ug/L) benzene, 598 ug/L toluene, 604 ug/L ethylbenzene and 2.05 ug/L methyl tertiary butyl alcohol (MTBE).

#### Responsible Party Identification

Ambassador Business was the business owner, tank owner and property owner following and/or perhaps at the time of the release(s). Ambassador Business meets the definition of a responsible party for the site because they owned and operated the underground storage tanks (Definition 1), formerly owned the property where an unauthorized release occurred, (Definition 3), and may have had control of an underground storage tank at the time of an unauthorized release (Definition 4).

Owens Mortgage Investment Fund purchased the property in May 1994. Owens Mortgage Investment Fund meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Title Two Investment Corporation purchased the property in December 1997. Title Two Investment Corporation meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Adeline Investments, Inc. purchased the property in July 1999. Adeline Investments, Inc. meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Eltex Investment Inc. purchased the property in May 1994. Eltex Investment Inc. meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Exchange Support Services, Inc. purchased the property in May 1994. Exchange Support Services, Inc. meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Wilson Associates purchased the property in May 1994. Wilson Associates meets the definition of a responsible party for the site because they formerly owned the property where an unauthorized release occurred (Definition 3).

Emeryville Redevelopment Agency purchased the property in July 2003. The City of Emeryville meets the definition of a responsible party for the site because they are the current owners of a property where an unauthorized release of hazardous substance from an underground storage tank occurred (Definition 3), they owned the underground storage tanks (Definition 1).

**SENDER: COMPLETE THIS SECTION**

- Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired.
- Print your name and address on the reverse so that we can return the card to you.
- Attach this card to the back of the mailpiece, or on the front if space permits.

1. Article Addressed to:

**C/O Eller Media  
Adeline Investments  
2533 North Carson Street, # A324  
Carson City, NV 89706**

2. Article Number  
(Transfer from service label)

7002 2030 0006 9574 1426

**COMPLETE THIS SECTION ON DELIVERY**

A. Signature

X

- Agent
- Addressee

B. Received by (Printed Name)

C. Date of Delivery

D. Is delivery address different from Item 1?  Yes  
If YES, enter delivery address below:  No

3. Service Type

- Certified Mail
- Registered
- Insured Mail
- Express Mail
- Return Receipt for Merchandise
- C.O.D.

4. Restricted Delivery? (Extra Fee)

Yes

PS Form 3811, February 2004

Domestic Return Receipt

102595-02-M-1540

**CERTIFIED MAIL™**



7002 2030 0006 9574 1426



ALAMEDA COUNTY  
**HEALTH CARE SERVICES AGENCY**  
Department Of Environmental Health  
Environmental Protection Division  
1131 Harbor Bay Parkway  
Alameda, CA-94502-6577

**RECEIVED**  
JUN 18 2008

ENVIRONMENTAL HEALTH SERVICES

**DO NOT WRITE IN THESE SPACES**

**C/O Eller Media  
Adeline Investments  
2533 North Carson Street, # A324  
Carson City, NV 89706**

