


AZ-16

Shi Coh Horse Ranch  
Cactus Valley


5-10-88

L.S.



51512010 - Larry states that this case started as a complaint by someone who stated that property owner was burying 55-gallon drums. It was later learned that the Empty drums were not buried, but were layed on the site for the horses to jump over. Some soil staining was present, but Larry said it was residual diesel fuel that was in the drum.

Shi Coh Horse Ranch  
Castro Valley  
5-10-88 L.S.



Shi Coh horse Ranch  
Castro Valley  
5-10-88  
L.S.

