

R04

Chan, Barney, Env. Health

From: Chan, Barney, Env. Health
Sent: Tuesday, May 04, 2004 9:20 AM
To: Mike Bowery (E-mail)
Subject: work plan for Thrifty #49, 3400 San Pablo Ave.,Oakland

Mike: I've made a mistake. In concurring with your previous e mail to install wells instead of the borings prior to wells, **I thought that the wells would be installed in addition to the borings, not instead of the borings.** Without additional borings to the west of the site it would be tough to close the western edge of the plume and distinguish a release from the neighboring Shell site. Elevated TPHg, BTEX and MTBE was detected in the grab groundwater sample from B-2 and no water sample was collected from B-1. Therefore, I believe several borings to the west of the site in addition to the 3 wells proposed is warranted. Please give me your thoughts.

Thank you,

Barney M. Chan
Hazardous Materials Specialist
Alameda County Environmental Health
510-567-6765