

F A C S I M I L E

Earth Systems Consultants
Northern California
47853 Warm Springs Blvd.
Fremont, CA 94539-7400
(510) 353-0320
Fax (510) 353-0344

TO: ACHCSA
ATTENTION: Larry Seto
SUBJECT: Addendum letter
FROM: Gary Dischke
FAX NUMBER: 337-9335
DATE: 6/10/99
TOTAL PAGES: (INCLUDING COVER) 2.

NOTES: Addendum to RWQCB meeting letter.
We plan on proceeding w/ well install
temp @ T-1 and replacement
for MW-6 this month & a
round of GRC's

IF YOU HAVE A PROBLEM REGARDING THIS TRANSMISSION, PLEASE CALL (510) 353-0320

a full-service, multidisciplinary firm offering services in the fields of
geotechnical engineering, geology, environmental assessment and remediation,
drilling, inspection and testing.



Earth Systems Consultants
Northern California



Earth Systems Consultants
Northern California

47853 Warm Springs Blvd.
Fremont, CA 94539-7400
(510) 353-0320
FAX (510) 353-0344

File No. NFE-4392-01
June 8, 1999

Doc. No. 9906-031

Mr. Larry Seto
Ms. Madhulla Logan
Alameda County
Health Care Services Agency
Environmental Protection Division
1131 Harbor Bay Parkway, Room 250
Alameda, California 94502-6577

Subject: 415 Mariner Square Drive
Alameda, California
**ADDENDUM TO SUMMARY OF APRIL 14, 1999, MEETING WITH
REGIONAL WATER QUALITY CONTROL BOARD**

Dear Mr. Seto and Ms. Logan:

As requested, Earth Systems Consultants Northern California (ESCNC) is providing this addendum to the summary of the April 14th meeting at the Regional Water Quality Control Board's (RWQCB) office in Oakland, California.

EASTERN RESIDENTIAL PARCEL

- 1) The RWQCB recommends monitoring wells, MW-1, MW-7 and MW-8, within the parcel on a one-time basis.
- 2) No active remediation is required for the parcel.

Please call me at (510) 353-0320, if you have any questions.

Very truly yours,

EARTH SYSTEMS CONSULTANTS
Northern California

Gary M. Pischke
Senior Geologist
Certified Engineering Geologist 1501

GMP:dh Ltr#200

Distribution: 2 to Addressee
1 to Mr. John Beery