

Contact Log (2394 Marinier Sq.)

- 10/28/96 Gary Pishke, Hydro Enviro, (510) 521-2684
Mr. Pishke will submit a proposal to Mr. Barnhill by next week. Discussed site. Will notify me if Hydro Environmental is retained by Mr. Barnhill.
- 11/8/96 Spoke to Gary Pishke. He inquired as to whether it would be okay to place temporary sampling points in lieu of permanent wells. I stated that if they did find contaminant concentrations of concern from temporary locations, that they would have to install permanent wells.
- 11/25/96 Spoke to Gary Pishke re workplan. Need info on depths of Posay tube and depth of storm drain trench prior to approving workplan. Also, need to consider possibility of doing elevation contours for temporary sample points.
- 1/10/97 Gary Pishke, 510-521-2684, called to update County on implementation of workplan. Zone 7 has approved the proposed well installations, however, they are still waiting for Cal Trans to grant them access on to its right-of-way for Posay tube.
- 1/21/97 Gary Pishke called to say that he has moved the proposed southeastern geoprobe location ~4 feet west to get outside of the Cal Trans right-of-way instead of holding up the project by having to wait for Cal Trans to grant access. He said he would fax me copy of new location map & would schedule work for late this week or early next wk.
- 1/22/97 Gary Pishke called to say that geoprobe field work would commence on ^{the} Jan 30th.
- 3/27/97 Called Gary Pishke & inquired about the screen intervals of the geoprosbes. The screened intervals were from about 3-3½' to 8-8½' bgs w/ the water table being at ~4' bgs.

Contact Log

- 11/22/95 George Wilson, consultant 415 822-9555
Tank Removal Report and work plan are
on its way. There may be some problems w/
the Webster Tube underlying the site at
~15' bgs.
- 12/13/95 George Wilson, consultant - called to say delay
in submitting w.p. due to the fact that a car
drove through their office building and destroyed
info in computer database. They tried put w/
barrier, backfilled w/ pea gravel, & covered to
prevent rain from getting in. Mr. Wilson has
discovered that tank pit is right above the Webster
Tube, so there will be some problems w/ investigations.
He will submit Col Trans map showing location
of Webster Tube & tentative w.p. for my review
before setting up a meeting to discuss options.
- 10/24/96 Left message for A.V. Barnhill, (510)521-8387.
He has never responded w/ County in response
to County's letters & requests. Let him know that
the next step will be to issue NOV or call him
in for DA hearing. Requested that he return
my call.
- 10/24/96 Mr. Barnhill returned my call. He stated that
he spoke to Low and they had allegedly submitted
a workplan & letter. I told Mr. Barnhill that we have
not received any correspondence since 12/95 from L.W.
Mr. Barnhill wants to do work & will get back to me w/in