

12/1/93

Learner Co.  
Tel con w/ Bob DeVorey of Weiss Assoc. re 768 46th Ave  
requested an update of recent project status.

Said did a series of borings which ~~at~~ indicated possible  
~~outside~~ offsite contam. Plans to install 4 mws in the  
hottest areas where contam was found. We discussed adjacent  
contam. at PG&E 1 Volvo GMC/Glidden st.

I requested that he notify me in writing when next mw  
inst. phase is scheduled. He thought in Dec or Jan  
the next phase would commence.

We also discussed conducting a site search ~~is~~ to get copies  
of reports on the adjacent files. I requested that he perhaps  
hire a copy service. ~~and~~ due to the volumes of reports requested to  
be copied. He said he'd submit a written request.

11:45 5/17/93

Site visit - met w/ Bob DeVernoy of Weiss Assoc

Had completed 2 of 8 borings - visible contour was noted at 8 feet in B-2.

we discussed the installation of mws - Bob thought that it might be necessary to install more than the originally proposed 3. He mentioned the Chevron <sup>asphalt</sup> plant (containing numerous above ground tanks) and also ~~the~~ a paint factory both in the potential/probable up gradient direction. Bob was interested in placing a well or two up gradient to see if contamination was coming onto the learner site from an up gradient source.

I left it with Bob that if he wanted to check with me re: locations of the wells I would be glad to discuss it with him otherwise he would place them as he saw fit. I mentioned to him that if he did install wells without Divisional concurrence the placement would be subject to possible dispute.

off site 12:45

11/22/93

(209) 948-3498

called Jack Hecht of Learner re: report of findings from 5/17 work left message for him to call me.

11/23/93 spoke w/ Jack Hecht & requested a report of findings for Mary work performed at the site. He said he still hadn't received results from Weiss. He said he would contact Bob DeVernoy & request that he either produce a report or contact me regarding this matter.

stid 3705

5/10/93 Lerner Co. 768 46th Avenue, Oakland 94601

tel con w/ Bob DeVaney / weiss Assoc re: workplan

- will perform borings to delimit nature & extent of contam.
- will install/site wells based upon next phase of work
- will seek (in groundwater samples) all pollutants previously found in soil

- I disputed the thought in May 5<sup>th</sup> <sup>weiss</sup> correspondence that surface pollutant would not be considered a point source. However, we both agreed that we didn't yet have enough info to definitively make that claim.

- Scheduled work (next phase) & set up an appt to meet with Scott Nelson & Bob DeVaney at the Lerner site on 5/17 at 11:00 AM.

3/15/93

Review Feb 16, 1993 Investigation workplan

re: 768 46th Avenue, Oakland 94601

Ferrett Sorenson Weiss Assoc.

547-5420

on { plan states eight additional borings + soil samples Figs 415 depict  
8 ~~to~~ borings, which is it ~~to~~ ~~to~~? 4 around former building area  
4 drive area

workplan states placement of 3 mws will be based upon  
grab groundwater samples, why not base mw inst on soil data  
particularly metals in 3 locations in which wet test indicated  
high levels of lead & zinc

- Quarterly sampling of mws
- initial analysis in groundwater at each well location for all  
constituents previously detected
- size of wells

HLS plan

check on ionization potential of TPH hydraulic oil

(Have BTax constituents been analyzed for  
need to look for these

2 shallow soil samples from public areas near the site are  
proposed - location unspecified

review of historical pictures maps to id areas of activity/pollution

- wets formerly or presently onsite

need to know location of Composite - bench test soil sample id # 35135

- what other metals or pollutants other than the 5 metals are likely to be  
encountered

- Stiles in addition to lead & Zn were exceeded need to run wet test

for Cd, Cr Ni B-3, B-6, B-10, B-11, B-12

Cr B-8, B-9, Pb B-4, B-3, B-5, B-6

3/15/93

tel con w/ Everett Sorenson - Weirs Assoc

asked him about composite sample Benches soil where both  
STC & TFC <sup>data</sup> ~~values~~ were available - I needed to know the location  
of the collection of these data.

Also discussed the criteria for deciding where to place the  
monitoring wells mentioned in the workplan which was based upon  
results of the grab groundwater samples. He said that there  
was some discussion between the client & Weirs regarding whether  
to actually install the wells in the next phase of work or wait  
until more definition of the lateral & vertical extent of the  
contaminant occurs. He said at this time the plan is to  
collect more data and then install the wells during the next  
phase of work. I told him in my letter I would discuss  
this understanding and would ask some questions which I thought  
were appropriate re: wells such as size, location, initial  
sampling, quarterly events etc. . . .

10/9/92

Everett Sorenson of Weirs Associates contacted me and informed me that the other Lerner site at 3675 Alameda Ave is a Regional Board lead site and is being handled by Rich Hiatt. He also informed me that Don Bradshaw of Leine Fricke is the main contact for that site remediation.

3/4/92

Stuffs

May not be LOP eligible

1) UGT (diesel) removed - n.d. for soil  
contamination

2) all other contaminants found at site ~~are~~  
are from subsurface spill

delete for LOP

4/21/92

Paul,

Here's the worksheet (P/R)

Up Lerner Co

Mass - lead

new system of

Susan

NEED ↓ scale will be removed

↓ SITE HISTORY

TPN & P2B

PROPOSED  
min 8 soil & 4 H2O pits + 7 SURFACE  
NOTIFICATION TO SAMPLING  
COMPOSITE SAMPLE OF PILES

STAMP + PILES  
SURFACE SAMPLES

called complete 7/2/58

PATTON

**WHILE YOU WER AWAY**

FOR <u>AL</u>	DATE _____	TIME _____	A.M. P.M.
M <u>Royer</u>	OF <u>Werner Co</u>	<input type="checkbox"/>	TELEPHONED
PHONE <u>213/612-7820</u>	<small>AREA CODE NUMBER EXTENSION</small>	<input type="checkbox"/>	RETURNED YOUR CALL
MESSAGE <u>Sample taken on</u>	<u>Jan. 26th</u>	<input checked="" type="checkbox"/>	PLEASE CALL
<u>768 - 46th Ave</u>	<u>Oakland</u>	<input type="checkbox"/>	WILL CALL AGAIN
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	CAME TO SEE YOU
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	WANTS TO SEE YOU
SIGNED _____	TOPS  FORM 4002		

**WHILE YOU WER AWAY**

FOR <u>AL</u>	DATE <u>2/9</u>	TIME <u>10:40</u>	A.M. P.M.
M <u>ROGER CARRICK</u>	OF _____	<input type="checkbox"/>	TELEPHONED
PHONE <u>213/612-7820</u>	<small>AREA CODE NUMBER EXTENSION</small>	<input type="checkbox"/>	RETURNED YOUR CALL
MESSAGE <u>Re: inspection done at</u>	<u>768 - 46th Ave</u>	<input checked="" type="checkbox"/>	PLEASE CALL
<u>Oakland</u>	<input type="checkbox"/>	<input type="checkbox"/>	WILL CALL AGAIN
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	CAME TO SEE YOU
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	WANTS TO SEE YOU
SIGNED _____	TOPS  FORM 4002		

4/5/88

SPOKE TO CANNICK.

INTENDED HIM OF NEED FOR REFORM  
ACTION PLAN.

INTEND HIM THAT LETTER WILL BE SENT  
IF LEARNER COMP DOESN'T REPLY NOW.

CANNICK SAID THEY WILL MEET & RESPOND  
BY 4/15/88.

ROBER. CANNICK

213-689-0200

INTERNATIONAL DISPOSAL

MANIFESTING OF WASTE

cc DA




CLIFF DAVENPORT

1/20/88

CHECKED SITE. FOUND  
[ 707-648-4805 ]

RUBEN RA.

SPAM BAILEY



2 SAMPLES TAKEN.

H<sub>2</sub>O 1-25-88-1 } SEE CHAIN  
soil 1-25-88-2 } OF CUSTODY

PICTURES TAKEN.

HEAVY CONTAMINATION APPARENT.