ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY



DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

July 24, 2009

MARILYN PONTE BAY ROCK RESIDENTIAL LLC 1300 CLAY STREET, SUITE 620 OAKLAND CA 946121427 JOHN TIBBETTS
OAK'S CLUB ROOM
4097 SAN PABLO AVENUE
EMERYVILLE CA 94608

Subject:

Fuel Leak Case No. RO0002733 and Geotracker Global ID T06019705080, OAK WALK REDEVELOPMENT SITE, 4090 SAN PABLO AVE, EMERYVILLE CA 94608- Groundwater Monitoring Requirements

The purpose of this correspondence is to inform you of changes to groundwater monitoring requirements for all fuel leak cases in California. The California State Water Resources Control Board (State Water Board) has approved Resolution No. 2009-0042 (Actions to Improve Administration of the UST Cleanup Fund and UST Cleanup Program). Resolution No. 2009-0042 states that, "Regional Water Board and LOP agencies shall reduce quarterly groundwater monitoring requirements to semiannual or less frequent monitoring at all sites unless site-specific needs warrant otherwise and shall notify all responsible parties of the new requirements no later than August 1, 2009. If more than semiannual monitoring is required for a case, the responsible party and State Water board shall be notified of the rationale and the notice shall be posted on Geotracker."

Upon review of your site, we find the following site-specific conditions that warrant continuation of quarterly groundwater monitoring:

Quarterly groundwater monitoring is required due to recent monitoring well installation.

If you believe that continued quarterly groundwater monitoring for your site is not warranted, you may submit a proposal for a revised sampling and analysis schedule along with your technical rationale supporting the proposal.

If you have any questions, please call me at (510) 383-1767 or send me an electronic mail message at steven.plunkett@acgov.org.

Sincerely,

Steven Plunkett

Hazardous Materials Specialist

Enclosure: ACEH Electronic Report Upload (ftp) Instructions

cc: Donna Drogos, ACEH (Sent via E-mail to: donna.drogos@acgov.org)
Steven Plunkett, ACEH (Sent via E-mail to: steven.plunkett@acgov.org)
Geotracker.File

RESPONSIBLE PARTY OF RECORD AS OF 07/22/2009

RO0002733, OAK WALK REDEVELOPMENT SITE, 4090 SAN PABLO AVE , EMERYVILLE, CA, 94608

Alameda County Environmental Health (ACEH) has the following information on record regarding the Responsible Party(ies) for the above referenced site. Please update the following information for our records. Should you have contact information regarding additional Responsible Parties, please correct the information accordingly. Also, please check the "e-mail preferred" box to receive all future correspondences and notifications by e-mail.

☐ E-mail Preferred ACEH is requesting your e-mail address so that we can corresp privacy. Your e-mail address will remain confidential and will	☐ Hardcopy Preferred pond with you quickly and efficiently regarding your case. Please note that ACEH respects not be provided to any third party.	yo
Current Information	Corrections or Additions	
MARILYN PONTE	Name:	
BAY ROCK RESIDENTIAL LLC	Company:	
1300 CLAY STREET, SUITE 620	Address:	
OAKLAND CA 946121427	City: State: Zip:	
	E-mail:	
	Home Phone: ()	
	Office Phone: ()	
	Cell Phone: ()	
JOHN TIBBETTS	Name:	
OAK'S CLUB ROOM	Company:	
4097 SAN PABLO AVENUE	Address:	
EMERYVILLE CA 94608	City: State: Zip:	
	E-mail:	
	Home Phone: ()	
	Office Phone: ()	_

Cell Phone: (____)