

11-8-91

Left mess. for Rich Hiatt of RWQCB - is collecting a water sample from a piezometer to be used to determine downgradient water quality acceptable, or does a monitoring well need to be installed. Hiatt said a monitoring well is needed. (Needs to be grouted properly, screened, etc to min. contamination)

RO1

RO1  
PH LOG BY DH

1/4/07 1042 ANNIKO MOLNAR LEFT MES 415-254-7855: ?REVIEWED 7/06  
REPORT

1/4/07 1450 PHONED MOLNAR: NOT SURE WHEN WILL REVIEW 7/06 REPORT

8/7/90

Aniko Molnar called and said she sent a letter to me on 6-5-90. I told her I did not have it. She said in the letter she would have a work plan by first part of Aug. She called to let me know she is working on getting a consultant within a week, and the work plan should be submitted by the end of the month. She will submit the 6-5-90 letter to me again today, with ~~the~~ her new time table for submitting of the work plan.

8/24/90

Aniko Molnar said they have a new consultant who is presently putting together a work plan. This work plan should be submitted to this office after the Labor Day holiday.

9/24/90

Informed Greg Keller of Streamborn that I would approve his geologic soil investigation plan dated 8-31-90 if two additional soil borings are installed in the North part of the property near B-9. He said the difference between the monitoring well and piezometer he is proposing is really the name only. They do not want to monitor the M.W., so they are calling two piezometer.

- 5/25 Lee Hennings said she received the letter of 5-23-90, 2<sup>nd</sup> notice, but not the 1<sup>st</sup> dated 3-8-90. She said Mr. Molnar will not be in until 6/12/90, and she will tell him to contact me immediately. Send out another copy of the 3-8-90 letter.
- 5/30 Lee Hennings said Mr. Molnar's daughter who is an environmental consultant will write a letter to me within two weeks.
- 6/4 Aniko Molnar, daughter of owner ~~she~~ said she will write a letter identifying her father will be back in town next week, and when they expect to get a new consultant and a time frame when I can expect a work plan.
- 7/16 Raymond Yu, present owner of the property said there is money still in escrow for the cleanup of this site. He wanted to know if he should release it. I told him the remediation is not complete. I will send him a copy of my March 8<sup>th</sup> letter. His mailing address is 2819 MacArthur Blvd, Oak. 94602