


CLAIMANT: American Brass and Iron Foundry SITE:

7825 San Leandro

Street

CLAIM NO:	004132	Oakland, CA 94621	
Date	Date Comments		
4-10-91	CNTY ONSITE FOR INSPECTION: 1) REQUE: HMMP, 2) INFORMED OF MONOTORING NEW YORK THE MONTH OF THE PARTY SIX MONTH.	PERMINDING SECTION OF THE PERMINDING SECTION	
7-30-91	CNTY LTR TO CLMNT - NOV: CNTY IS AW USTS AND THE ABANDONMENT OF ANOTHER CLMNT TO PROVIDE ALL DETAILS OF THE REQUESTED A PLAN OF CORRECTION FOR	UST IN 1987. REQUESTED ABANDONMENT OF THE ONE UST.	
7-30-91	CNTY RCVD A HEALTH AND SAFETY PLAN		
8-7-91	CNTY RCVD UST CLOSURE PLAN		
8-8-91	CNTY ONSITE FOR REMOVAL OF 8K GAL TANK		
8-16-91	CLMNT REQUESTED A TWO-WEEK EXTENSION TO REPLY TO NOV		
8-26-91	CNTY ONSITE FOR REMOVAL OF 1 550 GAL UST		
9-26-91	CLMNT RESPONDED TO JULY 30, 1991 NOV		
10-31-91	8K GAL UST REMOVED		
11-9-91	CNTY RCVD A PROPOSAL FROM CLMNT TO	RECYCLE A UST REMOVED ON	
	10-18-91 THROUGH NORMAL OPERATION O	F THE FOUNDRY	
1-6-92	CLMNET LTR TO CNTY: FOLLOWUP TO PHONE CLMNT INTENDS TO REMOVE THE EXISTING FOR DIESEL FUEL STORAGE. A NEW OIL INCLUDED LABORATORY ANALYSIS FOR FOMIXTURES GENERATED FROM THIS SITE.	NE COVERSATION W/BARNY CHAN. G UST PRESENTLY BEING USED ROOM IS BEING CONSTRUCTED. UNDRY WASTE SAND, SLAG AND	
	RESULTS OF SAMPLING AT SITE BORINGS	FROM 1987 TANK REMOVAL.	
2-13-92	CNTY RCVD A COPY OF A REMOVAL OF A	550 GAL UST REPORT	
4-14-92	CNTY RCVD A COPY OF A REPORT ON REM	OVAL OF 8K GAL UST	
5-22-92	CLMNT NOTIFIED CNTY OF SCHEDULE TO 3 6-1-92	REMOVE DIESEL UST WEEK OF	
5-28-92	SITE TRANSFERRED TO LOP		
5-28-92	CNTY NAMED AMERICAN BRASS & IRON FO	UNDRY AS RP	
6-2-92	CNTY ONSITE FOR 12K GAL TANK REMOVAL		
9-10-92	CNTY RCVD A REPORT ON REMOVAL OF 12	K GAL UST	
9-29-92	CNTY RCVD A COPY OF A REPORT ON THE CONCLUDES A SERIES OF TANK REMOVALS		
10-2-92	CNTY REQUESTED A WORKPLAN FOR THE I SOIL/GROUNDWATER CONTAMINATION FOR	THE ENTIRE SITE	
10-28-92	CLMNT RESPONDED TO 10-2-92 REQUEST QUOTES FOR WORK		
11-18-92	CNTY RCVD WORKPLAN FOR A SUBSURFACE	INVESTIGATION	
11-25 <b>-</b> 92	CNTY RESPONDED TO WORKPLAN. SOME C BY CLMNT; 1) REQUESTED AN ADDT'L PAC CNTY OF THE TYPE OF GW TREATMENT TO ATTEMPT BE MADE TO DETERMINE EXTENT SIDE OF PIT? PROVIDE WRITTEN RESPO	TION OF WORKPLAN 2) INFORM BE USED IN WELL. WILL AN OF CONTAMINATION TO THE WEST NSE TO ISSUES BY 12/25/92	
12-18-92 2-10 <b>-</b> 93	CLMNT RESPONDED TO CNTY'S 11-25-92 CNTY LTR TO CLMNT - GAVE LIST OF PA	RAMETERS TO BE ANALYZED IN	
6-17-93	MWS. CNTY RCVD A SHALLOW SOIL AND GW INV	ESTIGATION REPORT	





## THE RECEIPED

Consultant will re-draft a workplan to install an additional well based on results of several monitoring events. County Considers claimant in compliance. 3-23-95

PROTECTION AGENCY

....

PETE WILSON, Governor

STATE WATER RESOURCES CONTRO

STATE WATER RESOURCES CONTROL BOARD DIVISION OF CLEAN WATER PROGRAMS 2014 T STREET, SUITE 130

P.O. BOX 944212 SACRAMENTO, CA 94244-2120

FAX (916) 227-4349 FAX (916) 227-4530 FAX (916) 227-4595



P01

## TRANSMITTAL OF FAX MATERIAL

DATE:	3-23-95
TO:	Barney Chan  FAX # 5(510) 337-9335
FROM:	DIVISION OF CLEAN WATER PROGRAMS FAX # (916): 139 CLEANUP FUND FAX (916) 227-4530 Planning Facilities FAX (916) 227-4530
	Cheryl Gordon
	(If you did not receive all your FAX, please call (916) 227-4539
NO. OF PA	AGES $\frac{4}{2}$ (including this sheet)
// For	r your information
// Per	r your request
/ <u>_</u> / For	r your review and comments
REMARKS:	Barney, please
pign	sheet only back to
1/100	
6/23/93	

W. " /-\"			
SENDER: Complete items 1 and 2 when additional services are desired, and complete items 3 and 4.  Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested.  1. Show to whom delivered, date, and addressee's address.  2. Restricted Delivery (Extra charge)			
3. Article Addressed to: (BC) #523	4. Article Number P 367 604 272		
American Brass and Iron Foundry Attn: Mr. Allan Boscacci 7825 San Leandro St. Oakland, CA 94621	Type of Service:  Registered Insured COD COD Return Receipt for Merchandise  Always obtain signature of addressee		
5. Signature — Address	or agent and <u>DATE DELIVERED</u> .  8. Addressee's Address (ONLY if requested and fee paid)		
X 6. Signature — August X (UV)4 (Me)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
7. Pate of Delivery  PS Form 3811, Mar. 1988 * U.S.G.P.O. 1988-212	-865 DOMESTIC RETURN RECEIPT		

## HEALTH CARE SERVICES

DAVID J. KEARS, Agency Director



State Water Resources Control Board Division SMEHCLeantaWatery Programs

UST Local Oversight Program
DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

certified mailer #P 367 604 272

AGENCY

May 28, 1992 STID# 523

## Notice of Requirement to Reimburse

American Brass and Iron Foundry ATTN: Mr. Allan Boscacci 7825 San Leandro St. Oakland, CA 94621

American Brass and Iron 7825 San Leandro St. Oakland, CA 94621

SITE

Responsible Party Contact Person Property Owner

Date First Reported: 10/91 Substance:gasoline, TCA solvent Petroleum (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from The direct and indirect costs of underground storage tanks. overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Barney Chan, Hazardous Material Specialist, at (510) 271-4530.

Sincerely,

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use :

add: X

Reason: New case