DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, #250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #2143559310 09/12/96 STID# 251

Notice of Requirement to Reimburse

Henry Suico Automobile Service Company 820 Isabella St. Oakland C A 94607

Auto Service Co 820 Isabella Oakland , CA 94607 Responsible Party (RP) Property Owner

SITE

Date First Reported 09/10/96

Substance: Waste Oil Petroleum: (X) Yes

Source: F

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s).or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Section 25297.1 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board (SWRCB) not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above referenced underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the SWRCB.

A determination of a secondary RP status may be made if it is shown that one or more of the RP(s) is performing corrective action and it is clear that the party seeking secondary status did not in any way initiate or contribute to the actual discharge. If the primary RP fails to perform corrective action, then the secondary RP will be considered a primary RP. To request designation as a secondary RP, contact this office.

Report: ReImbB 9/95

Reimburse Letter 09/12/96 StID# 251 Page 2

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the SWRCB. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, Please fax your request to Roni Riley at the SWRCB at (916) 227-4349 telephone the SWRCB at (916) 227-4408. Please contact Eberle, Jennifer, Hazardous Materials Specialist at this office if you have any further questions concerning this matter.

Gordon Coleman, Acting Chief Contract Project Director

c: Lori Casias, SWRCB

Please Circle One Add Delete Change

Reason: New

P 143 589 312 JE

US Postal Service
Receipt for Certified Mail
No Insurance Coverage Provided.
Do not use for International Mail (See reverse)

		Mehry Suico Auto Service Co.				
		820 Isabella St. Post Office, State, & ZiP Code Oakland, CA 94607				
		Postage	\$			
		Certified Fee				
		Special Delivery Fee				
	in	Restricted Delivery Fee				
	1998	Return Receipt Showing to Whom & Date Delivered				
	Apri	Return Receipt Showing to Whorn, Date, & Addressee's Address				
	Form 3800	TOTAL Postage & Fees	\$			
		Postmark or Date				
	PS F					
egrapje i nami i jiri					প্ৰাৰ্থনায়: গাড়াজ ক্লাছৰ ডু	
Complete Items 1 and/or 2 for additional services. Complete Items 3, and 4s & b. Print your name and address on the reverse of this form so that					t also wish to rendire the	
				we can	fee):	
Attach	Treturn this oged to you. • Attach this form to the front of the mailpiece, or on the back if the does not permit.				following services (for an extra fee): 1. **ExAddressee's Address 2. **Restricted Delivery Consult postmaster for fee. cle Number 3589312 //ice Type tered	
Write "Return Receipt Requested" on the mailpiece below the article numb The Return Receipt will show to whom the article was delivered and the da				le number. d the date	2. Restricted Delivery	
5 delivered.			JE	4a. Artic	cle Number	
9 3. AIL	3. Article Addressed to:				P143589312	
Ę Ą	Henry Suico Automobile Service Company				vice Type	i
8 820 Isabella ST.				Red : COD	•	
8 0	0 0akland, CA 94607				Return Receipt for	
delivered. 3. Article Addressed to: Henry Suico Automobile Service Company 820 Isabella ST. Oakland, CA 94607 5. Signature (Addressee) 6. Signature (Agent)				7. Date	of Delivery	į
					9-18-96	
				8. Addr	essee's Address (Only if requested	1
				grid i	, , , , , , , , , , , , , , , , , , ,	:
6. Sign	éture (Agent)	N				
- 5 <u></u>				- 54	AND DESCRIPTION OF THE PARTY OF	