DAVID J. KEARS, Agency Director



### State Water Resources Control Board Division of Clean Water Programs UST Local Oversight Program

RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P 367 604 010

AGENCY

03/20/92 STID# 1940 DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200 Oakland, CA 94621 (510) 271-4320

#### Notice of Requirement to Reimburse

Chevron Ss #95542 7007 San Ramon Rd. Dublin C Ad 94568 Responsible Party #1
Property Owner

Clint Rogers Chevron U S A Inc. Po Box 5004 San Ramon C A 94583

Responsible Party #2 Contact Person Contact Company

Rich's Chevron Service 7007 San Ramon Rd. Dublin, CA 94568

SITE

Date First Reported 02/13/90

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

# P 367 604 010 RECEIPT FOR CERTIFIED MAIL NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL (See Reverse)

LO.	100011070707	
234-55	Sent 10 Clint Rogers	
<u>\$</u> ]	Street and No. 5004	
:: U.S.G.RO. 1989-234-555	P.O., State and ZIP Code San Ramon CA	94583
∂	Postage	S
	Certified Fee	
PS Form 3800, June 1985	Special Delivery Fee	
	Restricted Delivery Fee	
	Return Receipt showing to whom and Date Delivered	
	Return Receipt showing to whom, Date, and Address of Delivery	
	TOTAL Postage and Fees	\$
3800	Postmark or Date	
orm		i
S		. 1

Put years attacked in the "RETURN TO" Space on the said from being returned to you. The return receipt fee to and the date of delivery. For additional fees the folio for fees and check box(es) for additional service(s) re	reverse side. Failure to do this will prevent this will provide you the name of the person delivered owing services are evallable. Consult postmaster
3. Article Addressed to: Clint Rogers Chevron USA Inc. PO Box 5004 San Ramon CA 94583	4. Article Number (JE) #1940  Type of Service:  Registered Insured Certified COD Express Mail Return Receipt for Merchandise  Always obtain signature of addressee or agent and DATE DELIVERED.
5. Signature — Address X 6. Signature — Agent X 7. Date of Delivety APR 2 1992 8 Power 3811, Mar. 1988 * U.S.Q.P.O. 1988-	8. Addressee's Address (ONLY if requested and fee paid)  212-865 DSMETTE RETURN RECEPT

## State Water Resources Control Board Division of Clean Water Programs UST Local Oversight Program

RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P 367 604 009

03/20/92 STID# 1940 DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200 Oakland, CA 94621 (510) 271-4320

#### Notice of Requirement to Reimburse

Chevron Ss #95542 7007 San Ramon Rd. Dublin C Ad 94568

Responsible Party #1 Property Owner

Clint Rogers Chevron U S A Inc. Po Box 5004 San Ramon C A 94583

Responsible Party #2 Contact Person Contact Company

Rich's Chevron Service 7007 San Ramon Rd. Dublin, CA 94568

SITE

Date First Reported 02/13/90

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

# P 367 604 009

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED

NOT FOR INFERNATIONAL MAIL

(See Reverse)

	(See Heverse)		
PS Form 3800, June 1985 × U.S.G.P.O. 1989-234-555	Sent to Chevron Ss #955	542	
	Street and No. 7007 San Ramon	Rd.	
	P.O., State and ZIP Code Dublin CA 94568		
	Postage	S	
	Certified Fee		
	Special Delivery Fee		
	Restricted Delivery Fee		
	Return Receipt showing to whom and Date Delivered		
	Return Receipt showing to whom, Date, and Address of Delivery		
	TOTAL Postage and Fees	\$	
	Postmark or Date	•	
		•	
S			

SENDER: Complete interest and submit a service 3 and 4.  Put your address in the "REPART TO COMPLETE A Service on the Text and the date of delivery, for additional fees the following and check box(es) for additional service(s) request. The service of the servic	arse side. Fallure to do this will prevent the provide you the name of the person delivere g services are available. Consult postmasticated.
Chevron Ss #95542 7007 San Ramon Rd. Dublin CA 94568	4. Article Number  (JE) #1940  Type of Service:  Registered Insured Cortified COD Express Mail Receipt for Merchandise
nature Agent X 7. Date of Delivery	Always obtain signature of addressee or agent and <u>DATE DELIVERED</u> .  8. Addressee's Address (ONLY if requested and fee paid)