

98 MAY 28 AM 10:10

Ultramar

Ultramar, Inc.
P.O. Box 466
525 W. Third Street
Hanford, CA 93232-0466
(209) 582-0241

Telecopy: 209-585-5685 Credit
209-583-3330 Administrative
209-583-3302 Information Services
209-583-3358 Accounting

May 22, 1998

Ms. Eva Chu
Department of Environmental Health
Alameda County Health Care Services
1131 Harbor Bay Parkway, Room 250
Alameda, CA 94502-6577

**SUBJECT: BEACON STATION NO. 604, 1619 FIRST STREET, LIVERMORE,
CALIFORNIA**


Dear Ms. Chu:

Enclosed is a copy of the First Quarter 1998 Ground Water Monitoring Report for the above-referenced Ultramar facility. Also included is a copy of the Quarterly Status Report.

Please call if you have any questions regarding this site.

Sincerely,

ULTRAMAR INC.



Terrence A. Fox
Senior Project Manager
Marketing Environmental Department

cc: Mr. Cecil Fox, San Francisco Bay Region, RWQCB
Walter and Dorothy Anderson, 1091 Buckingham Drive, Los Altos,
CA 94024
Mr. Leon Crane, BDM, 7840 Madison Avenue, #185, Fair Oaks, CA
95628



A Member of the Ultramar Group of Companies

BEACON
#1 Quality and Service

Ultramar

Ultramar, Inc.
P.O. Box 466
525 W. Third Street
Hanford, CA 93232-0466
(209) 582-0241

Telecopy: 209-585-5685 Credit
209-583-3330 Administrative
209-583-3302 Information Services
209-583-3358 Accounting

ENVIRONMENTAL PROJECT QUARTERLY STATUS REPORT

DATE REPORT SUBMITTED: May 22, 1998
QUARTER ENDING: March 31, 1998

SERVICE STATION NO.: 604
ADDRESS: 1619 First Street, Livermore, CA
COUNTY: Alameda
ULTRAMAR CONTACT: Terrence A. Fox

TEL. NO: 209-583-5545

BACKGROUND:

In November 1992, three underground storage tanks were removed. Hydrocarbons were detected and the excavation was extended to a depth of 27 feet in the southwest corner. Hydrocarbons were detected in the sample collected from the base of the overexcavation.

In May and June 1993, three monitoring wells (MW-1 through MW-3), three vapor wells (VW-1 through VW-3), and one boring were drilled. The soil plume has been defined.

The site has been placed on a quarterly monitoring program.

In March 29 and 30, 1994, four additional offsite wells (MW-4 through MW-7) were installed. The ground-water plume is not defined downgradient.

In June 1994, performed assessment on the Livermore Arcade Shopping Center Property by drilling borings and collecting ground-water samples using a Hydropunch tool.

In June 1994, performed vapor extraction and ground-water extraction tests.

In September and October 1995, installed of vapor extraction and air sparging wells.

In January, 1997, discontinued operation of the remediation system.

In August 1997, submitted RBCA.



A Member of the Ultramar Group of Companies

BEACON
#1 Quality and Service

SUMMARY OF THIS QUARTER'S ACTIVITIES:

Performed quarterly monitoring on March 19, 1998.

RESULT OF QUARTERLY MONITORING:

Monitoring data indicates that the benzene concentrations were not detected in MW-1 and MW-5. The benzene concentrations were detected MW-2, MW-6, and MW-7. MW-3 and MW-4 were not sampled this quarter.

PROPOSED ACTIVITY OR WORK FOR NEXT QUARTER:

<u>ACTIVITY</u>	<u>ESTIMATED COMPLETION DATE</u>
Continue quarterly monitoring program.	