# ALAMEDA COUNTY **HEALTH CARE SERVICES**



**ENVIRONMENTAL HEALTH DEPARTMENT** OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

## AGENCY

Certified Mail #: 7011 3500 0003 1848 1035

February 05, 2013

#### NOTICE OF RESPONSIBILITY

Site Name & Address:

**UNOCAL #4186** 

1771 1ST ST

Livermore, CA 94550

Local ID:

RO0000436

Related ID:

4121

RWQCB ID:

01-1917

Global ID:

T0600101777

Responsible Party:

HAKAM S AND SIMRAT K MISSON

2952 COLLIER CANYON ROAD **LIVERMORE CA 94551-9224** 

Date First Reported: 1/27/1998

Substance: 8006619 Gasoline-Automotive (motor gasoline and

additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified HAKAM S. AND SIMRAT K. MISSON as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker WICKHAM, JERRY, at this office at (510)567-6791 if you have questions regarding your site.

ARIU LEVI, Director

Contract Project Director

Date:

Action: Add

Reason: ADD RP

## ALAMEDA COUNTY ENVIRONMENTAL HEALTH LUFT LOCAL OVERSIGHT PROGRAM

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

February 05, 2013

Site Name & Address: **UNOCAL #4186** 1771 1ST ST

Livermore, CA 94550

Local ID:

RO0000436

Related ID: 4121

RWQCB ID: 01-1917

Global ID:

T0600101777

#### All Responsible Parties

RP has been named a Primary RP - ERIC G HETRICK CONOCOPHILLIPS

76 BROADWAY | SACRAMENTO, CA 95818 | Phone (916) 558-7604

RP has been named a Primary RP - THOMAS T & CELINE T VADAKKEKUNNEL

4481 PEACOCK CT | DUBLIN, CA 94568 | Phone No Phone Number Listed

RP has been named a Primary RP - HAKAM S AND SIMRAT K MISSON

2952 COLLIER CANYON ROAD | LIVERMORE, CA 94551-9224 | Phone No Phone Number Listed

### Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

ACEH has named the responsible parties for this site as detailed below.

# ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET (Continued)

February 05, 2013

#### Responsible Party Identification

#### Existence of Unauthorized Release

In September 1997, six soil gas probes were advanced and sampled in the area of the underground storage tanks (USTs), dispensers, and product lines as part of a baseline site investigation. Subsequent site investigations have detected petroleum hydrocarbons and fuel oxygenates in soil and groundwater beneath the site. Based on the site characterization data, an unauthorized release or releases occurred from the UST system.

### Responsible Party Identification

ConocoPhillips was identified as the primary or active responsible party for the site in a Notice of Responsibility dated July 22, 2005. ConocoPhillips is a responsible party for the fuel leak because they or their corporate predecessors were the business owner, tank owner, and tank operator at the time of the unauthorized release (Definition 1), were the property owner at the time of the unauthorized release (Definition 3), and had control of the UST at the time of or following an unauthorized release (Definition 4).

Thomas T. and Celine T. Vadakkekunnel were identified as responsible parties for the site in a Notice of Responsibility dated July 22, 2005. Thomas T. and Celine T. Vadakkekunnel are responsible parties for the fuel leak because they were the property owner where an unauthorized release occurred (Definition 3).

Hakam S. and Simrat K Misson purchased the property in June 2012. As the current owner of the property where an unauthorized release occurred (Definition 3), Hakam S. and Simrat K Misson are also responsible parties.