**AGENCY** 

ALEX BRISCOE, Agency Director



**ENVIRONMENTAL HEALTH DEPARTMENT** OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 5715

August 18, 2014

#### NOTICE OF RESPONSIBILITY

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

Responsible Party:

HANG M. LY **169 DHILLON COURT HAYWARD CA 94544-5959**  Date First Reported:

12/16/1987

Substance:

8006619 Gasoline-Automotive (motor gasoline and

additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified HANG M. LY as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker NOWELL, KEITH, at this office at (510)567-6764 if you have questions regarding your site.

ARIU LEVI, Director Contract Project Director

Action: Update

Reason: ADD

## ALAMEDA COUNTY ENVIRONMENTAL HEALTH LUFT LOCAL OVERSIGHT PROGRAM

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

August 18, 2014

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

**All Responsible Parties** 

RP has been named a Primary RP - CAPITOL VALERO AUTO CARE INC

1610 TULLY RD | SAN JOSE, CA 95112 | No Phone Number Listed

RP has been named a Primary RP -

YO W & MI Y KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP - PHILLIPS 66 COMPANY

**ED RALSTON** 

76 BROADWAY | SACRAMENTO, CA 95818 | Phone (916) 558-7633

RP has been named a Primary RP - CHEVRON CORP

**NICOLE ARCENEAUX** 

6101 BOLLINGER CANYON RD, ROOM 5119 | SAN RAMON, CA 94583 | Phone (925) 790-6912

RP has been named a Primary RP -

SANG SOO KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP -

HANG M. LY

169 DHILLON COURT | HAYWARD, CA 94544-5959 | Phone (510) 562-9848

RP has been named a Primary RP – UNION OIL COMPANY OF CALIFORNIA

C/O UNOCAL 76 PROP TAX

August 18, 2014

#### **Responsible Party Identification Background**

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

August 18, 2014

#### **Existence of Unauthorized Release**

An active 76 Service Station operates at the subject property located at 500 Bancroft Avenue in San Leandro, Ca. The underground storage tanks (USTs) were removed and replaced in the late 1980s. Activities conducted at the site associated with the UST removal revealed free phase gasoline product present on the groundwater in the UST pit and maximum soil concentrations of 3,692 milligrams per kilogram (mg/kg) total petroleum hydrocarbons (TPH) as gasoline. This concentration and the presence of free phase gasoline product indicate an unauthorized release has occurred from the underground storage tank system at this site.

#### **Responsible Party Identification**

Union Oil Company of California was the property owner since June, 1970. Through a series of mergers acquisitions and spin offs, Union Oil Company of California became TOSCO, then ConocoPhillips, and, most recently, the Chevron Corporation. Chevron Corporation meets the definition of a responsible party for the site because they owned or operated an underground storage tank used for the storage of any hazardous substance (Definition 1), owned the property where an unauthorized release occurred (Definition 3), and had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Yo W. and Mi Y. Kim purchased the property in March of 2004. Yo W. and Mi Y. Kim are responsible parties because they owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Capitol Valero Auto Care Inc. purchased the property in March 2005. Capitol Valero Auto Care Inc. is a responsible party because it owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Hang M. Ly purchased the property in January 2007. Hang M. Ly is a responsible party because he owns the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

AGENCY

ALEX BRISCOE, Agency Director



**ENVIRONMENTAL HEALTH DEPARTMENT** OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 5708

August 18, 2014

## **NOTICE OF RESPONSIBILITY**

Site Name & Address:

UNOCAL #5367

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

Responsible Party:

**CAPITOL VALERO AUTO CARE INC** 1610 TULLY RD SAN JOSE CA 95112

Date First Reported:

12/16/1987

Substance:

8006619 Gasoline-Automotive (motor gasoline and

additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CAPITOL VALERO AUTO CARE INC as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your easeworker NOWELL, KEITH, at this office at (510)567-6764 if you have questions regarding your site.

ARIU LEVI, Director Contract Project Director

Action:

ADD

Update

## ALAMEDA COUNTY ENVIRONMENTAL HEALTH LUFT LOCAL OVERSIGHT PROGRAM

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

August 18, 2014

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

**All Responsible Parties** 

RP has been named a Primary RP - CAPITOL VALERO AUTO CARE INC

1610 TULLY RD | SAN JOSE, CA 95112 | No Phone Number Listed

RP has been named a Primary RP -

YO W & MI Y KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP - PHILLIPS 66 COMPANY

**ED RALSTON** 

76 BROADWAY | SACRAMENTO, CA 95818 | Phone (916) 558-7633

RP has been named a Primary RP - CHEVRON CORP

**NICOLE ARCENEAUX** 

6101 BOLLINGER CANYON RD, ROOM 5119 | SAN RAMON, CA 94583 | Phone (925) 790-6912

RP has been named a Primary RP -

SANG SOO KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP -

HANG M. LY

169 DHILLON COURT | HAYWARD, CA 94544-5959 | Phone (510) 562-9848

RP has been named a Primary RP – UNION OIL COMPANY OF CALIFORNIA

C/O UNOCAL 76 PROP TAX

August 18, 2014

## Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

August 18, 2014

#### **Existence of Unauthorized Release**

An active 76 Service Station operates at the subject property located at 500 Bancroft Avenue in San Leandro, Ca. The underground storage tanks (USTs) were removed and replaced in the late 1980s. Activities conducted at the site associated with the UST removal revealed free phase gasoline product present on the groundwater in the UST pit and maximum soil concentrations of 3,692 milligrams per kilogram (mg/kg) total petroleum hydrocarbons (TPH) as gasoline. This concentration and the presence of free phase gasoline product indicate an unauthorized release has occurred from the underground storage tank system at this site.

#### Responsible Party Identification

Union Oil Company of California was the property owner since June, 1970. Through a series of mergers acquisitions and spin offs, Union Oil Company of California became TOSCO, then ConocoPhillips, and, most recently, the Chevron Corporation. Chevron Corporation meets the definition of a responsible party for the site because they owned or operated an underground storage tank used for the storage of any hazardous substance (Definition 1), owned the property where an unauthorized release occurred (Definition 3), and had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Yo W. and Mi Y. Kim purchased the property in March of 2004. Yo W. and Mi Y. Kim are responsible parties because they owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Capitol Valero Auto Care Inc. purchased the property in March 2005. Capitol Valero Auto Care Inc. is a responsible party because it owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Hang M. Ly purchased the property in January 2007. Hang M. Ly is a responsible party because he owns the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

**AGENCY** 

ALEX BRISCOE, Agency Director



**ENVIRONMENTAL HEALTH DEPARTMENT** OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #: 7009 2820 0001 4359 5722

August 18, 2014

## **NOTICE OF RESPONSIBILITY**

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWOCB ID:

01-1604

Global iD:

T0600101479

Responsible Party:

YO W & MI Y KIM 17635 WICKMAN PLACE **SAN LORENZO CA 94580**  Date First Reported:

12/16/1987

Substance:

8006619 Gasoline-Automotive (motor gasoline and

additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified YO W & MI Y KIM as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker NOWELL, KEITH, at this office at (510)567-6764 if you have questions regarding your site.

ARIU LEVI, Director Contract Project Director

Action:

Reason: ADD

Update

## ALAMEDA COUNTY ENVIRONMENTAL HEALTH LUFT LOCAL OVERSIGHT PROGRAM

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

August 18, 2014

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

#### All Responsible Parties

RP has been named a Primary RP - CAPITOL VALERO AUTO CARE INC

1610 TULLY RD | SAN JOSE, CA 95112 | No Phone Number Listed

RP has been named a Primary RP -

YO W & MI Y KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP - PHILLIPS 66 COMPANY

**ED RALSTON** 

76 BROADWAY | SACRAMENTO, CA 95818 | Phone (916) 558-7633

RP has been named a Primary RP - CHEVRON CORP

**NICOLE ARCENEAUX** 

6101 BOLLINGER CANYON RD, ROOM 5119 | SAN RAMON, CA 94583 | Phone (925) 790-6912

RP has been named a Primary RP -

SANG SOO KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP -

HANG M. LY

169 DHILLON COURT | HAYWARD, CA 94544-5959 | Phone (510) 562-9848

RP has been named a Primary RP – UNION OIL COMPANY OF CALIFORNIA

C/O UNOCAL 76 PROP TAX

August 18, 2014

## Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

August 18, 2014

#### **Existence of Unauthorized Release**

An active 76 Service Station operates at the subject property located at 500 Bancroft Avenue in San Leandro, Ca. The underground storage tanks (USTs) were removed and replaced in the late 1980s. Activities conducted at the site associated with the UST removal revealed free phase gasoline product present on the groundwater in the UST pit and maximum soil concentrations of 3,692 milligrams per kilogram (mg/kg) total petroleum hydrocarbons (TPH) as gasoline. This concentration and the presence of free phase gasoline product indicate an unauthorized release has occurred from the underground storage tank system at this site.

#### **Responsible Party Identification**

Union Oil Company of California was the property owner since June, 1970. Through a series of mergers acquisitions and spin offs, Union Oil Company of California became TOSCO, then ConocoPhillips, and, most recently, the Chevron Corporation. Chevron Corporation meets the definition of a responsible party for the site because they owned or operated an underground storage tank used for the storage of any hazardous substance (Definition 1), owned the property where an unauthorized release occurred (Definition 3), and had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Yo W. and Mi Y. Kim purchased the property in March of 2004. Yo W. and Mi Y. Kim are responsible parties because they owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Capitol Valero Auto Care Inc. purchased the property in March 2005. Capitol Valero Auto Care Inc. is a responsible party because it owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Hang M. Ly purchased the property in January 2007. Hang M. Ly is a responsible party because he owns the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).





ALEX BRISCOE, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-933

August 18, 2014

Nicole Arceneaux Chevron Environmental Management Company 6101 Bollinger Canyon Road San Ramon, CA 94583

Sang Soo Kim 17635 Wickman Place San Lorenzo, CA 94580 Ed Ralston Phillips 66 Company 76 Broadway Sacramento, CA 95818

Unocal 76 Prop Tax Union Oil Company of California PO Box 7600 Los Angeles, CA 90051-0600

Subject: Fuel Leak Case No. RO0000499 and Geotracker Global ID T0600101479, Unocal #5367, 500 Bancroft Ave, San Leandro, CA 94577; Add Responsible Parties

#### Dear Responsible Parties:

In a Notice of Responsibility dated October 7, 1993, Sang Soo Kim and the Unocal Corporation were notified that the above referenced site had been placed in the Local Oversight Program and that Sang Soo Kim and the Unocal Corporation were named as a Responsible Parties for the fuel leak case. Yo and Mi Kim purchased the property in March 2004 and have been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Capitol Valero Auto Care Inc. purchased the property in March 2005 and has also been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Hang Ly purchased the property in January 2007 and has also been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Please see Attachment A – Responsible Parties Data Sheet, which identifies all Responsible Parties and provides background on the unauthorized release and Responsible Party Identification.

Should you have any questions regarding this correspondence or your case, please call me at (510) 567-6764 or send an electronic mail message at <a href="mailto:keith.nowell@acgov.org">keith.nowell@acgov.org</a>.

Sincerely,

DN: Cou Env

Digitally signed by Keith Nowell DN: cn=Keith Nowell, o=Alameda County, ou=Department of Environmental Health, email=keith.nowell@acgov.org, c=US

Date: 2014.08.19 09:35:23 -07'00

Keith Nowell

Hazardous Materials Specialist

Attachment A - Responsible Parties Data Sheet

cc:

Dilan Roe, ACEH Keith Nowell, ACEH

File

AGENCY

ALEX BRISCOE, Agency Director



**ENVIRONMENTAL HEALTH DEPARTMENT** OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #:

August 18, 2014

#### **NOTICE OF RESPONSIBILITY**

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

Responsible Party:

SANG SOO KIM

17635 WICKMAN PLACE SAN LORENZO CA 94580-- Date First Reported:

12/16/1987

Substance:

8006619 Gasoline-Automotive (motor gasoline and

additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified SANG SOO KIM as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your pageworker NOWELL, KEITH, at this office at (510)567-6764 if you have questions regarding your site.

ARIU LEVI, Director Contract Project Director

Update

Action: Reason:

ADD

## ALAMEDA COUNTY ENVIRONMENTAL HEALTH LUFT LOCAL OVERSIGHT PROGRAM

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

August 18, 2014

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

## All Responsible Parties

RP has been named a Primary RP - CAPITOL VALERO AUTO CARE INC

1610 TULLY RD | SAN JOSE, CA 95112 | No Phone Number Listed

RP has been named a Primary RP -

YOW & MIYKIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP - PHILLIPS 66 COMPANY

**ED RALSTON** 

76 BROADWAY | SACRAMENTO, CA 95818 | Phone (916) 558-7633

RP has been named a Primary RP - CHEVRON CORP

NICOLE ARCENEAUX

6101 BOLLINGER CANYON RD, ROOM 5119 | SAN RAMON, CA 94583 | Phone (925) 790-6912

RP has been named a Primary RP -

SANG SOO KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP -

HANG M. LY

169 DHILLON COURT | HAYWARD, CA 94544-5959 | Phone (510) 562-9848

RP has been named a Primary RP - UNION OIL COMPANY OF CALIFORNIA

C/O UNOCAL 76 PROP TAX

August 18, 2014

## Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

August 18, 2014

#### **Existence of Unauthorized Release**

An active 76 Service Station operates at the subject property located at 500 Bancroft Avenue in San Leandro, Ca. The underground storage tanks (USTs) were removed and replaced in the late 1980s. Activities conducted at the site associated with the UST removal revealed free phase gasoline product present on the groundwater in the UST pit and maximum soil concentrations of 3,692 milligrams per kilogram (mg/kg) total petroleum hydrocarbons (TPH) as gasoline. This concentration and the presence of free phase gasoline product indicate an unauthorized release has occurred from the underground storage tank system at this site.

#### Responsible Party Identification

Union Oil Company of California was the property owner since June, 1970. Through a series of mergers acquisitions and spin offs, Union Oil Company of California became TOSCO, then ConocoPhillips, and, most recently, the Chevron Corporation. Chevron Corporation meets the definition of a responsible party for the site because they owned or operated an underground storage tank used for the storage of any hazardous substance (Definition 1), owned the property where an unauthorized release occurred (Definition 3), and had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Yo W. and Mi Y. Kim purchased the property in March of 2004. Yo W. and Mi Y. Kim are responsible parties because they owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Capitol Valero Auto Care Inc. purchased the property in March 2005. Capitol Valero Auto Care Inc. is a responsible party because it owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Hang M. Ly purchased the property in January 2007. Hang M. Ly is a responsible party because he owns the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

**AGENCY** 



ALEX BRISCOE, Agency Director

ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-933

August 18, 2014

Nicole Arceneaux Chevron Environmental Management Company 6101 Bollinger Canyon Road San Ramon, CA 94583

Sang Soo Kim 17635 Wickman Place San Lorenzo, CA 94580 Ed Ralston Phillips 66 Company 76 Broadway Sacramento, CA 95818

Unocal 76 Prop Tax Union Oil Company of California PO Box 7600 Los Angeles, CA 90051-0600

Subject: Fuel Leak Case No. RO0000499 and Geotracker Global ID T0600101479, Unocal #5367, 500 Bancroft Ave, San Leandro, CA 94577; Add Responsible Parties

## Dear Responsible Parties:

In a Notice of Responsibility dated October 7, 1993, Sang Soo Kim and the Unocal Corporation were notified that the above referenced site had been placed in the Local Oversight Program and that Sang Soo Kim and the Unocal Corporation were named as a Responsible Parties for the fuel leak case. Yo and Mi Kim purchased the property in March 2004 and have been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Capitol Valero Auto Care Inc. purchased the property in March 2005 and has also been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Hang Ly purchased the property in January 2007 and has also been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Please see Attachment A – Responsible Parties Data Sheet, which identifies all Responsible Parties and provides background on the unauthorized release and Responsible Party Identification.

Should you have any questions regarding this correspondence or your case, please call me at (510) 567-6764 or send an electronic mail message at <a href="mailto:keith.nowell@acgov.org">keith.nowell@acgov.org</a>.

Sincerely,

Licht North Environment

Digitally signed by Keith Nowell DN: cn=Keith Nowell, o=Alameda County, ou=Department of Environmental Health, email=keith.nowell@acgov.org, c=US Date; 2014.08.19.09:35;23-07'00'

Keith Nowell

Hazardous Materials Specialist

Attachment A - Responsible Parties Data Sheet

CC:

Dilan Roe, ACEH Keith Nowell, ACEH

File

AGENCY

ALEX BRISCOE, Agency Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #:

August 18, 2014

## **NOTICE OF RESPONSIBILITY**

Site Name & Address:

UNOCAL #5367

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

Responsible Party:

**CHEVRON CORP** C/O NICOLE ARCENEAUX 6101 BOLLINGER CANYON RD, ROOM 5119 **SAN RAMON CA 94583** 

Date First Reported:

12/16/1987

Substance:

8006619 Gasoline-Automotive (motor gasoline and

additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CHEVRON CORP as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your case forker NOWELL, KEITH, at this office at (510)567-6764 if you have questions regarding your site.

ARIU LEVI, Director Contract Project Director

Update

Action: Reason:

ADD

## ALAMEDA COUNTY ENVIRONMENTAL HEALTH LUFT LOCAL OVERSIGHT PROGRAM

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

August 18, 2014

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

CB ID: 01-1604

Global ID:

T0600101479

**All Responsible Parties** 

RP has been named a Primary RP -

CAPITOL VALERO AUTO CARE INC

1610 TULLY RD | SAN JOSE, CA 95112 | No Phone Number Listed

RP has been named a Primary RP -

YO W & MI Y KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP - PHILLIPS 66 COMPANY

**ED RALSTON** 

76 BROADWAY | SACRAMENTO, CA 95818 | Phone (916) 558-7633.

RP has been named a Primary RP - CHEVRON CORP

**NICOLE ARCENEAUX** 

6101 BOLLINGER CANYON RD, ROOM 5119 | SAN RAMON, CA 94583 | Phone (925) 790-6912

RP has been named a Primary RP -

SANG SOO KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP -

HANG M. LY

169 DHILLON COURT | HAYWARD, CA 94544-5959 | Phone (510) 562-9848

RP has been named a Primary RP - UNION OIL COMPANY OF CALIFORNIA

C/O UNOCAL 76 PROP TAX

August 18, 2014

## Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

August 18, 2014

#### **Existence of Unauthorized Release**

An active 76 Service Station operates at the subject property located at 500 Bancroft Avenue in San Leandro, Ca. The underground storage tanks (USTs) were removed and replaced in the late 1980s. Activities conducted at the site associated with the UST removal revealed free phase gasoline product present on the groundwater in the UST pit and maximum soil concentrations of 3,692 milligrams per kilogram (mg/kg) total petroleum hydrocarbons (TPH) as gasoline. This concentration and the presence of free phase gasoline product indicate an unauthorized release has occurred from the underground storage tank system at this site.

#### **Responsible Party Identification**

Union Oil Company of California was the property owner since June, 1970. Through a series of mergers acquisitions and spin offs, Union Oil Company of California became TOSCO, then ConocoPhillips, and, most recently, the Chevron Corporation. Chevron Corporation meets the definition of a responsible party for the site because they owned or operated an underground storage tank used for the storage of any hazardous substance (Definition 1), owned the property where an unauthorized release occurred (Definition 3), and had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Yo W. and Mi Y. Kim purchased the property in March of 2004. Yo W. and Mi Y. Kim are responsible parties because they owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Capitol Valero Auto Care Inc. purchased the property in March 2005. Capitol Valero Auto Care Inc. is a responsible party because it owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Hang M. Ly purchased the property in January 2007. Hang M. Ly is a responsible party because he owns the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).





ENVIRONMENTAL HEALTH SERVICES **ENVIRONMENTAL PROTECTION** 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-933

August 18, 2014

Nicole Arceneaux Chevron Environmental Management Company 6101 Bollinger Canyon Road San Ramon, CA 94583

Sang Soo Kim 17635 Wickman Place San Lorenzo, CA 94580 Ed Ralston Phillips 66 Company 76 Broadway Sacramento, CA 95818

Unocal 76 Prop Tax Union Oil Company of California PO Box 7600 Los Angeles, CA 90051-0600

Subject: Fuel Leak Case No. RO0000499 and Geotracker Global ID T0600101479, Unocal #5367, 500 Bancroft Ave, San Leandro, CA 94577; Add Responsible Parties

## Dear Responsible Parties:

In a Notice of Responsibility dated October 7, 1993, Sang Soo Kim and the Unocal Corporation were notified that the above referenced site had been placed in the Local Oversight Program and that Sang Soo Kim and the Unocal Corporation were named as a Responsible Parties for the fuel leak case. Yo and Mi Kim purchased the property in March 2004 and have been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Capitol Valero Auto Care Inc. purchased the property in March 2005 and has also been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Hang Ly purchased the property in January 2007 and has also been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Please see Attachment A - Responsible Parties Data Sheet, which identifies all Responsible Parties and provides background on the unauthorized release and Responsible Party Identification.

Should you have any questions regarding this correspondence or your case, please call me at (510) 567-6764 or send an electronic mail message at keith.nowell@acgov.org.

Sincerely,

Digitally signed by Keith Nowell DN: cn=Keith Nowell, o=Alameda County, ou=Department of Environmental Health. email=keith.nowell@acgov.org, c=U5 Date: 2014.08.19 09:35:23 -07'00

Keith Nowell

Hazardous Materials Specialist

Attachment A - Responsible Parties Data Sheet

CC:

Dilan Roe, ACEH Keith Nowell, ACEH

File

AGENCY

ALEX BRISCOE, Agency Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #:

August 18, 2014

## **NOTICE OF RESPONSIBILITY**

Site Name & Address:

**UNOCAL #5367** 

500 BANCROFT AVE

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

RWQCB ID:

758

01-1604

Global ID:

T0600101479

Responsible Party:

PHILLIPS 66 COMPANY C/O ED RALSTON **76 BROADWAY SACRAMENTO CA 95818**  Date First Reported:

12/16/1987

Substance:

8006619 Gasoline-Automotive (motor gasoline and

additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified PHILLIPS 66 COMPANY as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your castworker NOWELL, KEITH, at this office at (510)567-6764 if you have questions regarding your site.

ARIU LEVI, Director Contract Project Director

Action:

Update

Reason: ADD

## ALAMEDA COUNTY ENVIRONMENTAL HEALTH LUFT LOCAL OVERSIGHT PROGRAM

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

August 18, 2014

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

CB ID: 01-1604

Global ID:

T0600101479

All Responsible Parties

RP has been named a Primary RP -

CAPITOL VALERO AUTO CARE INC

1610 TULLY RD | SAN JOSE, CA 95112 | No Phone Number Listed

RP has been named a Primary RP -

YO W & MI Y KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP - PHILLIPS 66 COMPANY

**ED RALSTON** 

76 BROADWAY | SACRAMENTO, CA 95818 | Phone (916) 558-7633

RP has been named a Primary RP - CHEVRON CORP

**NICOLE ARCENEAUX** 

6101 BOLLINGER CANYON RD, ROOM 5119 | SAN RAMON, CA 94583 | Phone (925) 790-6912

RP has been named a Primary RP -

SANG SOO KIM

17635 WICKMAN PLACE | ŞAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP -

HANG M. LY

169 DHILLON COURT | HAYWARD, CA 94544-5959 | Phone (510) 562-9848

RP has been named a Primary RP – UNION OIL COMPANY OF CALIFORNIA

C/O UNOCAL 76 PROP TAX

August 18, 2014

#### Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

August 18, 2014

#### **Existence of Unauthorized Release**

An active 76 Service Station operates at the subject property located at 500 Bancroft Avenue in San Leandro, Ca. The underground storage tanks (USTs) were removed and replaced in the late 1980s. Activities conducted at the site associated with the UST removal revealed free phase gasoline product present on the groundwater in the UST pit and maximum soil concentrations of 3,692 milligrams per kilogram (mg/kg) total petroleum hydrocarbons (TPH) as gasoline. This concentration and the presence of free phase gasoline product indicate an unauthorized release has occurred from the underground storage tank system at this site.

#### **Responsible Party Identification**


Union Oil Company of California was the property owner since June, 1970. Through a series of mergers acquisitions and spin offs, Union Oil Company of California became TOSCO, then ConocoPhillips, and, most recently, the Chevron Corporation. Chevron Corporation meets the definition of a responsible party for the site because they owned or operated an underground storage tank used for the storage of any hazardous substance (Definition 1), owned the property where an unauthorized release occurred (Definition 3), and had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Yo W. and Mi Y. Kim purchased the property in March of 2004. Yo W. and Mi Y. Kim are responsible parties because they owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Capitol Valero Auto Care Inc. purchased the property in March 2005. Capitol Valero Auto Care Inc. is a responsible party because it owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Hang M. Ly purchased the property in January 2007. Hang M. Ly is a responsible party because he owns the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

**AGENCY** 





ENVIRONMENTAL HEALTH SERVICES ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250 Alameda, CA 94502-6577 (510) 567-6700 FAX (510) 337-933

August 18, 2014

Nicole Arceneaux Chevron Environmental Management Company 6101 Bollinger Canyon Road San Ramon, CA 94583

Sang Soo Kim 17635 Wickman Place San Lorenzo, CA 94580 Ed Ralston Phillips 66 Company 76 Broadway Sacramento, CA 95818

Unocal 76 Prop Tax Union Oil Company of California PO Box 7600 Los Angeles, CA 90051-0600

Subject: Fuel Leak Case No. RO0000499 and Geotracker Global ID T0600101479, Unocal #5367, 500 Bancroft Ave, San Leandro, CA 94577; Add Responsible Parties

Dear Responsible Parties:

In a Notice of Responsibility dated October 7, 1993, Sang Soo Kim and the Unocal Corporation were notified that the above referenced site had been placed in the Local Oversight Program and that Sang Soo Kim and the Unocal Corporation were named as a Responsible Parties for the fuel leak case. Yo and Mi Kim purchased the property in March 2004 and have been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Capitol Valero Auto Care Inc. purchased the property in March 2005 and has also been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Hang Ly purchased the property in January 2007 and has also been named an additional Responsible Party for the fuel leak case as defined under 23 C.C.R Sec. 2720. Please see Attachment A – Responsible Parties Data Sheet, which identifies all Responsible Parties and provides background on the unauthorized release and Responsible Party Identification.

Should you have any questions regarding this correspondence or your case, please call me at (510) 567-6764 or send an electronic mail message at <a href="mailto:keith.nowell@acgov.org">keith.nowell@acgov.org</a>.

Sincerely,

Digitally signed by Keith Nowell
DN: cn≅Keith Nowell, o=Alameda
County, ou=Department of
Environmental Health,

email=keith.nowell@acgov.org, c=US Date; 2014.08,19 09;35;23 -07'00'

Keith Nowell

Hazardous Materials Specialist

Attachment A - Responsible Parties Data Sheet

CC:

Dilan Roe, ACEH Keith Nowell, ACEH

File

**AGENCY** 

ALEX BRISCOE, Agency Director



ENVIRONMENTAL HEALTH DEPARTMENT OFFICE OF THE DIRECTOR 1131 HARBOR BAY PARKWAY ALAMEDA, CA 94502-6577 (510) 567-6700 FAX (510) 337-9335

Certified Mail #:

August 18, 2014

#### NOTICE OF RESPONSIBILITY

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

Responsible Party:

YO W & MI Y KIM 17635 WICKMAN PLACE **SAN LORENZO CA 94580**  Date First Reported:

12/16/1987

Substance:

8006619 Gasoline-Automotive (motor gasoline and

additives), leaded & unleaded

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified YO W & MI Y KIM as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5752.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for further information about the designation process.

Please contact your caseworker NOWELL, KEITH, at this office at (510)567-6764 if you have questions regarding your site.

ARIU LEVI, Director Contract Project Director

Update ADD

Action: Reason:

## ALAMEDA COUNTY ENVIRONMENTAL HEALTH LUFT LOCAL OVERSIGHT PROGRAM

## ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

August 18, 2014

Site Name & Address:

**UNOCAL #5367** 

**500 BANCROFT AVE** 

San Leandro, CA 94577

Local ID:

RO0000499

Related ID:

758

RWQCB ID:

01-1604

Global ID:

T0600101479

**All Responsible Parties** 

RP has been named a Primary RP - CAPITOL VALERO AUTO CARE INC

1610 TULLY RD | SAN JOSE, CA 95112 | No Phone Number Listed

RP has been named a Primary RP -

YO W & MI Y KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP - PHILLIPS 66 COMPANY

**ED RALSTON** 

76 BROADWAY | SACRAMENTO, CA 95818 | Phone (916) 558-7633

RP has been named a Primary RP - CHEVRON CORP

NICOLE ARCENEAUX

6101 BOLLINGER CANYON RD, ROOM 5119 | SAN RAMON, CA 94583 | Phone (925) 790-6912

RP has been named a Primary RP -

SANG SOO KIM

17635 WICKMAN PLACE | SAN LORENZO, CA 94580 | No Phone Number Listed

RP has been named a Primary RP -

HANG M. LY

169 DHILLON COURT | HAYWARD, CA 94544-5959 | Phone (510) 562-9848

RP has been named a Primary RP – UNION OIL COMPANY OF CALIFORNIA

C/O UNOCAL 76 PROP TAX

August 18, 2014

#### Responsible Party Identification Background

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

August 18, 2014

#### **Existence of Unauthorized Release**

An active 76 Service Station operates at the subject property located at 500 Bancroft Avenue in San Leandro, Ca. The underground storage tanks (USTs) were removed and replaced in the late 1980s. Activities conducted at the site associated with the UST removal revealed free phase gasoline product present on the groundwater in the UST pit and maximum soil concentrations of 3,692 milligrams per kilogram (mg/kg) total petroleum hydrocarbons (TPH) as gasoline. This concentration and the presence of free phase gasoline product indicate an unauthorized release has occurred from the underground storage tank system at this site.

## **Responsible Party Identification**

Union Oil Company of California was the property owner since June, 1970. Through a series of mergers acquisitions and spin offs, Union Oil Company of California became TOSCO, then ConocoPhillips, and, most recently, the Chevron Corporation. Chevron Corporation meets the definition of a responsible party for the site because they owned or operated an underground storage tank used for the storage of any hazardous substance (Definition 1), owned the property where an unauthorized release occurred (Definition 3), and had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance (Definition 4).

Yo W. and Mi Y. Kim purchased the property in March of 2004. Yo W. and Mi Y. Kim are responsible parties because they owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Capitol Valero Auto Care Inc. purchased the property in March 2005. Capitol Valero Auto Care Inc. is a responsible party because it owned the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).

Hang M. Ly purchased the property in January 2007. Hang M. Ly is a responsible party because he owns the property where an unauthorized release of a hazardous substance from an underground storage tank has occurred (Definition 3).