R0511

RAFAT A. SHAHID, ASST, AGENCY DIRECTOR

Certified Mail #

DAVID J. KEARS, Agency Director

07/27/94 STID# 1771 DEPARTMENT OF ENVIRONMENTAL HEALTH State Water Resources Control Board Division of Clean Water Programs **UST Local Oversight Program** 80 Swan Way, Rm 200 Oakland, CA 94621 (510) 271-4530

Notice of Requirement to Reimburse

Pauline Reith B P Oil, Env. Resource. Mgmt. 295 SW - 41st St., Ste N Renton, Washington 98055

Responsible Party #1 Property Owner

Chester Bennett Tosco Corporation 3100 Zinfandel Dr., #200 Rancho Cordova, C A 95670

Responsible Party #2 Contact Person Contact Company

BP Oil Facility #11270 3255 Mecartney Rd Alameda, CA 94501

SITE

Date First Reported 11/04/92

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above ritter was a second responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incorred while oversigh specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Juliet M SHIN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Y UMiso Edgar B. Howell, III, Chief Contract Project Director

Mike Harper, SWRCB cc:

SWRCB Use:

update: X Reason: adel RP# 2

ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

RAFAT A. SHAHID, ASST, AGENCY DIRECTOR

DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

Certified Mail # P 367 604 564

04/07/93 STID# 1771 DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

R0511

Notice of Requirement to Reimburse

Pauline Reith B P Oile Company 16400 Southcenter Pkwy Tukwila, Washington 98188

BP Oil Facility #11270 3255 McCartney Rd. Alameda , CA 94501 Responsible Party Property Owner

SITE

Date First Reported 11/04/92

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Juliet M Shin, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

QUIBHOWN

SWRCB Use:

Add: X Reason: New Case