



certified mailer #P 367 604 620

December 26, 1991
STID# 3606

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Program
80 Swan Way, Rm. 200
Oakland, CA 94621
~~XXX~~(510) 271-4320

Notice of Requirement to Reimburse

Tumac Lumber Co. Inc.
ATTN: Andy Macko
22008 Meekland Ave.
Hayward, CA 94541

Responsible Party
Contact Person
Property ownery

K.D. Cedar Supply Co.
22008 Meekland Ave.
Hayward, CA 94541

SITE

Date First Reported:12/07/89
Substance: gasoline
Petroleum (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Thomas Peacock, Supervising Hazardous Material Specialist, at this office.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use : add: X Reason: New case

SENDER: Complete items 1 and 2 when additional services are desired, and complete items 3 and 4.
 Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested.

1. Show to whom delivered, date, and addressee's address. (Extra charge)
 2. Restricted Delivery (Extra charge)

3. Article Addressed to: Tumac Lumber Co., Inc. attn: Andy Macko 22008 Meekland Ave. Hayward, CA 94541	4. Article Number 3606 Type of Service: <input type="checkbox"/> Registered <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD <input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED.
5. Signature Address X <i>[Signature]</i>	8. Addressee's Address (ONLY if requested and fee paid)
6. Signature - Agent X <i>[Signature]</i>	
7. Date of Delivery 1-28-92	

PS Form 3811, Mar. 1988 * U.S.G.P.O. 1988-212-865 DOMESTIC RETURN RECEIPT

P 367 604 620
RECEIPT FOR CERTIFIED MAIL
 NO INSURANCE COVERAGE PROVIDED
 NOT FOR INTERNATIONAL MAIL
 (See Reverse)

U.S.G.P.O. 1989-234-555 PS Form 3800, June 1985	Sent to Tumac Lumber	
	Street and No. 22008 Meekland Ave	
	P.O., State and ZIP Code Hayward, CA 94541	
	Postage	\$
	Certified Fee	
	Special Delivery Fee	
	Restricted Delivery Fee	
	Return Receipt showing to whom and Date Delivered	
Return Receipt showing to whom, Date, and Address of Delivery		
TOTAL Postage and Fees	\$ 2.29	
Postmark of Date <i>[Signature]</i> Jan 7, 92		

3606

Fold at line over top of envelope of the...