HEALTH CARE SERVICES

AGENCY
DAVID J. KEARS, Agency Director
certified—mailer—#P-367-604-276

State Water Resources Control Board Division of Clean Water Programs RAUSTA DAMAD, AVERSIGHT, ARROGRAM

June 3, 1992 STID# 532 DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200

Notice of Requirement toakeim6094621 (510) 271-4320

O-I Brockway Glass, Inc. ATTN: Mr. Robert Neal 6150 Stoneridge Mall Rd., # 375 Pleasanton, CA 94588

Responsible Party Contact Person

Mr. William Taylor 8451 San Leandro St. Oakland, CA 94621

Responsible Party Property Owner

Brockway, Inc. 8717 G St. Oakland, CA 94621

SITE

Date First Reported 01/30/87 Substance: gasoline Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Barney Chan, Hazardous Material Specialist, at (510) 271-4530.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use :

add: X

Reason: New case

HEALTH CARE SERVICE

DAVID J. KEARS, Agency Director certified mailer #P-367

AGENCY

State Water Resources Control Board Division of Clean Water Programs RAHATA BARAID, Aversight Arggram

> DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200

June 3, 1992 STID# 532

Notice of Requirement toakermbarsel (510) 271-4320

O-I Brockway Glass, Inc. ATTN: Mr. Robert Neal 6150 Stoneridge Mall Rd., # 375 Pleasanton, CA 94588

Responsible Party Contact Person

Mr. William Taylor 8451 San Leandro St. Oakland, CA 94621

Responsible Party Property Owner

Brockway, Inc. 8717 G St. Oakland, CA 94621

SITE

Date First Reported 01/30/87 Substance: gasoline Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Barney Chan, Hazardous Material Specialist, at (510) 271-4530.

Edgar B. Howell, III, Chief Contract Project Director

Sandra Malos, SWRCB

SWRCB Use

add: X

Reason: New case