

Meeting Attendees

Subject MRCP
6707 BAY STREET EMERYVILLE
Date 9/23/94
Location 6707 BAY STREET EMERYVILLE

Name	Affiliation	Phone # / FAX #
1 <u>SUSAN HUGO</u>	<u>AC DEH</u>	<u>(510) 567-6700 / (510) 337-9335</u>
2 <u>Ravi Arulanandam</u>	<u>ACDEH / RWQ, CB</u>	<u>286-1331 / 286-1380</u>
3 <u>Sum Arigala</u>	<u>RWQ, CB</u>	<u>286 0434 /</u>
4 <u>R. William Rudolph</u>	<u>SCI</u>	<u>262 28 208 0461 /</u>
5 <u>Brian Berger</u>	<u>Pettit & Martin</u>	<u>415 439 7000 / 982 4608</u>
6 <u>Russell Juncal</u>	<u>RESNA</u>	<u>916 253 2155 / 916 253 2294</u>
7 _____	_____	_____ / _____
8 _____	_____	_____ / _____
9 _____	_____	_____ / _____
10 _____	_____	_____ / _____
11 _____	_____	_____ / _____
12 _____	_____	_____ / _____
13 _____	_____	_____ / _____
14 _____	_____	_____ / _____
15 _____	_____	_____ / _____
16 _____	_____	_____ / _____
17 _____	_____	_____ / _____

9/23/94

HRCP
- 6701 Bay Street Emeryville

Meeting: w/ HRCP + Insurance Co.

Sealing of USTs only or all environmental issues

1) Deposit \$3000⁰⁰ - letter 6/15/94

2) Health Risk Assessment

3) Plume Management - How do we know plume is not migrating, testing all wells for target compounds MEX MIBK

4) Send Notices

5) Stockpiled soil used in backfill in the pit?

6) Extraction wells - proposed two but only MW8 was used. true? also MW 7?

7) Piping layout of UST's system? any piping left on site?

TOG

White soil
P20

MW8 150 ppm MIBK in Had
160 ppm

300 = 6040 ppm

160 ppm pb
153 ppm cu

7) Uncertainty of ^{groundwater} flow direction ← North west?
South west?

8) only 3 wells continuously monitored

2) need the ff data -
 Summary of historical data
 target concentration in soil left on site }
 in in AED ?

- ✓ - phone control deed notice
- ✓ - contingency plan
- ✓ - site safety plan - change of ^{of} construction
- Overall management plan

Play - 14 ppm MIBK in MW8
 TDG?

Qualitative
 RA
 Vinyl Cl
 Benzene
 MIBK
 Inhalation
 fixed model
 slab foundation
 (0.1)

disturbance
 to soil H₂S
 must be known
 by agencies

- Vinyl Cl - dl (1 ppm)
 (0) → compliance points
 → monitoring frequency
- Benzene

increasing
decreasing

10 MW 8
9
10
1

4 consecutive quarters

²
(1) done
²
(3) to do

then

2 semi-annual - 6 months

(3)

• increasing plume

Country review - other issues
sic