AGENCY DAVID J. KEARS, Agency Director State Water Resources Control Board Division of Clean Water Programs UST Local Oversight Program

BAFAT A. SHAHID, Assistant Agency Director

certified mailer # P 367 604 499 April 6, 1992 STID# 1385

DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materiais Division 80 Swan Way, Rm. 200 Oakland, CA 94621 (510) 271-4320

## Notice of Requirement to Reimburse

Coulter Steel & Forge Co. Attn: Mr. Dante Sambajon 1494 67th Street Emeryville, CA 94608

Responsible Party Property Owner Contact Person

Coulter Steel & Forge Co. 1494 67th Street Emeryville, CA 94608

SITE

Date First Reported: 12/27/91

Substance: Diesel Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Susan L. Hugo, Senior Hazardous Material Specialist, at (510) 271-4530.

Edgar B. Howell, III, Chief Contract Project Director

Sandra Malos, SWRCB

SWRCB Use

add: X

Reason: New case

3 and 4.  Put your address in the "RETURN card from being returned to you. The to and the date of delivery. For add for fees and check box(es) for add Show to whom delivered, and the state of the s	TO" Space on the rever ne return receipt fee will printional fees the following fittional service (s) request	services are desired, and complete items se side. Failure to do this will prevent this rovide you the name of the person delivered services are available. Consult postmaster ted.  dress. 2.   Restricted Delivery (Extra charge)
3. Article Addressed to:	#1385	4. Article Number P 367 604 499
Coulter Steel & Forge Co. Attn: Mr. Dante Sambajon 1494 67th Street Emeryville, CA 94608		Type of Service:  Registered Insured Certified COD Express Mail Return Receipt for Merchandise
Emeryville, CA	1992 000	Always obtain signature of addressee
5. Signature — Address X	HAY /	*8. Addressee's Address (ONLY if requested and fee paid)
6. Signature Agent	20 3 LIVE	,
7. Date of Delivery		

## P 367 604 499 RECEIPT FOR CERTIFIED MAIL NO INSURANCE COVERAGE PROVIDED NOT FOR INTERNATIONAL MAIL (See Rejugge)

ιŋ	(See Reverse)			
234-55	Sent Bante Sambajon			
°U.S.G.P.O. 1989-234-555	1挙약4angN9th Street			
.G.P.O	PO. State and ZIP Code Emeryville, CA 94608			
Š.U.S	Postage	s		
1_	Certified Fee			
PS Form 3800, June 1985 #1385	Special Delivery Fee	<del> </del>		
	Restricted Delivery Fee			
	Return Receipt showing to whom and Date Delivered			
	Return Receipt showing to whom Date, and Address of Delivery			
June	TOTAL Postage and Fees	S		
3800	Postmark or Date			
Ē				
PS F				