

ALAMEDA COUNTY
HEALTH CARE SERVICES



AGENCY
DAVID J. KEARS, Agency Director

Alameda County CC4580
Environmental Health Services
1131 Harbor Bay Pkwy., #250
Alameda CA 94502-6577
(510)567-6700 FAX(510)337-9335

May 22, 1996

Dear sir:

The attached "**Notice of Reimbursement**" is not a bill. It is required by our contract with the State Water Resources Control Board that we send this letter to all responsible parties involved in a leaking petroleum underground tank site. A responsible party may be the operator of the tank or the property owner. You fall into the following category:

The site is contaminated and the Alameda County Local Oversight Program will be overseeing the cleanup through to a closure of the case. This letter says that you will be billed for the time that our technical staff spends on your case **after** the work has been accomplished.

We will work with you to expedite the remediation of your site.

If you have any questions please call this office at 567-6700 and ask for the specialist noted in the accompanying notice.

Sincerely,

Thomas F. Peacock, Supervising HMS
Environmental Health Services

ALAMEDA COUNTY
HEALTH CARE SERVICES



AGENCY
DAVID J. KEARS, Agency Director

Certified Mail #P 368 729 336
11/01/96
STID# 1068

ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION (LOP)
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335

Notice of Requirement to Reimburse

George Gasper Et Al
C/o Vigo N. Smith
3939 Walnut Avenue #264
Carmichael, Ca 95608-2197

Responsible Party (RP) #1
Property Owner

Marla Guensler
Exxon Company Usa # 7-0236
P. O. Box 4032
Concord, Ca 94524

Responsible Party (RP) #2
OPERATOR

Exxon # 7-0236
6600 E 14th St
Oakland, CA 94621

SITE


Date First Reported 04/01/91
Substance: Gasoline
Petroleum: (X)Yes
Source: F

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h) (6) and Section 25297.1 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board (SWRCB) not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above referenced underground storage tank site, and the above Responsible Party or Parties (RPs) must make full payment of such costs within 30 days of receipt of a detailed invoice from the SWRCB.

A determination of a secondary RP status may be made if it is shown that one or more of the RP(s) is performing corrective action and it is clear that the party seeking secondary status did not in any way initiate or contribute to the actual discharge. If the primary RP fails to perform corrective action, then the secondary RP will be considered a primary RP. To request designation as a secondary RP, contact this office.

Reimburse Letter
11/01/96
StID# 1068
Page 2

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the SWRCB. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, Please fax your request to Roni Riley at the SWRCB at (916) 227-4349 telephone the SWRCB at (916) 227-4408. Please contact Dale Klettke, Hazardous Materials Specialist at this office if you have any further questions concerning this matter.



Gordon Coleman, Acting Chief
Contract Project Director

Please Circle One Add Delete Change RP #3

Reason: ADDRESS CORRECTION

c: Lori Casias, SWRCB
Dale Klettke, Hazardous Materials Specialist

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY
DAVID J. KEARS, Agency Director



ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION (LOP)
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335

Certified Mail #P 368 729 337
11/01/96
STID# 1068

Notice of Requirement to Reimburse

George Gasper Et Al
C/o Vigo N. Smith
3939 Walnut Avenue #264
Carmichael, Ca 95608-2197

Responsible Party (RP) #1
Property Owner

Marla Guensler
Exxon Company Usa # 7-0236
P. O. Box 4032
Concord, Ca 94524

Responsible Party (RP) #2
OPERATOR

Exxon # 7-0236
6600 E 14th St
Oakland, CA 94621

SITE


Date First Reported 04/01/91
Substance: Gasoline
Petroleum: (X) Yes
Source: F

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Section 25297.1 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board (SWRCB) not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above referenced underground storage tank site, and the above Responsible Party or Parties (RPs) must make full payment of such costs within 30 days of receipt of a detailed invoice from the SWRCB.

A determination of a secondary RP status may be made if it is shown that one or more of the RP(s) is performing corrective action and it is clear that the party seeking secondary status did not in any way initiate or contribute to the actual discharge. If the primary RP fails to perform corrective action, then the secondary RP will be considered a primary RP. To request designation as a secondary RP, contact this office.

Reimburse Letter
11/01/96
StID# 1068
Page 2

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the SWRCB. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, Please fax your request to Roni Riley at the SWRCB at (916) 227-4349 telephone the SWRCB at (916) 227-4408. Please contact Dale Klettke, Hazardous Materials Specialist at this office if you have any further questions concerning this matter.



Gordon Coleman, Acting Chief
Contract Project Director

Please Circle One Add Delete Change

RP#3

Reason: ADDRESS CORRECTION

c: Lori Casias, SWRCB
Dale Klettke, Hazardous Materials Specialist

P 368 729 337
STID 1068

US Postal Service
Receipt for Certified Mail
No Insurance Coverage Provided.
Do not use for International Mail (See reverse)

Sender Marla Guensler	
Street & Number Exxon Co. #7-0236	
P.O. Box P.O. Box 4032	
Post Office Name & ZIP Code Concord, CA 94524	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date, & Addressee's Address	
TOTAL Postage & Fees	\$
Postmark or Date	

PS Form 3800, April 1995

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, and 4a & b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

- Addressee's Address
- Restricted Delivery
Consult postmaster for fee.

3. Article Addressed to:

**George Gasper Et Al
c/o Vigo N. Smith
3939 Walnut Ave #264
Carmicheal, CA 95608-2197
STID1068**

4a. Article Number
P 368 729 336

4b. Service Type

<input type="checkbox"/> Registered	<input type="checkbox"/> Insured
<input checked="" type="checkbox"/> Certified	<input type="checkbox"/> COD
<input type="checkbox"/> Express Mail	<input checked="" type="checkbox"/> Return Receipt for Merchandise

7. Date of Delivery
11-6-96

8. Addressee's Address (Only if requested and fee is paid)

5. Signature (Addressee)

6. Signature (Agent)
George Gasper

Is your RETURN ADDRESS completed on the reverse side?

PS Form 3811, December 1991 *U.S. GPO: 1993-2-714

DOMESTIC RETURN RECEIPT

Thank you for using Return Receipt Service.

ALAMEDA COUNTY
HEALTH CARE SERVICES



AGENCY
DAVID J. KEARS, Agency Director

ENVIRONMENTAL HEALTH SERVICES
ENVIRONMENTAL PROTECTION (LOP)
1131 Harbor Bay Parkway, Suite 250
Alameda, CA 94502-6577
(510) 567-6700
FAX (510) 337-9335

Certified Mail #P 368 729 336
11/01/96
STID# 1068

Notice of Requirement to Reimburse

George Gasper Et Al
C/o Vigo N. Smith
3939 Walnut Avenue #264
Carmichael, Ca 95608-2197

Responsible Party (RP) #1
Property Owner

Marla Guensler
Exxon Company Usa # 7-0236
P. O. Box 4032
Concord, Ca 94524

Responsible Party (RP) #2
OPERATOR

Exxon # 7-0236
6600 E 14th St
Oakland, CA 94621

SITE

Date First Reported 04/01/91
Substance: Gasoline
Petroleum: (X) Yes
Source: F

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Section 25297.1 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board (SWRCB) not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above referenced underground storage tank site, and the above Responsible Party or Parties (RPs) must make full payment of such costs within 30 days of receipt of a detailed invoice from the SWRCB.

A determination of a secondary RP status may be made if it is shown that one or more of the RP(s) is performing corrective action and it is clear that the party seeking secondary status did not in any way initiate or contribute to the actual discharge. If the primary RP fails to perform corrective action, then the secondary RP will be considered a primary RP. To request designation as a secondary RP, contact this office.


Reimburse Letter

11/01/96

StID# 1068

Page 2

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the SWRCB. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, Please fax your request to Roni Riley at the SWRCB at (916) 227-4349 telephone the SWRCB at (916) 227-4408. Please contact Dale Klettke, Hazardous Materials Specialist at this office if you have any further questions concerning this matter.



Gordon Coleman, Acting Chief
Contract Project Director

Please Circle One Add Delete Change RP #3

Reason: ADDRESS CORRECTION

c: Lori Casias, SWRCB

Dale Klettke, Hazardous Materials Specialist

Is your RETURN ADDRESS completed on the reverse side?

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, and 4a & b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

1. Addressee's Address
2. Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:
Marla Guensler
Maxxon Company USA #7-0236
P.O. Box 4032
Concord, CA 94524
STID 1068

4a. Article Number
P 368 729 337

4b. Service Type
 Registered Insured
 Certified COD
 Express Mail Return Receipt for Merchandise

7. Date of Delivery
NOV 07 1995

5. Signature (Addressee)

8. Addressee's Address (Only if requested and fee is paid)

6. Signature (Agent)


Thank you for using Return Receipt Service.

P 368 729 336

US Postal Service **STID 1068**

Receipt for Certified Mail

No Insurance Coverage Provided.

Do not use for International Mail (See reverse)

Sent to	
George Gasper Et al	
Area & City	
3939 Walnut Ave. #264	
Post Office, State, & ZIP Code	
Carmichael, CA 95608	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date, & Addressee's Address	
TOTAL Postage & Fees	\$
Postmark or Date	

PS Form 3800, April 1995

Returned

ALAMEDA COUNTY
HEALTH CARE SERVICES



AGENCY
DAVID J. KEARS, Agency Director

State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P367 603 997

03/27/92
STID# 1068

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

William Wong
Exxon Company Usa
Po Box 4032
Concord C A 94524

Responsible Party #1
Property Owner

George Gasper Et Al
C/o Vigo N. Smith
1009 Blossom River Wy 347
San Jose C A 95123

Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0236
6630 E. - 14th St.
Oakland, CA 94621

SITE Date First Reported 04/01/91
Substance: Gasoline
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Thomas F. Peacock
for Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

ge SWRCB Use: Add: X Reason: New Case

Fold at line over top of envelope to the right
of the return address.

Is your **RETURN ADDRESS**
completed on the reverse side?

<p>● SENDER: Complete items 1 and 2 when additional services are desired, and complete items 3 and 4. Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested.</p> <p>1. <input type="checkbox"/> Show to whom delivered, date, and addressee's address. (Extra charge) 2. <input type="checkbox"/> Restricted Delivery (Extra charge)</p>	
3. Article Addressed to: George Gasper Et Al C/O Vigo N. Smith 1009 Blossom River Wy #347	4. Article Number
	Type of Service: <input type="checkbox"/> Registered <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD <input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise
Always obtain signature of addressee or agent and <u>DATE DELIVERED</u> .	
5. Signature — Address X	8. Addressee's Address (ONLY if requested and fee paid)
6. Signature — Agent X	
7. Date of Delivery	

PS Form 3811, Mar. 1988 * U.S.G.P.O. 1988-212-865 DOMESTIC RETURN RECEIPT

Thank you for using
Return Receipt Service.

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY
DAVID J. KEARS, Agency Director



State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program

RAFAT A. SHAHID, Assistant Agency Director

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

March 23, 1992

Dear Sir:

The attached "**Notice of Reimbursement**" is not a bill. It is required by our contract with the State Water Resources Control Board that we send this letter to all responsible parties involved in a leaking petroleum underground tank site. You fall into the following category:

You (or your contractor/consultant) deposited funds for us to use to oversee the tank removal followed by the cleanup. Your case has been transferred to the Alameda County Local Oversight Program. This will involve your being billed **after** after the work has been accomplished. It is directed to all responsible parties as the law requires all operators and owners to be notified.

We will continue to work with you to resolve the site remediation in progress.

If you still have any question please call this office at 271-4530 and ask for the specialist noted in the attached notice.

Sincerely,

Thomas F. Peacock, Supervising HMS
Hazardous Material Division

ALAMEDA COUNTY
HEALTH CARE SERVICES
AGENCY

DAVID J. KEARS, Agency Director



RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

Certified Mail # P 113 815 463

06/07/93
STID# 1068

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Notice of Requirement to Reimburse

Marla Guensler
Exxon Company Usa
Po Box 4032
Concord C A 94524

Responsible Party #1
Property Owner

George Gasper Et Al
C/o Vigo N. Smith
3939 Walnut Ave.#264
Carmichael,c A 95608-2197

Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0236
6630 E. - 14th St.
Oakland, CA 94621

SITE

Date First Reported 04/01/91
Substance: Gasoline
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.


Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Update : X Reason: New address RP #2

Is your RETURN ADDRESS completed on the reverse side?

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, and 4a & b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

MB

I also wish to receive the following services (for an extra fee):

1. Addressee's Address

2. Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:

Marla Guensler
 EXXon Company USA
 P.O. Box 4032
 Concord, CA 94524
 STID# 1068

4a. Article Number
 P 113 815 463

4b. Service Type

Registered Insured

Certified COD

Express Mail Return Receipt for Merchandise

7. Date of Delivery
 JUN 1 1 1993

5. Signature (Addressee)

8. Addressee's Address (Only if requested and fee is paid)

6. Signature (Agent)

[Handwritten Signature]

Thank you for using Return Receipt Service.

PS Form 3811, December 1991 ☆ U.S.G.P.O. : 1992-307-530

DOMESTIC RETURN RECEIPT

P 113 815 463



Receipt for Certified Mail
 No Insurance Coverage Provided
 Do not use for International Mail
 (See Reverse)

PS Form 3800, June 1991

Sent to	
Street and No	
P.O., State and ZIP Code	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date, and Addressee's Address	
TOTAL Postage & Fees	\$
Postmark or Date	



Certified Mail # P 113 815 171

10/06/92
STID# 1068

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Marla Guensler
Exxon Company Usa
Po Box 4032
Concord C A 94524

Responsible Party #1
Property Owner

Mmm Properties
10 Crest Rd.
San Anselmo, Ca 94960


Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0236
6630 E. - 14th St.
Oakland, CA 94621

SITE Date First Reported 04/01/91
Substance: Gasoline
Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.


Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use: Add: X Reason: New RP

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, and 4a & b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt Fee will provide you the signature of the person delivered to and the date of delivery.

I also wish to receive the following services (for an extra fee):

1. Addressee's Address
2. Restricted Delivery

Consult postmaster for fee.

MMM Properties
 10 Crest Rd.
 San Anselmo, CA 94960

(TP) #1068

4a. Article Number
 P 113 815 171

4b. Service Type
 Registered Insured
 Certified COD
 Express Mail Return Receipt for Merchandise

7. Date of Delivery

10-14-90

8. Addressee's Address (Only if requested and fee is paid)

Eva Williams
 5. Signature (Addressee)

6. Signature (Agent)

PS Form 3811, November 1990 *U.S. GPO: 1991-287-066

DOMESTIC RETURN RECEIPT

P 113 815 171



Receipt for Certified Mail

No Insurance Coverage Provided
 Do not use for International Mail
 (See Reverse)

(TP) #1068

Sent to	
MMM Properties	
Street and No.	
10 Crest Rd.	
P.O., State and ZIP Code	
San Anselmo CA 94960	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date, and Addressee's Address	
TOTAL Postage & Fees	\$
Postmark or Date	

PS Form 3800, June 1991

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P367 603 997

03/27/92
STID# 1068

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

William Wong
Exxon Company Usa
Po Box 4032
Concord C A 94524

Responsible Party #1
Property Owner

George Gasper Et Al
C/o Vigo N. Smith
1009 Blossom River Wy 347
San Jose C A 95123

Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0236
6630 E. - 14th St.
Oakland, CA 94621

SITE

Date First Reported 04/01/91
Substance: Gasoline
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Thomas F. Peacock
for Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

92

SWRCB Use:

Add: X Reason: New Case

P 367 603 997

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED
NOT FOR INTERNATIONAL MAIL
(See Reverse)

U.S.G.P.O. 1989-234-555

PS Form 3800, June 1985

Sent to	
George Gasper Et Al	
Street and No.	
1009 Blossom River WY	
P.O., State and ZIP Code	
#347 San Jose CA 95123	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt showing to whom and Date Delivered	
Return Receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$
Postmark or Date	

ALAMEDA COUNTY
HEALTH CARE SERVICES



AGENCY

DAVID J. KEARS, Agency Director

RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P 113 815 169

10/06/92
STID# 1068

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Marla Guensler
Exxon Company Usa
Po Box 4032
Concord C A 94524

Responsible Party #1
Property Owner

MJM DK
Mjm Properties
10 Crest Rd.
San Anselmo, Ca 94960

Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0236
6630 E. - 14th St.
Oakland, CA 94621

SITE

Date First Reported 04/01/91
Substance: Gasoline
Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III
Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: ~~ED~~ New RP

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, and 4a & b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt Fee will provide you the signature of the person delivered to and the date of delivery.

I also wish to receive the following services (for an extra fee):

1. Addressee's Address
2. Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:
 (TP) #1068
 Exxon Company USA
 Attn: Marla Guensler
 P.O. Box 4032
 Concord, CA 94524
*6630 - E. 14th St.
 024621*

4a. Article Number

P 113 815 169

4b. Service Type

- Registered Insured
 Certified COD
 Express Mail Return Receipt for Merchandise

7. Date of Delivery

OCT. 13 1992

5. Signature (Addressee)

8. Addressee's Address (Only if requested and fee is paid)

6. Signature (Agent)

PS Form 3811, November 1990 * U.S. GPO: 1991-287-066

DOMESTIC RETURN RECEIPT

P 113 815 169



Receipt for Certified Mail

No Insurance Coverage Provided
 Do not use for International Mail
 (See Reverse)

(TP) #1068

Sent to	
Marla Guensler	
Street and No.	
P.O. Box 4032	
P.O., State and ZIP Code	
Concord, CA 94524	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to Whom & Date Delivered	
Return Receipt Showing to Whom, Date, and Addressee's Address	
TOTAL Postage & Fees	\$
Postmark or Date	

PS Form 3800, June 1991

ALAMEDA COUNTY
HEALTH CARE SERVICES



AGENCY
DAVID J. KEARS, Agency Director

State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program

RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P 367 603 996

03/27/92
STID# 1068

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

William Wong
Exxon Company Usa
Po Box 4032
Concord C A 94524

Responsible Party #1
Property Owner

George Gasper Et Al
C/o Vigo N. Smith
1009 Blossom River Wy 347
San Jose C A 95123

Responsible Party #2
Contact Person
Contact Company

Exxon # 7-0236
6630 E. - 14th St.
Oakland, CA 94621

SITE

Date First Reported 04/01/91
Substance: Gasoline
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Thomas F. Deacock
for Edgar B. Howell, III, Chief
Contract Project Director


cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

SENDER: Complete items 1 and 2 when additional services are desired, and complete items 3 and 4.
 Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check boxes for additional service(s) requested.

1. Show to whom delivered, date, and addressee's address. (Extra charge) 2. Restricted Delivery (Extra charge)

3. Article Addressed to: William Wong 1068 Exxon Company Usa PO Box 4032 Concord CA 94524	4. Article Number Type of Service: <input type="checkbox"/> Registered <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD <input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise Always obtain signature of addressee or agent and <u>DATE DELIVERED</u> .
5. Signature - Address X	8. Addressee's Address (ONLY if requested and fee paid)
6. Signature - Agent X 	
7. Date of Delivery <p style="text-align: center;">APR 2 1992</p>	

PS Form 3811, Mar. 1988 * U.S.G.P.O. 1988-212-865 DOMESTIC RETURN RECEIPT

P 367 603 996
RECEIPT FOR CERTIFIED MAIL
 NO INSURANCE COVERAGE PROVIDED
 NOT FOR INTERNATIONAL MAIL
 (See Reverse)

U.S.G.P.O. 1989-234-555

Sent to William Wong	
Street and No. PO Box 4032	
P.O., State and ZIP Code Concord CA 94524	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt showing to whom and Date Delivered	
Return Receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$
Postmark or Date	

PS Form 3800, June 1985