HEALTH CARE SERVICES

AGENCY DAVID J. KEARS, Agency Director

State Water Resources Control Board Division of Clean Water Programs UST Local Oversight Program

RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P 367 604 305

07/20/92 STID# 86 DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200 Oakland, CA 94621 (510) 271-4320

Notice of Requirement to Reimburse

Mr. Kurt Miller Shell Oil Co. P O Box 5278 Concord Ca 94520-9998

Responsible Party #1 Property Owner

Compliance Analyst Shell Oil Co P O Box 2099 Houston, T X 77252

Responsible Party #2 Contact Person Contact Company

Shell Station 3750 E. - 14th St. Oakland, CA 94601

SITE

Date First Reported 02/06/91

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Barney CHAN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

ouas. laiour "LEdgar B. Howell, IĬI, Chief Contract Project Director

Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

DAVID J. KEARS, Agency Director



State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P 367 604 304

07/20/92 STID# 86 DEPARTMENT OF ENVIRONMENTAL HEALTH Hazardous Materials Division 80 Swan Way, Rm. 200 Oakland, CA 94621 (510) 271-4320

Notice of Requirement to Reimburse

Mr. Kurt Miller Shell Oil Co. P O Box 5278 Concord Ca 94520-9998

Responsible Party #1 Property Owner

Compliance Analyst Shell Oil Co P O Box 2099 Houston, T X 77252

Responsible Party #2 Contact Person Contact Company

Shell Station 3750 E. - 14th St. Oakland, CA 94601

SITE

Date First Reported 02/06/91

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Barney CHAN, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

Put your address in the "RETURN TO" Space on the rever card from being returned to you. The return receipt fee will p to and the date of delivery. For additional fees the following for fees and check box(es) for additional service(s) request 1. Show to whom delivered, date, and addressee's a	roylde you the name of the person delivered services are available. Consult postmaster
3. Article Addressed to: (BC) #86 ROSA7 Shell Oil Company Attn: Compliance Analyst P.O. Box 2099 Houston, TX 77252	4. Article Number P 367 604 305 Type of Service: Registered
5. Signature — Address X 6. Signature — Agent X 7. Date of Delivery JUL 27 1992	8. Addressee's Address (ONLY if requested and fee paid)

to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) red 1. Show to whom delivered, date, and addressee's (Extra charge)	address. 2. Restricted Delivery
3. Article Addressed to: (BC) #86 Shell Oil Company Attn: Mr. Kurt Miller P.O. Box 5278	4. Article Number P 367 604 304 Type of Service: Registered Insured Certified COD
Concord, CA 94520-9998	Express Mail Return Receipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED.
5. Signature — Address X 3. Signature — Agent X 7. Date of Delivery	8. Addresses's Address (ONLY if requested and fee paid)