R0953

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

Certified Mail #

DAVID J. KEARS, Agency Director

P 386 338 130

10/01/93 STID# 2682 DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Notice of Requirement to Reimburse

Attn. Marla Guensler Exxon Co. 2300 Clayton Rd., #1250 Concord, C A 94540

Responsible Party #1 Property Owner

Attn. Ron Zielinski Texaco 108 Cutting Blvd. Richmond, C A 94804

Responsible Party #2 Contact Person Contact Company

EXXON Corp. 1175 Catalina Ave Livermore, CA 94550

SITE

Date First Reported 11/05/92

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Eva CHU, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Lori Casias, SWRCB

SWRCB Use:

CHANGE: X Reason: Add new RP#2



DAVID J. KEARS, Agency Director

R0953

(510) 271-4530

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621

Certified Mail #

P 386 338 129

10/01/93 STID# 2682

Notice of Requirement to Reimburse

Attn. Marla Guensler Exxon Co. 2300 Clayton Rd., #1250 Concord, C A 94540

Responsible Party #1 Property Owner

Attn. Ron Zielinski Texaco 108 Cutting Blvd. Richmond, C A 94804

Responsible Party #2 Contact Person Contact Company

EXXON Corp. 1175 Catalina Ave Livermore, CA 94550

SITE

Date First Reported 11/05/92

Substance: Gasoline Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Eva CHU, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Lori Casias, SWRCB

SWRCB Use:

CHANGE: X Reason: Add now RP#2

ALAMEDA COUNTY HEALTH CARE SERVICES AGENCY

R0953
RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

DAVID J. KEARS, Agency Director

TAFAT A. SHARID, ASST. AGENCY DIRECTOR

Certified Mail # P 113 815 371

02/18/93 STID# 2682 DEPARTMENT OF ENVIRONMENTAL HEALTH
State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program
80 Swan Way, Rm 200
Oakland, CA 94621
(510) 271-4530

Notice of Requirement to Reimburse

Attn. Marla Guensler Exxon Co. 2300 Clayton Rd., #1250 Concord, C A 94540

Responsible Party Property Owner

EXXON Corp. 1175 Catalina Ave. Livermore , CA 94550

Date First Reported 11/05/92 SITE Substance: Gasoline

Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Eva Chu, Hazardous Materials Specialist at this office if you have any questions concerning this matter.

Edgar B. Howell, III, Chief Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

CENTED.	
SENDER:	I also wish to receive the
Complete items 1 and/or 2 for additional services.	following services (for an extre
 Complete items 3, and 4a & b. Print your name and address on the reverse of this form so the 	at we can fee):
eature this card to VMI.	
Attach this form to the front of the mailpiece, or on the back if	if space 1. Addressee s Address
does not permit. Write "Return Receipt Requested" on the mailpiece below the arti-	scle number. 2. 🗌 Restricted Delivery
The Return Receipt will show to whom the article was delivered at	. 9 Adelhaide I
delivered.	Collegit postificates for too.
3. Article Addressed to: (EC) #2682	4a. Article Number
3. Article Addressed to: (EC) #2002 953	P 113 815 371
Marla Guensler	4b. Service Type
	Degictored Insured
Exexon Co.	Registered COD Everyose Mail Return Receipt for
2300 Clayton Rd., #1250	Return Receipt for
Concord CA 94540	Express Mail Heturn Receipt for Merchandise
- Sh	7 Descriptions
	2/22/93
	122/73
5. Signature (Addressee)	8. Addressee's Address (Only if requested
H. Italeu	and fee is∕paid)
A Cimphum (Ament)	
6. Signature (Agent)	
<u>U</u>	The state of the s
PS Form 3811, December 1991 * U.S.G.P.O.: 1992-30	77-530 DOMESTIC RETURN RECEIVE
ER:	I also wish to receive the
Complete items 3, and 4a & b.	following services ifor an extra
Print your name and address on the reverse of this form so	that we can fee):
return this card to your *** • Attach this form to the front of the mailpiece, or on the bac	ck if space 1. Addressee's Address
e Attach this form to the front of the mailpiece, or on the bac does not permit.	CK II opaco
 Write "Return Receipt Requested" on the mailpiece below the s 	article number 2. Restricted Delivery
The Return Receipt will show to whom the article was delivered	d and the date Consult postmaster for fee.
6 delivered.	4a. Article Number
3. Article Addressed 192682 RV 053	P 386 338 129
Ron Zielinski Texaco	P 380 336 129
🖣 Ron Zielinski	4b. Service Type
2 Texaco	☐ Registered ☐ Insured
5 16ACO	☑ Certified ☐ COD
108 Cutting BLvd	<u> </u>
Richmond CA 94804	Express Mail Heturn Receipt for Merchandise
108 Cutting BLvd Richmond CA 94804	7. Date of Delivery
a Kan U Notta	1018/98
z · · · · · · · · · · · · · · · · · · ·	8. Addressee's Address (Only if requester
~	and fee is paid)
	did is is powi
6. Signature (Agent)	
5	
8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
5	307-530 DOMESTIC RETURN COM
8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	-307-530 DOMESTIC RETURN INC.
8 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	-307-530 DOMESTIC RETURN INC.
PS Form 3811, December 1991 & U.S.G.P.O.: 1992-	
PS Form 3811, December 1991 & U.S.G.P.O.: 1992-	-307-530 DOMESTIC RETURN INC.
PS Form 3811, December 1991 ★ U.S.G.P.O.: 1992-	anal services are desired, and complete lights
PS Ferm 3811, December 1991 & U.S.G.P.O.: 1992-	onal services are desired, and complete lates
PS Ferm 3811, December 1991 & U.S.G.P.O.: 1992-	onal services are desired, and complete lates
PS Form 3811, December 1991 & U.S.G.P.O.: 1992-	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery
PS Ferm 3811, December 1991 & U.S.G.P.O.: 1992-	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. a address. 2. Restricted Delivery (Extra charge)
PS Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year indeass in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) req 1. Show to whom delivered, date, and addressee's (Extra charge)	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. a address. 2. Restricted Delivery (Extra charge)
P\$ Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) req 1. Show to whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to:	reverse side. Failure to do this will prevent this will provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number D 296 338 130
P\$ Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) req 1. Show to whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to:	reverse side. Failure to do this will prevent this will provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number D 296 338 130
PS Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year indeass in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) req 1. Show to whom delivered, date, and addressee's (Extra charge)	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service:
P\$ Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) req 1. Show to whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to:	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. 3 Article Number P 386 338 130 Type of Service: Registered insured
Present 3811, December 1991 & U.S.G.P.O.: 1992- Complete items 1 and 2 when addition and the date of delivery. For additional service (s) required to and the date of delivery. For additional service (s) required to some service (s) required to some service (s) required. Article Addressed to: Complete items 1 and 2 when additional receipt fee we have a some service (s) required. The service is the following for additional service (s) required. Complete items 1 and 2 when additional receipt fee we have to and the date of delivery. For additional service (s) required to ser	reverse side. Failure to do this will prevent this will provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured COD Return Receipt
Present 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) required to whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to: PEC#2682 Marla Guensler Exxon Co 2300 Clayton Rd #1250	reverse side. Failure to do this will prevent this will provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured COD Return Receipt for Merchandise
Present 3811, December 1991 & U.S.G.P.O.: 1992- Complete items 1 and 2 when addition and the date of delivery. For additional service (s) required to and the date of delivery. For additional service (s) required to some service (s) required to some service (s) required. Article Addressed to: Complete items 1 and 2 when additional receipt fee we have a some service (s) required. The service is the following for additional service (s) required. Complete items 1 and 2 when additional receipt fee we have to and the date of delivery. For additional service (s) required to ser	reverse side. Failure to do this will prevent this will provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured COD Return Receipt for Merchandise
Present 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) required to whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to: PEC#2682 Marla Guensler Exxon Co 2300 Clayton Rd #1250	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured COD Return Receipt for Merchandise Always obtain signature of addressee
Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) required to the whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to: PEC#2682 Marla Guensler Exxon Co 2300 Clayton Rd #1250 Concord CA 94540	reverse side. Failure to do this will prevent this will provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured Certified COD Return Receipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED.
Present 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) required to whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to: PEC#2682 Marla Guensler Exxon Co 2300 Clayton Rd #1250	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured Cortified COD Express Mail Return Recaipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED. 8. Addressee's Address (ONLY if
Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) required to the whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to: PEC#2682 Marla Guensler Exxon Co 2300 Clayton Rd #1250 Concord CA 94540	reverse side. Failure to do this will prevent this will provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured Certified COD Return Receipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED.
Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional service(s) requires and check box(es) for additional service(s) requires and addressee's (Extra charge) 3. Article Addressed to: PE #2682 Marla Guensler Exxon Co 2300 Clayton Rd #1250 Comcord CA 94540	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured Cortified COD Express Mail Return Recaipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED. 8. Addressee's Address (ONLY if
Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional fees the follow for fees and check box(es) for additional service(s) required to the whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to: PEC#2682 Marla Guensler Exxon Co 2300 Clayton Rd #1250 Concord CA 94540	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured Cortified COD Express Mail Return Recaipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED. 8. Addressee's Address (ONLY if
Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional service(s) requires and check box(es) for additional service(s) requires and addressee's (Extra charge) 3. Article Addressed to: PE #2682 Marla Guensler Exxon Co 2300 Clayton Rd #1250 Comcord CA 94540	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured Cortified COD Express Mail Return Recaipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED. 8. Addressee's Address (ONLY if
Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year address in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional service(s) requires and check box(es) for additional service(s) requires and addressee's (Extra charge) 3. Article Addressed to: PE #2682 Marla Guensler Exxon Co 2300 Clayton Rd #1250 Comcord CA 94540	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured Cortified COD Express Mail Return Recaipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED. 8. Addressee's Address (ONLY if
Ps Ferm 3811, December 1991 & U.S.G.P.O.: 1992- Put year inderess in the "RETURN TO" Space on the recard from being returned to you. The return receipt fee we to and the date of delivery. For additional service(s) required to some to whom delivered, date, and addressee's (Extra charge) 3. Article Addressed to: Carra charge Carra charge	reverse side. Failure to do this will prevent this vill provide you the name of the person delivered wing services are available. Consult postmaster quested. s address. 2. Restricted Delivery (Extra charge) 4. Article Number P 386 338 130 Type of Service: Registered Insured Cortified COD Express Mail Return Recaipt for Merchandise Always obtain signature of addressee or agent and DATE DELIVERED. 8. Addressee's Address (ONLY if

UNITED STATES POSTAL SERVICE

Official Business


PENALTY FOR PRIVATE, USE TO AVOID PAYMENTS OF POSTAGE, \$300.




93 FEB 23 AM 3: 25

Print your name, address and ZIP Code here

DEPARTMENT OF ENVIRONMENTAL HEALTH
HAZARDOUS MATERIALS DIVISON
80 SWAN WAY, SUITE 200
OAKLAND, CA 94621
430 - 4530





Print your name, address and ZIP Code here

UNITED STATES POSTATESERVICE

SENDER INSTRUCTIONS

Print your name, address and ZIP Code in the space below. • Complete items 1, 23, and 4 on the reverse.

- Attach to front article if space permits, otherwise affix to back of article.
- Endorse article (Return Receipt Requested" adjacent to number.





PENALTY FOR PRIVATE USE, \$300

RETURN TO

Print Sender's name, address, and ZIP Code in the space below.

DEPARTMENT OF ENVIRONMENTAL HEALTH HAZARDOUS MATERIALS DIVISON

80 SWAN WAY, SUITE 200 OAKLAND, CA 94621 430 - 4530