

## Subsurface Consultants, Inc.

5117 4578

R William Rudolph, P.E. President

August 21, 1997 SCI 955.002

Andreas Godfrey Alameda County Department of Public Works 940 Turner Court, Suite 300 Hayward, California 94545-2651

Monitoring Well Destruction Completion Letter 1016 West MacArthur Blvd. Oakland, CA 94608

Dear Mr. Godfrey:

In accordance with your permit issued on August 13, 1997, one monitoring well at the referenced site has been decommissioned per the Alameda County Health Care Services Agency (ACHCSA) request.

Monitoring well MW-1 is located on the west end of the Blazic property, near the junction of Apgar Street and West MacArthur Boulevards. On August 15, 1997, the well was destroyed by overdrilling, grouting by tremie, and pressure grouting for 10 minutes at a minimum of 10 pounds per square inch, as per Alameda County specifications. The well head was then removed and the final 3 feet of borehole was filled with cement grout to grade.

SCI believes that the conditions stipulated in your permit have been met. Furthermore, we request that the ACHCSA issue a final Remedial Action Completion Certificate for this site.

If you have any questions, please call.

Yours very truly,

Subsurface Consultants, Inc.

James. R. Helge

Project Environmental Scientist

JS:JH:ly 955.002\finallet.doc

cc: Mr. Albert Blazic

Ms. Susan Hugo - Alameda County Health Care Services Agency

P01

COVERENT COUNTER BLAZIO

02-15-95 12:12 PM Juson Huso Juson Huso 2/16/95 & len & Coll Thanks & May 3/14/44



655-5111 (510)

WEST Mac WARTHER OAKLAND CA. to purchase A TO BE A GAS STATION, OAKLAN
MD. BLAZIC SAID IT HAD 94608
BEEN CLEARED (SOIL TESTED)
BY THE APPRODE ATE PARTY A I AM
WITCHESTED TO SEE IF THIS IS TRUE. 名つる PEICE OF PROPERTY AT 1016 I KNOW THS PROPERTY USED しのとことの I AM CUIRRENTLY

JAY **TO:** 

Deember 5, 1994

Dear Susan Hugo, This letter is for my records, to confirm I called you on Oct. 13th, 1994, and you returned the call on October 17th. The essence of the conversation is that you and your "board" agreed we would put a "test drill" through the dirt (where you specify), testing as they go down, and then the water. If the water oclean, you close. You are in the process of writing a letter with instructions. We await this letter. Thank you.

File: 571D # 4575 Blazie Industrial Balancing Happy Holidaya, Sincerely, Jois Blazie (for al Blazie)