

ALAMEDA COUNTY  
HEALTH CARE SERVICES  
AGENCY

DAVID J. KEARS, Agency Director



R01026

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

Certified Mail #

02/18/93  
STID# 26

DEPARTMENT OF ENVIRONMENTAL HEALTH  
State Water Resources Control Board  
Division of Clean Water Programs  
UST Local Oversight Program  
80 Swan Way, Rm 200  
Oakland, CA 94621  
(510) 271-4530

**Notice of Requirement to Reimburse**

Kathleen Scheutzow  
Bridgestone/firestone Inc.  
1200 Firestone Pkwy.  
Akron, Oh 44317

Responsible Party #1  
Property Owner

Jim Given  
Argonaut Financial Service Inc  
#1 Eastmont Mall  
Oakland, Ca 94605

Responsible Party #3  
Contact Person  
Contact Company


Firestone  
2701 - 73rd Ave.  
Oakland, CA 94605

SITE

Date First Reported 12/20/89  
Substance: Gasoline  
Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

  
Edgar B. Howell, III, Chief  
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Update: X Reason: New RP #1 Address

ALAMEDA COUNTY - DEPARTMENT OF ENVIRONMENTAL HEALTH  
HAZARDOUS MATERIALS DIVISION

02/18/93

LIST OF RESPONSIBLE PARTIES FOR

SITE

StID: 26  
Firestone  
2701 - 73rd Ave.  
Oakland, CA 94605

Date First Reported 12/20/89  
Substance: Gasoline  
Petroleum (X) Yes

Kathleen Scheutzow  
Bridgestone/firestone Inc.  
1200 Firestone Pkwy.  
Akron, Oh 44317

Responsible Party #1  
Property Owner

Bob Gerber, Real Est  
J. C. Peney  
P. O. Box 4015  
Buena Park, Ca 90624

Responsible Party #2  
Contact Person  
Contact Company

Jim Given  
Argonaut Financial Service Inc  
#1 Eastmont Mall  
Oakland, Ca 94605

Responsible Party #3  
Contact Person  
Contact Company

ALAMEDA COUNTY  
HEALTH CARE SERVICES  
AGENCY

DAVID J. KEARS, Agency Director



R01026

RAFAT A. SHAHID, ASST. AGENCY DIRECTOR

Certified Mail #

02/18/93  
STID# 26

DEPARTMENT OF ENVIRONMENTAL HEALTH  
State Water Resources Control Board  
Division of Clean Water Programs  
UST Local Oversight Program  
80 Swan Way, Rm 200  
Oakland, CA 94621  
(510) 271-4530

Notice of Requirement to Reimburse

Kathleen Scheutzw ~~013815372~~  
Bridgestone/firestone Inc.  
1200 Firestone Pkwy.  
Akron, Oh 44317

Responsible Party #1  
Property Owner

Bob Gerber, Real Est  
J. C. Penney  
P. O. Box 4015  
Buena Park, Ca 90624

Responsible Party #2  
Contact Person  
Contact Company

Firestone  
2701 - 73rd Ave.  
Oakland, CA 94605

SITE

Date First Reported 12/20/89  
Substance: Gasoline  
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of site investigation or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Tom PEACOCK, Supervising Hazardous Materials Specialist at this office if you have any questions concerning this matter.

  
Edgar B. Howell, III, Chief  
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Update  Reason: New RP #1 Address

ALAMEDA COUNTY - DEPARTMENT OF ENVIRONMENTAL HEALTH  
HAZARDOUS MATERIALS DIVISION

02/18/93

LIST OF RESPONSIBLE PARTIES FOR

SITE

StID: 26  
Firestone  
2701 - 73rd Ave.  
Oakland, CA 94605

Date First Reported 12/20/89  
Substance: Gasoline  
Petroleum (X) Yes

Kathleen Scheutzow  
Bridgestone/firestone Inc.  
1200 Firestone Pkwy.  
Akron, Oh 44317

Responsible Party #1  
Property Owner

Bob Gerber, Real Est  
J. C. Penney  
P. O. Box 4015  
Buena Park, Ca 90624

Responsible Party #2  
Contact Person  
Contact Company

Jim Given  
Argonaut Financial Service Inc  
#1 Eastmont Mall  
Oakland, Ca 94605

Responsible Party #3  
Contact Person  
Contact Company

ALAMEDA COUNTY  
HEALTH CARE SERVICES

AGENCY  
DAVID J. KEARS, Agency Director



State Water Resources Control Board  
Division of Clean Water Programs  
UST Local Oversight Program

R01026

certified mailer #P 367 604 632

January 2, 1992  
STID# 26

DEPARTMENT OF ENVIRONMENTAL HEALTH  
Hazardous Materials Program  
80 Swan Way, Rm. 200  
Oakland, CA 94621  
~~(415)~~ (510) 271-4320

Notice of Requirement to Reimburse

Firestone  
ATTN: Kurt Jergens  
205 N. Michigan #34-000  
Chicago, IL 60601

Responsible Party  
Contact Person  
Contact Company

J.C. Penney  
ATTN: Bob Gerber, Real Estate Dept.  
P.O.Box 4015(6131 Orangethorpe Ave.)  
Buena Park, CA 90624

Responsible Party  
Contact Person  
Contact Company

Argonaut Financial Services, Inc.  
ATTN: Jim Given  
#1 Eastmont Mall  
Oakland, CA 94605

Responsible Party  
Property Owner

Former Firestone Store  
2701 73rd Ave.  
Oakland, CA 94605

SITE

Date First Reported 12/20/89  
Substance: gasoline  
Petroleum (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Notice of Requirement to Reimburse  
Former Firestone Store STID 26  
January 2, 1992  
Page 2 of 2

If you have any questions concerning this matter please contact  
Thomas Peacock, Supervising Hazardous Material Specialist, at  
this office.

Sincerely,



*for* Edgar B. Howell, III, Chief  
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use : 

add: X	Reason: New case
--------	------------------