

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY

DAVID J. KEARS, Agency Director



R01078

State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program

RAFAT A. SHAHID, Assistant Agency Director

Certified Mail # P 367 604 479

05/28/92
STID# 337

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Beatrice Slater
Golden State Linen Service
599 Loganberry Dr.
San Rafael, Ca 94903

Responsible Party #1
Property Owner

Rebecca J. Whitsett
Aratex Services, Inc.
1834 Walden Sq. Suite 450
Schaumburg, Il 60173-4299

Responsible Party #2
Contact Person
Contact Company

Golden State Linen Service
958 - 28th St.
Oakland, CA 94608

SITE

Date First Reported 05/24/88
Substance: Gasoline
Petroleum: (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Susan HUGO, Hazardous Materials Specialist at this office if you have any questions concerning this matter.


Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: ~~CHANGE~~ Reason: New RP Information



Certified Mail # P 367 604 ~~478~~ 480

05/28/92
STID# 337

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Beatrice Slater
Golden State Linen Service
599 Loganberry Dr.
San Rafael, Ca 94903

Responsible Party #1
Property Owner

Rebecca J. Whitsett
Aratex Services, Inc.
1834 Walden Sq. Suite 450
Schaumburg, Il 60173-4299

Responsible Party #2
Contact Person
Contact Company

Golden State Linen Service
958 - 28th St.
Oakland, CA 94608

SITE

Date First Reported 05/24/88
Substance: Gasoline
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

Please contact Susan HUGO, Hazardous Materials Specialist at this office if you have any questions concerning this matter.


Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: ~~CHANGE~~ Reason: New RP Information



Certified Mail # P 367 604 699

03/05/92
STID# 337

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Division
80 Swan Way, Rm. 200
Oakland, CA 94621
(510) 271-4320

Notice of Requirement to Reimburse

Beatrice Slater
Golden State Linen Service
599 Loganberry Dr.
San Rafael, Ca 94903

Responsible Party #1
Property Owner

~~Eric Burnett
Aratek Services
958 28th Street
Oakland, Ca 94608~~

Responsible Party #2
Contact Person
Contact Company

Golden State Linen Service
958 - 28th St.
Oakland , CA 94608

SITE

Date First Reported 05/24/88
Substance: Gasoline
Petroleum: (X)Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been indentified as the party or parties responsible for investigation and cleanup of the above site. YOU ARE HEREBY NOTIFIED that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Thomas Peacock, Supervising Hazardous Material Specialist, at this office.

Edgar B. Howell, III, Chief
Contract Project Director

cc: Sandra Malos, SWRCB

SWRCB Use:

Add: X Reason: New Case

JS