

JAN 27 1992



HAYWARD FIRE DEPARTMENT

Mr. Hugh Murphy
City of Hayward Fire Department
20 January 1992
Page 4

During the four quarters of monitoring, oil was reported in two of the three wells during the first quarter of sampling; the reported levels of oil were 0.3 mg/l, barely above the detection limit of 0.2 mg/l. No other hazardous constituents have been detected in any of the wells during any of the sampling events. We believe that the three quarters of no detection following a detection barely above the detection limit is sufficient to establish non-degradation of groundwater in the vicinity of the wells.


We believe that this letter responds to questions raised in your 30 December 1991 letter, and we look forward to receiving a copy of your letter to the RWQCB recommending site closure. Please contact me if you have any additional questions about the information presented herein.

Sincerely yours,

GEOMATRIX CONSULTANTS, INC.

A handwritten signature in cursive script that reads 'Sally E. Goodin'.

Sally E. Goodin, R.G.
Senior Hydrogeologist



Attachments

cc: Curtis Carr

ugh-

Please substitute this page for
page 4 of the document we
sent you earlier. Sorry for the
inconvenience - I suddenly
remembered you wanted
a stamp on all letters.

Thanks!
Pam