HEALTH CARE SERVICES





NOTICE OF RESPONSIBILITY

DAVID J. KEARS. Agency Director

Certified Mail #: 7006 3450 0000 0503 0366

June 09, 2009

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577

510) 567-6700 FAX (510) 337-9335

Site Name & Address:

MCCORMACK/CHACKERIAN PROPERTY

5925 OCEAN VIEW DR OAKLAND, CA 94618

Local ID:

RO0003003

Related ID:

NA

RWQCB ID:

NA

Global ID:

T10000001165

Responsible Party:

CYNTHIA CHACKERIAN C/O MCCORMACK LAW FIRM 120 MONTGOMERY ST #1600 SAN FRANCISCO CA 94104

Date First Reported:

5/7/2009

Substance:

12 Heater fuel

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified CYNTHIA CHACKERIAN as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for

Please contact your caseworker DETTERMAN, MARK, at this office at (510)567-6876 if you have questions regarding

your site.

Contract Project Director

ARIU LEVI, Director

Date:

6/22/09

Action: Add

Reason: New case

Attachment A: Responsible Parties Data Sheet cc: Jenniffer Jordan, SWRCB, D. Drogos, File

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

June 09, 2009

Site Name & Address:

MCCORMACK/CHACKERIAN PROPERTY 5925 OCEAN VIEW DR OAKLAND, CA 94618 Local ID:

RO0003003

Related ID: NA

RWQCB ID: NA

117

Global ID:

T10000001165

All Responsible Parties

RP has been named a Primary RP - CYNTHIA CHACKERIAN

C/O MCCORMACK LAW FIRM

120 MONTGOMERY ST #1600 | SAN FRANCISCO, CA 94104 | Phone (415) 440-6662

RP has been named a Primary RP - BRIAN MCCORMACK

C/O MCCORMACK LAW FIRM

120 MONTGOMERY ST #1600 | SAN FRANCISCO, CA 94104 | Phone (415) 440-6662

RP has been named a Primary RP - JOHN MOREHOUSE

5925 OCEAN VIEW DR | OAKLAND, CA 94612 | Phone (415) 512-3016

RP has been named a Primary RP - KATRINA RAPA

5925 OCEAN VIEW DR | OAKLAND, CA 94612 | Phone (415) 672-0355

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

June 09, 2009

Responsible Party Identification

Existence of Unauthorized Release

An approximately 250-gallon underground storage tank (UST) was removed from beneath the driveway at 5925 Ocean View Drive, Oakland, CA on April 21, 2009. The age or history of the UST was not known by the owner. The UST was in good condition with no noticeable holes; however, hydrocarbon odors were noted in the overburden soil and within the UST pit. A removal confirmation soil sample collected beneath the UST at a depth of approximately 8.5 feet contained 448 milligrams per kilogram (mg/Kg) Total Petroleum Hydrocarbons (TPH) as heating oil, non-detectable concentrations of TPH as motor oil, benzene, toluene, and methyl-tert-butyl ether at elevated detection limits, and 0.047 mg/Kg and 0.0396 mg/Kg ethylbenzene and total xylenes, respectively. Total lead was detected at a concentration of 35.6 mg/Kg. Two stockpile samples were analyzed, a four-point composite and a hotspot sample. Both contained multiple detectable concentrations; however, the hotspot contained up to 2,750 mg/kg TPH heating oil. Based on the results of soil sampling an unauthorized release occurred from the UST.

Responsible Party Identification

Bryon McCormack and Cynthia Chackerian were the property owners at the time of UST removal. Both have been named as a "Responsible Party" under Definitions 1 and 3, above.

HEALTH CARE SERVICES





NOTICE OF RESPONSIBILITY

DAVID J. KEARS, Agency Director

Certified Mail #: 7006 3450 0000 0503 0373

June 09, 2009

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577

:5101.567-6700 FAX (310) 837-9335

Site Name & Address:

MCCORMACK/CHACKERIAN PROPERTY

5925 OCEAN VIEW DR OAKLAND, CA 94618

Local ID:

RO0003003

Related ID:

NA

RWQCB ID:

NA

Global ID:

T10000001165

Responsible Party:

BRIAN MCCORMACK C/O MCCORMACK LAW FIRM **120 MONTGOMERY ST #1600 SAN FRANCISCO CA 94104**

Date First Reported:

5/7/2009

Substance:

12 Heater fuel

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified BRIAN MCCORMACK as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for

Please contact your caseworker DETTERMAN, MARK, at this office at (510)567-6876 if you have questions regarding your site.

ARIU-LEVI, Director Contract Project Direct Date: 6/22/09

Action: Add

Reason: New case

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

June 09, 2009

Site Name & Address:

MCCORMACK/CHACKERIAN PROPERTY 5925 OCEAN VIEW DR OAKLAND, CA 94618 Local ID:

RO0003003

Related ID: NA

RWQCB ID:

NA

Global ID:

T10000001165

All Responsible Parties

RP has been named a Primary RP - CYNTHIA CHACKERIAN C/O MCCORMACK LAW FIRM

120 MONTGOMERY ST #1600 | SAN FRANCISCO, CA 94104 | Phone (415) 440-6662

RP has been named a Primary RP - BRIAN MCCORMACK C/O MCCORMACK LAW FIRM

120 MONTGOMERY ST #1600 | SAN FRANCISCO, CA 94104 | Phone (415) 440-6662

RP has been named a Primary RP - JOHN MOREHOUSE

5925 OCEAN VIEW DR | OAKLAND, CA 94612 | Phone (415) 512-3016

RP has been named a Primary RP - KATRINA RAPA

5925 OCEAN VIEW DR | OAKLAND, CA 94612 | Phone (415) 672-0355

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

June 09, 2009

Responsible Party Identification

Existence of Unauthorized Release

An approximately 250-gallon underground storage tank (UST) was removed from beneath the driveway at 5925 Ocean View Drive, Oakland, CA on April 21, 2009. The age or history of the UST was not known by the owner. The UST was in good condition with no noticeable holes; however, hydrocarbon odors were noted in the overburden soil and within the UST pit. A removal confirmation soil sample collected beneath the UST at a depth of approximately 8.5 feet contained 448 milligrams per kilogram (mg/Kg) Total Petroleum Hydrocarbons (TPH) as heating oil, non-detectable concentrations of TPH as motor oil, benzene, toluene, and methyl-tert-butyl ether at elevated detection limits, and 0.047 mg/Kg and 0.0396 mg/Kg ethylbenzene and total xylenes, respectively. Total lead was detected at a concentration of 35.6 mg/Kg. Two stockpile samples were analyzed, a four-point composite and a hotspot sample. Both contained multiple detectable concentrations; however, the hotspot contained up to 2,750 mg/kg TPH heating oil. Based on the results of soil sampling an unauthorized release occurred from the UST.

Responsible Party Identification

Bryon McCormack and Cynthia Chackerian were the property owners at the time of UST removal. Both have been named as a "Responsible Party" under Definitions 1 and 3, above.



HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

Certified Mail #: 7006 3450 0000 0503 0380

June 09, 2009

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577

(510) 567-6709 FAX (510) 337-9335

NOTICE OF RESPONSIBILITY

Site Name & Address:

MCCORMACK/CHACKERIAN PROPERTY

5925 OCEAN VIEW DR OAKLAND, CA 94618

Local ID:

RO0003003

Related ID:

NA

RWQCB ID: NA

Global ID:

T10000001165

Responsible Party:

JOHN MOREHOUSE

5925 OCEAN VIEW DR OAKLAND CA 94612

Date First Reported:

5/7/2009

Substance:

12 Heater fuel

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified JOHN MOREHOUSE as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for

Please contact your caseworker DETTERMAN, MARK, at this office at (510)567-6876 if you have questions regarding your site.

ARIU-LEVI, Director Contract Project Director

Date: 6/2408

Action: Add

Reason: New case

Attachment A: Responsible Parties Data Sheet cc: Jenniffer Jordan, SWRCB, D. Drogos, File

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

June 09, 2009

Site Name & Address:

MCCORMACK/CHACKERIAN PROPERTY 5925 OCEAN VIEW DR OAKLAND, CA 94618 Local ID:

RO0003003

Related ID: N

RWQCB ID: NA

Global ID:

T10000001165

All Responsible Parties

RP has been named a Primary RP - CYNTHIA CHACKERIAN C/O MCCORMACK LAW FIRM

120 MONTGOMERY ST #1600 | SAN FRANCISCO, CA 94104 | Phone (415) 440-6662

RP has been named a Primary RP - BRIAN MCCORMACK C/O MCCORMACK LAW FIRM

120 MONTGOMERY ST #1600 | SAN FRANCISCO, CA 94104 | Phone (415) 440-6662

RP has been named a Primary RP - JOHN MOREHOUSE

5925 OCEAN VIEW DR | OAKLAND, CA 94612 | Phone (415) 512-3016

RP has been named a Primary RP - KATRINA RAPA

5925 OCEAN VIEW DR | OAKLAND, CA 94612 | Phone (415) 672-0355

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

June 09, 2009

Responsible Party Identification

Existence of Unauthorized Release

An approximately 250-gallon underground storage tank (UST) was removed from beneath the driveway at 5925 Ocean View Drive, Oakland, CA on April 21, 2009. The age or history of the UST was not known by the owner. The UST was in good condition with no noticeable holes; however, hydrocarbon odors were noted in the overburden soil and within the UST pit. A removal confirmation soil sample collected beneath the UST at a depth of approximately 8.5 feet contained 448 milligrams per kilogram (mg/Kg) Total Petroleum Hydrocarbons (TPH) as heating oil, non-detectable concentrations of TPH as motor oil, benzene, toluene, and methyl-tert-butyl ether at elevated detection limits, and 0.047 mg/Kg and 0.0396 mg/Kg ethylbenzene and total xylenes, respectively. Total lead was detected at a concentration of 35.6 mg/Kg. Two stockpile samples were analyzed, a four-point composite and a hotspot sample. Both contained multiple detectable concentrations; however, the hotspot contained up to 2,750 mg/kg TPH heating oil. Based on the results of soil sampling an unauthorized release occurred from the UST.

Responsible Party Identification

Bryon McCormack and Cynthia Chackerian were the property owners at the time of UST removal. Both have been named as a "Responsible Party" under Definitions 1 and 3, above.



HEALTH CARE SERVICES





DAVID J. KEARS, Agency Director

Certified Mail #: 7006 3450 0000 0503 0397

June 09, 2009

ENVIRONMENTAL HEALTH SERVICES

ENVIRONMENTAL PROTECTION 1131 Harbor Bay Parkway, Suite 250

Alameda, CA 94502-6577 15101 567-6700

NOTICE OF RESPONSIBILITY FAX (510) 337-9335

Site Name & Address:

MCCORMACK/CHACKERIAN PROPERTY

5925 OCEAN VIEW DR OAKLAND, CA 94618

Local ID:

RO0003003

Related ID:

NA

RWQCB ID:

NA

Global ID:

T10000001165

Responsible Party:

KATRINA RAPA

5925 OCEAN VIEW DR OAKLAND CA 94612

Date First Reported:

5/7/2009

Substance:

12 Heater fuel

Funding for Oversight: LOPS - LOP State Fund

Multiple RPs?: Yes

Pursuant to sections 25297.1 and 25297.15 of the Health and Safety Code, you are hereby notified that the above site has been placed in the Local Oversight Program and the individual(s) or entity(ies) shown above, or on the attached list, has (have) been identified as the party(ies) responsible for investigation and cleanup of the above site. Section 25297.15 further requires the primary or active Responsible Party to notify all current record owners of fee title before the local agency considers cleanup or site closure proposals or issues a closure letter. For purposes of implementing section 25297.15, this agency has identified KATRINA RAPA as the primary or active Responsible Party. It is the responsibility of the primary or active Responsible Party to submit a letter to this agency, within 20 calendar days of receipt of this notice that identifies all current record owners of fee title. It is also the responsibility of the primary or active Responsible Party to certify to the local agency that the required notifications have been made at the time a cleanup or site closure proposal is made or before the local agency makes a determination that no further action is required. If property ownership changes in the future, you must notify this local agency within 20 calendar days from when you are informed of the change.

Any action or inaction by this local agency associated with corrective action, including responsible party identification, is subject to petition to the State Water Resources Control Board. Petitions must be filed within 30 days from the date of the action/inaction. To obtain petition procedures, please FAX your request to the State Water Board at (916) 341-5808 or telephone (916) 341-5650.

Pursuant to section 25296.10(c)(6) of the Health and Safety Code, a responsible party may request the designation of an administering agency when required to conduct corrective action. Please contact this office for

Please contact your caseworker DETTERMAN, MARK, at this office at (510)567-6876 if you have questions regarding your site.

ARIU LEVI, Director Contract Project Director Date:

KINDE

Action: Add

Reason: New case

ATTACHMENT A - RESPONSIBLE PARTIES DATA SHEET

June 09, 2009

Site Name & Address:

MCCORMACK/CHACKERIAN PROPERTY

5925 OCEAN VIEW DR

OAKLAND, CA 94618

Local ID:

RO0003003

Related ID: NA

NA NA

RWQCB ID:

Global ID:

T10000001165

All Responsible Parties

RP has been named a Primary RP - CYNTHIA CHACKERIAN

C/O MCCORMACK LAW FIRM

120 MONTGOMERY ST #1600 | SAN FRANCISCO, CA 94104 | Phone (415) 440-6662

RP has been named a Primary RP - BRIAN MCCORMACK

C/O MCCORMACK LAW FIRM

120 MONTGOMERY ST #1600 | SAN FRANCISCO, CA 94104 | Phone (415) 440-6662

RP has been named a Primary RP - JOHN MOREHOUSE

5925 OCEAN VIEW DR | OAKLAND, CA 94612 | Phone (415) 512-3016

RP has been named a Primary RP - KATRINA RAPA

5925 OCEAN VIEW DR | OAKLAND, CA 94612 | Phone (415) 672-0355

Responsible Party Identification Background

Alameda County Environmental Health (ACEH) names a "Responsible Party," as defined under 23 C.C.R Sec. 2720. Section 2720 defines a responsible party 4 ways. An RP can be:

- 1. "Any person who owns or operates an underground storage tank used for the storage of any hazardous substance."
- 2. "In the case of any underground storage tank no longer in use, any person who owned or operated the underground storage tank immediately before the discontinuation of its use."
- 3. "Any owner of property where an unauthorized release of a hazardous substance from an underground storage tank has occurred."
- 4. "Any person who had or has control over an underground storage tank at the time of or following an unauthorized release of a hazardous substance."

June 09, 2009

Responsible Party Identification

Existence of Unauthorized Release

An approximately 250-gallon underground storage tank (UST) was removed from beneath the driveway at 5925 Ocean View Drive, Oakland, CA on April 21, 2009. The age or history of the UST was not known by the owner. The UST was in good condition with no noticeable holes; however, hydrocarbon odors were noted in the overburden soil and within the UST pit. A removal confirmation soil sample collected beneath the UST at a depth of approximately 8.5 feet contained 448 milligrams per kilogram (mg/Kg) Total Petroleum Hydrocarbons (TPH) as heating oil, non-detectable concentrations of TPH as motor oil, benzene, toluene, and methyl-tert-butyl ether at elevated detection limits, and 0.047 mg/Kg and 0.0396 mg/Kg ethylbenzene and total xylenes, respectively. Total lead was detected at a concentration of 35.6 mg/Kg. Two stockpile samples were analyzed, a four-point composite and a hotspot sample. Both contained multiple detectable concentrations; however, the hotspot contained up to 2,750 mg/kg TPH heating oil. Based on the results of soil sampling an unauthorized release occurred from the UST.

Responsible Party Identification

Bryon McCormack and Cynthia Chackerian were the property owners at the time of UST removal. Both have been named as a "Responsible Party" under Definitions 1 and 3, above.

