

**From:** [Detterman, Karel, Env. Health](mailto:Detterman.Karel.Env.Health@dave@eras.biz)  
**To:** "dave@eras.biz"  
**Cc:** [F40RACER@aol.com](mailto:F40RACER@aol.com); [andrew@eras.biz](mailto:andrew@eras.biz)  
**Subject:** RE: Report Status for 1814 Everett - Fuel Leak Case RO3193, Walt Living Trust, 1814 Everett St, Alameda, CA, Geotracker Global ID No. T10000007934  
**Date:** Tuesday, July 12, 2016 1:42:28 PM

---

Hello Dave:

Below is the extension for the Soil and Groundwater Investigation Report, and are you going to be able to submit the Hydraulic Lift Removal Report tomorrow?

**TECHNICAL REPORT REQUEST EXTENSION**

-  
Please upload technical reports to the ACEH ftp site (Attention: Karel Detterman), and to the State Water Resources Control Board's Geotracker website, in accordance with the following specified file naming convention and schedule:

- **August 12, 2016 ~~July 13, 2016~~** – Soil and Groundwater Investigation Report  
File to be named: RO3193\_SWI\_R\_YYYY-MM-DD
- **July 13, 2016** – Hydraulic Lift Removal Report  
File to be named: RO3193\_MISC\_R\_YYYY-MM-DD

This report is being requested pursuant to California Health and Safety Code Section 25296.10. 23 CCR Sections 2652 through 2654, and 2721 through 2728 outline the responsibilities of a responsible party in response to an unauthorized release from a petroleum UST system, and require your compliance with this request. Online case files are available for review at the following website:

<http://www.acgov.org/aceh/lop/ust.htm>

Thank you,

Karel Detterman, PG  
Hazardous Materials Specialist  
Alameda County Environmental Health  
1131 Harbor Bay Parkway  
Alameda, CA 94502  
Direct: 510.567.6708  
Fax: 510.337.9335  
Email: [karel.detterman@acgov.org](mailto:karel.detterman@acgov.org)

PDF copies of case files can be downloaded at:

<http://www.acgov.org/aceh/lop/ust.htm>

---

**From:** dave@eras.biz [mailto:dave@eras.biz]  
**Sent:** Tuesday, July 12, 2016 1:02 PM  
**To:** Detterman, Karel, Env. Health  
**Cc:** F40RACER@aol.com; andrew@eras.biz  
**Subject:** Report Status for 1814 Everett

Hi Karel, we have completed the drilling and sampling for this site and are awaiting results.

The report is due July 13 (tomorrow), however we will require additional time to complete the report.

We respectfully request an extension to the deadline of at least 30 days.

Thanks, Dave

David Siegel  
Senior Program Manager  
ERAS Environmental, Inc.  
1533 B Street  
Hayward, CA 94546  
(510) 247-9885 x 304  
[www.eras.biz](http://www.eras.biz)