

ALAMEDA COUNTY
HEALTH CARE SERVICES

AGENCY
DAVID J. KEARS, Agency Director



State Water Resources Control Board
Division of Clean Water Programs
UST Local Oversight Program

DEPARTMENT OF ENVIRONMENTAL HEALTH
Hazardous Materials Program
80 Swan Way, Rm. 200
Oakland, CA 94621
(415) 271-4320
~~XXX~~(510) 271-4320

December 4, 1991
STID# 776

Chevron U.S.A. Inc.
ATTN: Nancy Vukelich
2410 Camino Ramon
San Ramon, CA 94583-0804

Responsible Party
Tank Operator

Former Chevron #9-0504
15900 Hesperian Blvd.
San Lorenzo, CA 94580

SITE

Date First Reported 12/01/83
Substance: gasoline
Petroleum (X) Yes

Dear Ms. Vukelich:

This office has reviewed Site Update Reports (April 25, 1991, February 20, 1991, July 18, 1991), a Work Plan (April 17, 1990), a Well Installation Report (October 19, 1990), a Groundwater Sampling Report (June 27, 1989), an Interim Remediation report (November 15, 1990), and a recent (Quarterly Monitoring) Report. In your letter of October 28, 1991 you recommend continuing quarterly monitoring for another 6 months.


However, you agreed in a meeting with the Regional Water Quality Control Board on February 14, 1991 that you would monitor for another 6 months at that time. You also agreed to develop a remediation system within that time frame (6 months) and to have it in operation by September 1991. In that meeting September was accepted as a deadline for implementation of a remediation system. That deadline seems to have included the plan, its approval, the necessary permits from other agencies, and the start of implementation of the remediation plan. It is now a full quarter after that deadline.

In the latest monitoring report dated 09/26/91 you show benzene levels in the groundwater of 220 ppb, 220ppb, 7.9 ppb, 47 ppb, and 66 ppb. These levels are orders of magnitude greater than any level allowed to remain. You also have TPHg in the groundwater at levels of 3,200 ppb, 4,900 ppb, 1,400 ppb, 8,100 ppb, and 1,400 ppb. You now have 11 wells surrounding the site. 5 of these wells are actually offsite. It does not seem that any more time is needed to study the matter. This office would like to see the promised Remediation Plan within 30 days. This plan should delineate the specific activities and procedures which will be implemented to remove or reduce the site and groundwater pollution to acceptable levels. The plan should specify dates for each important activity to occur and an expected schedule for progress and completion.

Chevron Station #9-0504
 December 4, 1991
 Page 2 of 2

If you have any questions concerning this matter please contact this office at 271-4320.

Sincerely,



Thomas F. Peacock, Supervising HMS
 Hazardous Material Division

cc: Mark Thompson, Alameda County District Attorney's Office
 Eddie So, RWQCB
 Bohannon D. Organization. P.O.Box 218, San Lorenzo

SENDER: Complete items 1 and 2 when additional services are desired, and complete items 3 and 4.

1. Address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this article from being returned to you. The return receipt fee will provide you the name of the person delivered to you. For additional fees the following services are available. Consult postage rates for additional information requested.

2. (Postage charge)

3. Article Addressed to:
 Bohannon D. Organization
 P.O.Box 218
 San Lorenzo, CA 94580

4. Article Number: **776**

Type of Service:
 Registered Insured
 Certified COD
 Express Mail Return Receipt for Merchandise

Always obtain signature of addressee or agent and DATE DELIVERED.

5. Signature -- Address
 X

6. Signature -- Agent
 X *Wanda Bratz*

7. Date of Delivery
 12/4/91

8. Addressee's Address (if requested and fee paid)
 SAN LORENZO, CA
 DFC
 1991

PS Form 3817, Mar. 1988 * U.S.G.P.O. 1988-212-865 DOMESTIC RETURN

P 367 604 593
RECEIPT FOR CERTIFIED MAIL
 NO INSURANCE COVERAGE PROVIDED
 NOT FOR INTERNATIONAL MAIL
 (See Reverse)

* U.S.G.P.O. 1985-234-555

Sent to Bohannon D. Organ.	
Street and No P.O.Box 218	
P.O. State and ZIP Code San Lorenzo, CA 94580	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt showing to whom and Date Delivered	
Return Receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$
Postmark or Date	

PS Form 3800, June 1985

P 367 604 594
RECEIPT FOR CERTIFIED MAIL
 NO INSURANCE COVERAGE PROVIDED
 NOT FOR INTERNATIONAL MAIL
 (See Reverse)

9LL

Sent to Chevron USA Inc	
Street and No 2410 Camion Ramon	
P.O. State and ZIP Code San Ramon, Ca 94583	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt showing to whom and Date Delivered	
Return Receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$
Postmark or Date	

PS Form 3800, June 1985

776



certified mailer #P 367 604 593

November 25, 1991
STID# 776

(415)
XXX(510) 271-4320

Notice of Requirement to Reimburse

Bohannon D. Organization
P.O. Box 218
San Lorenzo, CA 94580

Responsible Party
Contact Person
Property Owner

Chevron U.S.A. Inc.
ATTN: Nancy Vukelich
2410 Camino Ramon
San Ramon, CA 94583

Responsible Party
Tank Operator


Chevron Station #9-0504
15900 Hesperian Blvd.
San Lorenzo, CA 94580

SITE

Date First Reported 12/01/83
Substance: gasoline
Petroleum (X) Yes

The federal Petroleum Leaking Underground Storage Tank Trust Fund (Federal Trust Fund) provides funding to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The legislature has authorized funds to pay the local and state agency administrative and oversight costs associated with the cleanup of releases from underground storage tanks. The direct and indirect costs of overseeing removal or remedial action at the above site are funded, in whole or in part, from the Federal Trust Fund. The above individual(s) or entity(ies) have been identified as the party or parties responsible for investigation and cleanup of the above site. **YOU ARE HEREBY NOTIFIED** that pursuant to Title 42 of the United States Code, Section 6991b(h)(6) and Sections 25297.1 and 25360 of the California Health and Safety Code, the above Responsible Party or Parties must reimburse the State Water Resources Control Board not more than 150 percent of the total amount of site specific oversight costs actually incurred while overseeing the cleanup of the above underground storage tank site, and the above Responsible Party or Parties must make full payment of such costs within 30 days of receipt of a detailed invoice from the State Water Resources Control Board.

If you have any questions concerning this matter please contact Thomas Peacock, Supervising Hazardous Material Specialist, at this office.


Edgar B. Howell, III, Chief
Contract Project Director

Notice of Requirement to Reimburse
 Chevron Station # 9504
 November 25, 1991
 Page 2 of 2

cc: Sandra Malos, SWRCB

SWRCB Use : add: X Reason: New case

SENDER: Complete items 1 and 2 when additional services are desired, and complete items 3 and 4. Space on the reverse side. Failure to do this will prevent this office from providing you the name of the person delivered following services are available. Consult postmaster at post office.

<p>1. <i>P</i></p> <p>3. Article Addressed to:</p> <p style="text-align: center;">Chevron USA Inc 2410 Camion Ramon San Ramon, CA 94583</p> <p style="text-align: center;">attn: Nancy Vukelich</p>	<p>4. Article Number <i>776</i></p> <p>Type of Service:</p> <p><input type="checkbox"/> Registered <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD <input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise</p> <p>Always obtain signature of addressee or agent and DATE DELIVERED.</p>
<p>5. Signature — Address <i>X</i></p>	<p>8. Addressee's Address (ONLY if requested and fee paid)</p>
<p>6. Signature — Agent <i>X</i> <i>[Signature]</i></p>	
<p>7. Date of Delivery <i>NOV 27 1991</i></p>	