

C A T E L L U S  
ALCO  
HAZMAT



94 MAR 29 AM 9:52

March 24, 1994

Alameda County Health Agency  
Division of Hazardous Materials  
Department of Environmental Health  
80 Swan Way, Room 350  
Oakland, California 94621

Attention: Ms. Susan Hugo  
Senior Hazardous Materials Specialist

Subject: Map of Current Environmental Conditions in Area C  
East Baybridge Project  
Emeryville and Oakland, CA

Dear Susan:

Please find enclosed a copy of the above-referenced map for your use. This is the map that was used by Levine-Fricke during the health risk assessment meeting held on March 14, 1993 at the Regional Board offices between the Alameda County Health Agency, Catellus Development, Levine-Fricke, and SOMA Environmental Engineering.

If you have any questions regarding this project, please contact me at (415) 974-3705 or Jenifer Beatty at (510) 652-4500.

Sincerely,

Kimberly A. Brandt  
Environmental Specialist


attachment

cc: Ravi Arulanantham - RWQCB  
Lester Feldman - RWQCB


coresp/hugol.ltr

CATELLUS DEVELOPMENT CORPORATION

201 MISSION STREET, 30TH FLOOR • SAN FRANCISCO, CALIFORNIA 94105 • TEL 415 974-4500 FAX 415 974-4613



- EXPLANATION**
- Monitoring well location
  - ⊗ Wells abandoned in July or September 1993
  - ◆ Phase I investigation grab ground-water sampling location
  - ⊙ Proposed monitoring well location
  - Former building location
  - 10.45 Ground-water elevation, July 9, 1993 (feet, mean sea level)
  - 2 Ground-water elevation contour (feet, mean sea level)
  - NM Not measured
  - Jan 1990 Date sampled
  - 0.026 TCE  
0.015 1,2-DCE Chemical compound
  - Concentration (ppm) in ground water



**CURRENT ENVIRONMENTAL CONDITIONS  
AREA C  
YERBA BUENA PROJECT SITE**

Project No. 1649

**LEVINE-FRICKE**