

white -env.health
 yellow -facility
 pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH
 Hazardous Materials Inspection Form

1131 Harbor Bay Pkwy
 Alameda CA 94502
 510/567-6700

II, III

Site ID # _____ Site Name David Property Today's Date 9/8/97
 Site Address 106-110 Hegenberger Rd
 City Oak Zip 94621 Phone _____

_____ MAX AMT stored > 500 lbs, 55 gal., 200 cft.?

Inspection Categories:


- _____ I. Haz. Mat/Waste GENERATOR/TRANSPORTER
- _____ II. Hazardous Materials Business Plan, Acutely Hazardous Materials
- _____ III. Under ground Storage Tanks

* Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)

Comments:

BSK & Assoc. present to advance 2 borings through a hollow stem auger to sample soil in areas which previously ID'ed elevated benzene. The soil samples will be incorporated into a revised RBCA.

~~BSK & Assoc.~~
 8
 NW



12-55 gal drums - south side of parking lot @ 106 Hg Rd
 2-55 gal drums on east side of 106 Hg Rd 5 mix of water & soil
 7-55 gal drums on 110 Hegenberger Rd - none properly labeled.

Pls run the 5' soil sple from ea boring for TPHs + BTEX

Contact _____
 Title _____
 Signature _____

Inspector B. CHAN
 Signature [Signature]

II, III