

**RECEIVED**

By Alameda County Environmental Health at 2:11 pm, Oct 16, 2013

## Atlantic Richfield Company

**Chuck Carmel**  
Remediation Management Project Manager

PO Box 1257  
San Ramon, CA 94583  
Phone: (925) 275-3804  
Fax: (925) 275-3815  
E-Mail: chuck.carmel@bp.com

October 15, 2013

Re: Third Quarter 2013 Monitoring Report  
Atlantic Richfield Company Station #2035  
1001 San Pablo Avenue, Albany, California  
ACEH Case #RO0000100

I declare that to the best of my knowledge at the present time, that the information and/or recommendations contained in the attached document are true and correct.

Submitted by,



**Chuck Carmel**  
Remediation Management Project Manager

Attachment



**BROADBENT**

875 Cotting Ln., Suite G, Vacaville, CA 95688  
[T] 707-455-7290 [F] 707-455-7295  
broadbentinc.com

**CREATING SOLUTIONS. BUILDING TRUST.**

October 15, 2013

Project No. 06-88-610

Atlantic Richfield Company  
P.O. Box 1257  
San Ramon, CA 94583  
Submitted via ENFOS

Attn.: Mr. Chuck Carmel

Re: Third Quarter 2013 Status Report, Atlantic Richfield Company Station No. 2035,  
1001 San Pablo Avenue, Albany, California; ACEH Case #RO0000100

Dear Mr. Carmel:

Attached is the Third Quarter 2013 Status Report for Atlantic Richfield Company Station No. 2035 located at 1001 San Pablo Avenue in Albany, California. This report presents a summary of current developments at the Site through the Third Quarter 2013.


Should you have questions regarding this submittal, please do not hesitate to contact us at (707) 455-7290.

Sincerely,

BROADBENT & ASSOCIATES, INC.

Alejandra Hernandez  
Project Geologist

Kristene Tidwell, PG, CHG  
Senior Geologist



Enclosures

cc: Ms. Dilan Roe, P.E., Alameda County Environmental Health (submitted via ACEH ftp site)  
Mr. John LeStrange, 17851 State Highway 128, Calistoga, California 94515  
Electronic copy uploaded to GeoTracker

**THIRD QUARTER 2013  
STATUS REPORT  
ARCO STATION No. 2035, ALBANY, CALIFORNIA**

Broadbent & Associates, Inc. (Broadbent) is pleased to present this *Third Quarter 2013 Status Report* on behalf of Atlantic Richfield Company (a BP affiliated company) for ARCO Station No. 2035 located on 1001 San Pablo Avenue in Albany, Alameda County, California. Quarterly reporting is being submitted to the Alameda County Environmental Health Services Agency (ACEH) consistent with their requirements under the legal authority of the California Regional Water Quality Control Board as codified by California Code of Regulations Title 23, Section 2652(d). A summary description of current developments regarding the Site is provided below.

Facility Name / Address:	ARCO Station No. 2035 / 1001 San Pablo Avenue, Albany
Client Project Manager / Title:	Mr. Chuck Carmel / Remediation Management Project Manager
Broadbent Contact:	Ms. Kristene Tidwell, PG, CHG / 707-455-7290
Broadbent Project No.:	06-88-610
Primary Regulatory Agency / ID No.:	ACEH, Case #RO0000100
Current phase of project:	Monitoring
List of Acronyms / Abbreviations:	ACEH: Alameda County Environmental Health ARCO: Atlantic Richfield Company

**WORK PERFORMED THIS QUARTER (Third Quarter 2013):**

1. Submitted *Second Quarter 2013 Monitoring Report* on July 29, 2013.
2. No environmental field work was conducted at Station No. 2035 during the Third Quarter 2013.

**WORK SCHEDULED FOR NEXT QUARTER (Fourth Quarter 2013):**




1. Prepared and submitted *Third Quarter 2013 Status Report* (contained herein).
2. Conduct semi-annual groundwater monitoring/sampling for Fourth Quarter 2013, coordinated with consultant for nearby Shell Station.
3. Submit Conceptual Site Model for the Site.

**DISCUSSION:**

Groundwater monitoring and sampling is scheduled to be conducted at ARCO Station No. 2035 during the Fourth Quarter 2013, consistent with the current monitoring program. Currently, a Conceptual Site Model is being prepared.

**ATTACHMENTS:**

- Drawing 1: Site Location Map  
Drawing 2: Groundwater Elevation Contour Map, June 4, 2013



APPROXIMATE SCALE (mi)

IMAGE SOURCE: DeLorme USA Topo 7.0



1370 Ridgewood Dr., Suite 5  
Chico, California 95973



Project No.: 06-88-610 Date: 4/9/2013

ARCO Service Station #2035  
1001 San Pablo Avenue  
Albany, California

Site Location Map

Drawing

1



**BROADBENT**  
 1370 Ridgewood Dr., Suite 5  
 Chico, California 95973  
 Project No.: 06-88-610 Date: 7/11/2013

ARCO Service Station #2035  
 1001 San Pablo Avenue  
 Albany, California

Groundwater Elevation Contour Map  
 June 4, 2013

Drawing

2