(it'll be in draft form.)

Date	By	REMARKS
		there w delays bet.
		TSCA + ALCo deciding
		who lead agency was.
2-3-93	JE	site visit to observe
		drilling, see sump area.
2-9-93	JE	Mess fm D. Allen: got
		lab results for tank
		pit. Wants to backfill
		today. Spoke w/S. DeHoe.
		got faxed lab results
		OK'd the backfilling.
		Up to 19 ppm TPH-g +
		.031 ppm benz remains
		in sidewall. Overburden
		will be offhauled.
3-25	JE	Spoke w/D. Allen. The
		tank removal report
		will be submitted next
		week. The SI report
		will be in the form
		of a PEA (1st submittal
		to DTSC). DTSC needs
		30 days to review it.

Date	By	REMARKS
		ASE must get Caltrans
		payment prior to submitg
		PEA to DTSC.
3-31	JE	Rcvd 3-18-93 "Final
		Report, UST Removal"
		by ASE.
3-31	JE	Spoke w/D. Allen of ASE.
		Asked for copy of liquid
		manifest. Told him I was mis-quoted (p. 6) in report.
4-1	JE	Spoke w/D. Allen. Asked
		for copy of draft PEA.
		It's a Phase II for entire
		site; includes sump
		area. The tank pull
		report is in an appendix
		of the PEA. Conclusions
		are in the form of a
		risk assessmt. Only
		minor contam. Recommends
		NFA.

Date	By	REMARKS

FILE OR PER NO. Renewal | ENVELOPE No. ____ of ____

☐ OWNER Thomas L. Short Co.
Address 3430 Ward St
Oakland Phone
☐ Contractor Agra Science
Address 241 Old Crow Canyon
San Ramon Phone 820-9391
Dave Allen
☐ OTHER (Specify)
Address
Phone
☒ CONTACT FOR INVESTIGATION

PLAN REVIEW		By	Date
$ 714	Rec'd.		1-21-93
No.	Plans Rec'd.		
Plans Approved			
Layout Made			
Rejected			
Applicant Notified			
Plans Returned			
Permit Issued			

CONSTRUCTION PROGRESS ACCEPTANCE

		By	Date
FOOD	Pre-Plaster/drywall		
	Pre-Final		
	Final		

		By	Date
POOL	Pre-Concrete		
	Pre-Plaster		
	Final		
EXCAVATION	Septic Tank		
	Absorption Field		
	Absorption Bed		
FINAL	House Sewer		
	Septic Tank		
	Absorption Field		
	Absorption Bed		
OTHER			

		By	Date
G. TANKS	Pre-Covering		
	Final		

LOP 386 A →

XR

2777 El Camino Real
(650) 522-7183

REMARKS

Date	By	
1/28/93	A	TANKS REMOVED
1-29-93	JE	Spoke w/D. Allen of ASE. SBs were done prior to tank pull. Results: up to 14,000 ppm TPH-g (at 5' bgs nr gas tank). There is a mw. Cal Trans did this study; they want to buy site for freeway. → site visit for overex + resample. See report

REMARKS

Date	By	
1-1-93	JE	D. Allen of ASE delivered 1-28 "Proposal" for invest. (soil + gw) in sump area. Spoke w/M. Marello RG who said he ok'd D. Allen's signature of wp. Also rcv'd 10-1-92 Wp for Goodman Property in Alameda, which was previously approved by JM. The Health + Safety Plan + OA QC Plans in this doc. should apply to Thomas Short site. I'm giving them Dave Lowry's loc.

LOCATION

Vicinity Map

UL68902
$714
1/20/93

LOP 386 B

ENVELOPE No. ____ of ____

PER NO.

☐ OWNER Thomas Short Co.

Address 3430 Wood St.

Oak 608 Phone

☐ Contractor

Address

Phone

☐ OTHER (Specify) Dave Allen ASE

Address 820-~~[illegible]~~ 9391

Phone

☒ CONTACT FOR INVESTIGATION

XR

PLAN REVIEW		
$	Rec'd.	
No.	Plans Rec'd.	
Plans Approved		
Layout Made		
Rejected		
Applicant Notified		
Plans Returned		
Permit Issued		

CONSTRUCTION PROGRESS ACCEPTANCE			Date
FOOD	Pre-Plaster/drywall		
	Pre-Final		
	Final		
POOL	Pre-Concrete/Gunite		
	Pre-Plaster		
	Final		
EXCAVATION	Septic Tank		
	Absorption Field		
	Absorption Bed		
FINAL	House Sewer		
	Septic Tank		
	Absorption Field		
	Absorption Bed		
OTHER			

U.G. TANKS	By	Date
Pre-Welding		
Final		

LOCATION

Vicinity Map

Date	By	REMARKS
-20-93	JE	Reviewed "Draft PEA" by ASE, dated 4-1-93.
1-22	JE	Rcv'd manifest for liquid removed fm USTs prior to UST removal.
6-2	JE	Spoke w/D. Allen of ASE. They made an assumption on your direction. ~~DTSC approved their wp for one add. mw.~~ No, met with Nina Cantonio today. She's not
6-14	JE	Sp w/D. Allen. Are they doing QW? NO. They just did a site assessment. He does not propose a 3rd mw. They tried to put in a 3rd mw but

Date	By	REMARKS
		happy w/their R.A. w/in the PEA bec. it doesn't have the calculations. ASE is also working on B+A Auto Dismantlers on 7th St. 607. No USTs. He'll write me a ltr w/ his responses to my 5-10 comments.

Sandblasting area + driveway impermeable but hit an area or pipe. They tried in many areas. 2 wks for letter fm him.