ACTIVITY RECORD

Health Care Services

RO #: 0000127

DATE: Tuesday, April 22, 2008

TIME: 11:00 AM



X	Meeting	HAZ MAT SPECIALIST:	Paresh C. Khatri
	Site Visit/Inspection	Work Location:	1131 Harbor Bay Pkwy, Alameda
	Telephone Conversation	Conferee(`s):	Pritpaul Sappal
	Document Review		Reijo Ratilainen/Scott Jackson
	Peer Review	Phone #	

SITE NAME & ADDRESS: Alaska Gas Station, 6211 San Pablo Ave., Oakland TOPIC: Meeting to Discuss Site SUMMARY:

Attendees:

Pritpaul Sappal (Responsible Party) Scott Jackson (HerSchy Environmental) Reijo Ratilainen (HerSchy Environmental) Donna Drogos (Supervising Haz Mat Specialist, ACEH) Paresh Khatri (Haz Mat Specialist, ACEH)

- 1. HerSchy modified boring locations due to site access issues with off-site property owners and insurance bond language with the City of Oakland. I agreed to review the proposed locations, presented in a site status report submitted in August 2007.
- HerSchy is currently negotiating access to City Of Oakland Housing Authority property next door to install borings/wells. Previous contact at the City has left, was unassigned for a while, but a new contact person has been established. Also having difficulties with property owner across the street. We requested that HerSchy send us their documentation and ACEH will sent off-site owners a letter asking for cooperation.
- 3. The responsible party's insurance carrier is unable to meet the City of Oakland's requirements for a bond necessary to drill and install borings in the street (City property). According to the RP, the insurance carriers recommended by the City were unable to insure base on the City's required language. We asked that HerSchy send us their documentation so that we may ask the City what alternatives are available.