



**CONESTOGA-ROVERS  
& ASSOCIATES**

5900 Hollis Street, Suite A  
Emeryville, California 94608  
Telephone: (510) 420-0700 Fax: (510) 420-9170  
www.CRAworld.com

## TRANSMITTAL

DATE: June 8, 2009 REFERENCE NO.: 240733  
PROJECT NAME: 2120 Montana Street, Oakland

TO: Audrey Comeaux  
East Bay Municipal Utilities District-Mail Slot 702  
Environmental Services Division  
PO Box 24055  
Oakland, California 94623-1055

**RECEIVED**

*3:24 pm, Mar 22, 2012*

Alameda County  
Environmental Health

Please find enclosed:  Draft  Final  
 Originals  Other  
 Prints


Sent via:  Mail  Same Day Courier  
 Overnight Courier  Other GeoTracker

QUANTITY	DESCRIPTION
1	Self-Monitoring Report - First Semi-Annual 2009

As Requested  For Review and Comment  
 For Your Use  \_\_\_\_\_  
 \_\_\_\_\_

**COMMENTS:**  
If you have any questions regarding the content of this document, please contact Peter Schaefer at (510) 420-3319

Copy to: Denis Brown, 20945 S. Wilmington Avenue, Carson, CA 90810  
SF Data Room

Completed by: Peter Schaefer Signed: 

Filing: Correspondence File



Audrey Comeaux  
Wastewater Control Representative  
East Bay Municipal Utilities District-Mail Slot 702  
Environmental Services Division  
PO Box 24055  
Oakland, California 94623-1055

**Denis L. Brown**  
**Shell Oil Products US**  
HSE - Environmental Services  
20945 S. Wilmington Ave.  
Carson, CA 90810-1039  
**Tel** (707) 865 0251  
**Fax** (707) 865 2542  
**Email** [denis.l.brown@shell.com](mailto:denis.l.brown@shell.com)

Re: Shell-branded Service Station  
2120 Montana Street  
Oakland, California  
SAP Code 135675  
Incident No. 98995740  
EBMUD Discharge Permit No. 5050670-1

Dear Ms. Comeaux:

The attached document is provided for your review and comment.

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

If you have any questions or concerns, please call me at (707) 865-0251.

Sincerely,

A handwritten signature in black ink that reads "Denis L. Brown". The signature is written in a cursive style with a long, sweeping underline.

Denis L. Brown  
Project Manager



## **SELF-MONITORING REPORT- FIRST SEMI-ANNUAL 2009**

**SHELL-BRANDED SERVICE STATION  
2120 MONTANA STREET  
OAKLAND, CALIFORNIA**

<b>SAP CODE</b>	<b>135675</b>
<b>INCIDENT NO.</b>	<b>98995740</b>
<b>EBMUD DISCHARGE PERMIT NO.</b>	<b>5050670-1</b>

**JUNE 8, 2009**  
**REF. NO. 240733 (7)**  
This report is printed on recycled paper.

**Prepared by:  
Conestoga-Rovers  
& Associates**

5900 Hollis Street, Suite A  
Emeryville, California  
U.S.A. 94608

Office: (510) 420-0700  
Fax: (510) 420-9170

web: <http://www.CRAworld.com>

TABLE OF CONTENTS

1.0 INTRODUCTION .....1

2.0 SELF-MONITORING REPORT - FIRST SEMI-ANNUAL 2009.....2

    2.1 REPORTING PERIOD ACTIVITIES .....2

    2.2 REPORTING PERIOD DATA SUMMARY .....2

## 1.0 INTRODUCTION

Conestoga-Rovers & Associates (CRA) prepared this report on behalf of Equilon Enterprises LLC dba Shell Oil Products US (Shell) in accordance with the requirements of the wastewater discharge permit. **During the current reporting period, the remediation system at the subject site did not operate; therefore, no samples were collected.** Based on previous email correspondence with Ms. Audrey Comeaux with the East Bay Municipal Utilities District (EBMUD) and Mr. Jeff Schrupp of CRA it is our understanding that this will be the final self-monitoring report (SMR) submitted to your office. Additionally, Discharge Permit No. 5050670-1 will be terminated upon receipt and review of this SMR.

**2.0 SELF-MONITORING REPORT - FIRST SEMI-ANNUAL 2009**

**2.1 REPORTING PERIOD ACTIVITIES**

CRA manually shut down the groundwater extraction system to assess rebound on September 25, 2007. The system did not operate during the current reporting period and therefore, no operational data, laboratory analytical data, or laboratory analytical reports are included with this report. Based on previous email correspondence with Ms. Audrey Comeaux with the EBMUD and Mr. Jeff Schrupp of CRA it is our understanding that this will be the final SMR submitted to your office. Additionally, Discharge Permit No. 5050670-1 will be terminated upon receipt and review of this SMR.

**2.2 REPORTING PERIOD DATA SUMMARY**

Compliance Sampling Frequency	NA (system off)
Discharge Volume	0 gallons
Average Discharge Flow Rate	0 gallons per minute
Maximum Discharge Flow Rate	0 gallons per minute
Discharge Violations or Exceedances	None

All of Which is Respectfully Submitted,  
CONESTOGA-ROVERS & ASSOCIATES

A handwritten signature in cursive script that reads "Casey Sanders".

Casey Sanders