



RECEIVED

2:46 pm, Dec 17, 2008

Alameda County
Environmental Health

Cynthia Soohoo
Wastewater Control Representative
East Bay Municipal Utilities District-Mail Slot 702
Environmental Services Division
PO Box 24055
Oakland, California 94623-1055

Denis L. Brown
Shell Oil Products US
HSE - Environmental Services
20945 S. Wilmington Ave.
Carson, CA 90810-1039
Tel (707) 865 0251
Fax (707) 865 2542
Email denis.l.brown@shell.com

Re: Shell-branded Service Station
2120 Montana Street
Oakland, California
SAP Code 135675
Incident No. 98995740
EBMUD Discharge Permit No. 5050670-1

Dear Ms. Soohoo:

The attached document is provided for your review and comment. Upon information and belief, I declare, under penalty of perjury, that the information contained in the attached document is true and correct.

If you have any questions or concerns, please call me at (707) 865-0251.

Sincerely,

A handwritten signature in black ink, appearing to read "Denis L. Brown", is written over a horizontal line.

Denis L. Brown
Project Manager



SELF-MONITORING REPORT- SECOND SEMI-ANNUAL 2008

**SHELL-BRANDED SERVICE STATION
2120 MONTANA STREET
OAKLAND, CALIFORNIA**

| | |
|-----------------------------------|------------------|
| SAP CODE | 135675 |
| INCIDENT NO. | 98995740 |
| EBMUD DISCHARGE PERMIT NO. | 5050670-1 |

DECEMBER 15, 2008
REF. NO. 240733 (2)
This report is printed on recycled paper.

**Prepared by:
Conestoga-Rovers
& Associates**

5900 Hollis Street, Suite A
Emeryville, California
U.S.A. 94608

Office: (510) 420-0700
Fax: (510) 420-9170

web: <http://www.CRAworld.com>

TABLE OF CONTENTS

| | <u>Page</u> |
|--|-------------|
| 1.0 INTRODUCTION | 1 |
| 2.0 SELF-MONITORING REPORT - SECOND SEMI-ANNUAL 2008 | 2 |
| 2.1 REPORTING PERIOD ACTIVITIES | 2 |
| 2.2 REPORTING PERIOD DATA SUMMARY | 2 |

1.0 INTRODUCTION

Conestoga-Rovers & Associates (CRA) prepared this report on behalf of Equilon Enterprises LLC dba Shell Oil Products US (Shell) in accordance with the requirements of the wastewater discharge permit. **During the current reporting period, the remediation system at the subject site did not operate; therefore, no samples were collected.**

2.0 SELF-MONITORING REPORT - SECOND SEMI-ANNUAL 2008


2.1 REPORTING PERIOD ACTIVITIES

CRA manually shut down the groundwater extraction system to assess rebound on September 25, 2007. The system did not operate during the current reporting period and therefore, no operational data, laboratory analytical data, or laboratory analytical reports are included with this report.

2.2 REPORTING PERIOD DATA SUMMARY

| | |
|-------------------------------------|----------------------|
| Compliance Sampling Frequency | NA (system off) |
| Discharge Volume | 0 gallons |
| Average Discharge Flow Rate | 0 gallons per minute |
| Maximum Discharge Flow Rate | 0 gallons per minute |
| Discharge Violations or Exceedances | None |

All of Which is Respectfully Submitted,
CONESTOGA-ROVERS & ASSOCIATES

 for CS.

Casey Sanders