

3943 Bdwg

Per Aram 10/20/93

Pump test was done

pull 50 gall - then dry

later pulled 25 gall, then dry

i. couldn't do pump + treat in RW-1

Recommend pump test in <sup>M</sup>RW-3, 4, 5 + 8

verify RW-1 is not an anomaly.

Has water recovery  
pump test been  
performed. Yes -  
No very acceptable  
results - 3 of wells  
went dry  
Any QMRS - same 9/93

FILE OR ENVELOPE  
 PER NO. No. of

OWNER Unocal  
 Address 3943 Broadway  
 94611 Phone

Contractor R.W. Johnston + Son  
 Address 801-53rd Ave  
 Oakland 94612 Phone

OTHER (Specify) R.H. Lee  
 Address 1337 Howe Ave. Ste 211  
 San. 95825 Phone (916) 646-4003

CONTACT FOR INVESTIGATION

PLAN REVIEW	By	Date
\$ 663. Rec'd.	mc	6.21
No. Plans Rec'd.	mc	6.21
Plans Approved		
Layout Made		
Rejected		
Applicant Notified		
Plans Returned		
Permit Issued		
CONSTRUCTION PROGRESS ACCEPTANCE		
Pre-Plaster/drywall		
Pre-Final		
Final		

	By	Date
POOL		
Pre-Concrete		
Pre-Plaster		
Final		
EXCAVATION		
Septic Tank		
Absorption Field		
Absorption Bed		
House Sewer		
FINAL		
Septic Tank		
Absorption Field		
Absorption Bed		
OTHER		

	By	Date
U.G. TANKS		
Pre-covering		
Final		

**LOP 1119**

XR		REMARKS		LOCATION
Date	By	Date	By	
		4/11/90	GW	
7/5/89	GW			
7/6		8/9		
7/11		10/4		
8/16	GW			
		10/31		

Vicinity Map  
**-1993**  
 U542378 + 7/9  
 6.21.89  
 663.02

0570 Broadway  
 Oakland, CA 94611  
 BROADWAY UNOCAL 78, INC.  
 1119

