

Khatri, Paresh, Env. Health

From: Kiernan, James [jkiernan@croworld.com]
Sent: Thursday, September 17, 2009 9:45 AM
To: Khatri, Paresh, Env. Health
Subject: RO206 (Chevron 9-5542 Dublin)-Updated Soil Vapor Locations
Attachments: 611969-Updated Figure 2 SV Locations.pdf

Hi Paresh,

Per our discussion yesterday, attached is an updated site plan showing the three proposed soil vapor well locations at Chevron 9-5542 (RO206) in relation to the previous samples (approximately). Unless you have any other questions/issues, we will implement the investigation per this site plan. Thanks.

Sincerely,

James P. Kiernan, P.E.

Conestoga-Rovers & Associates (CRA)

2000 Opportunity Drive, Suite 110

Roseville, CA 95678

Direct: (916) 751-4102


Cell: (916) 919-6759

Fax: (916) 751-4199

jkiernan@croworld.com

Visit us at www.croworld.com

This e-mail may contain confidential and privileged material for the sole use of the intended recipient. Any review or distribution by others is strictly prohibited. If you are not the intended recipient please contact the sender and delete all copies.



LEGEND

- MW-1 ● MONITORING WELL LOCATION
- SB-1 ☒ EXPLORATORY BORING LOCATION
- VW-1 ⊕ VADOSE MONITORING WELL LOCATION
- CPT-1 ■ CPT BORING LOCATION
- P5 ☒ SOIL SAMPLE LOCATION
- MW-6 ☒ DESTROYED WELL LOCATION
- ▲ PROPOSED SOIL VAPOR WELL LOCATION




figure 2
SITE PLAN
 CHEVRON SERVICE STATION 9-5542
 7007 SAN RAMON ROAD
 Dublin, California

