



Tank #1, 2k tank w/ obvious holes  
9/22/94 BC



West wall B65 where brown  
liquid accumulates & flows  
Cal Trans 9/22/94



Repairing trench at Cal Trans STJ  
Heg, Rd 9/22/94 BC



South end Tank #4 CalTrane  
reddled w/holes 9/22/94 R



North end of Tank #4 - CalTrane  
holes also noted on South end 9/22/94



Tanks 4-1 @ CalTrane site  
SJT Hays Rd  
9/22/94 R



T-2, 6500 Tank no obvious tubes  
SSS Heyked, 9/22/94



Black hydrocarbon on water beneath  
Tank #3 Cal Trans SSS Heyked 9/22/94



OK tank #1, tubes on entire bottom  
liquid draining from tank. 9/22/94  
BC



Next to Cal Trans bldg  
8/5/93 see vicinity