

CERTIFICATE OF UNDERGROUND STORAGE TANK SYSTEM TESTING



8900 SHOAL CREEK, BUILDING 200
 AUSTIN, TEXAS 78757
 (512) 451-6334
 FAX (512) 459-1459

*paid ✓ 2106925
 12/08/99*

Store #	<u>30855</u>
Report Type Code:	<u>fuel test</u>
Description	<u>new installation</u>
Date	<u>12/28/99</u>

TEST RESULT SITE SUMMARY REPORT


TEST TYPE **TLD-1** PURPOSE **REQUEST**
 TEST DATE **11/19/99** CUSTOMER PO WORK ORDER NUMBER **2210682**

CLIENT **TOSCO MARKETING COMPANY**
 P.O. BOX 52189
 PHOENIX, AZ 85072

SITE **255325 TOSCO**
 3200 LAKESHORE AVE
 OAKLAND, CA 94610

DON ESPERSON
 (602) 728-3447

STEPHEN
 (510) 893-1676



The following test(s) were conducted at the site above in accordance with all applicable portions of Federal, NFPA and local regulations

Line and Leak Detector Tests

TANK NUMBER	PRODUCT	VOLUME CHANGE (gph)				LINE RESULT				LEAK DETECTOR PRESENT		LEAK DETECTOR RESULT		IMPACT VALVES OPERATIONAL	
		A	B	C	D	: P=pass, F=fail, I=Inconclusive				1	2	1	2		
						A	B	C	D						

Tanknology appreciates the opportunity to serve you, and looks forward to working with you in the future. Please call any time, day or night, when you need us.

Tanknology representative
MARK SHAW

Services conducted by
DAVID MATHIE

Reviewed

Technician Certification Number **98-1429**



8900 SHOAL CREEK, BUILDING 200
 AUSTIN, TEXAS 78757
 (512) 451-6334
 FAX (512) 459-1459

TEST DATE 11/19/99

WORK ORDER NUMBER 2210682

CLIENT TOSCO MARKETING COMPANY

SITE 255325 TOSCO

COMMENTS

MSIC PARTS INCLUDED WIRE, RJ11 BOXES, AND MOUNTING HARDWARE
 LABOR INCLUDES SOFTWARE UPGRADE

PARTS REPLACED

QUANTITY	DESCRIPTION

HELIUM PINPOINT TEST RESULTS (IF APPLICABLE)

ITEMS TESTED	3-	P

HELIUM PINPOINT LEAK TEST RESULTS

--